



Aviation Investigation Final Report

Location: Belmar, New Jersey Accident Number: GAA17CA339

Date & Time: June 11, 2017, 12:30 Local Registration: N71MH

Aircraft: Cessna 180 Aircraft Damage: Substantial

Defining Event: Loss of control on ground **Injuries:** 1 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

The pilot of the tailwheel-equipped airplane reported that, during the landing and as the left main landing gear (MLG) touched down, the airplane encountered a wind gust and then veered "abruptly" left. He added that, as the right MLG touched down, the airplane "began skidding to the left," and the right MLG collapsed. Subsequently, the airplane came to rest on the left side of the runway and nosed down.

The airplane sustained substantial damage to the right wing.

The pilot reported that there were no preaccident mechanical failures or malfunctions with the airplane that would have precluded normal operation.

The automated weather observation system at the airport reported that, about the time of the accident, the wind was from 260° at 10 knots, gusting to 15 knots. The pilot landed the airplane on runway 32.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The pilot's failure to maintain directional control while landing in gusting wind conditions.

Findings

Aircraft Directional control - Not attained/maintained

Personnel issues Aircraft control - Pilot

Environmental issues Gusts - Effect on operation

Page 2 of 5 GAA17CA339

Factual Information

History of Flight

| Landing | Other weather encounter |
|---------|--|
| Landing | Loss of control on ground (Defining event) |
| Landing | Landing gear collapse |
| Landing | Nose over/nose down |

Pilot Information

| Certificate: | Private | Age: | 50,Male |
|---------------------------|---|-----------------------------------|------------------|
| Airplane Rating(s): | Single-engine land | Seat Occupied: | Left |
| Other Aircraft Rating(s): | None | Restraint Used: | 3-point |
| Instrument Rating(s): | None | Second Pilot Present: | No |
| Instructor Rating(s): | None | Toxicology Performed: | No |
| Medical Certification: | Class 3 With waivers/limitations | Last FAA Medical Exam: | January 14, 2016 |
| Occupational Pilot: | No | Last Flight Review or Equivalent: | June 10, 2016 |
| Flight Time: | (Estimated) 1132 hours (Total, all aircraft), 681 hours (Total, this make and model), 1071 hours (Pilot In Command, all aircraft), 48 hours (Last 90 days, all aircraft), 15 hours (Last 30 days, all aircraft) | | |

Page 3 of 5 GAA17CA339

Aircraft and Owner/Operator Information

| Cessna | Registration: | N71MH |
|----------------------------------|--|--|
| 180 K | Aircraft Category: | Airplane |
| 1977 | Amateur Built: | |
| Normal | Serial Number: | 18052965 |
| Tailwheel | Seats: | 4 |
| April 18, 2017 Annual | Certified Max Gross Wt.: | 2800 lbs |
| | Engines: | 1 Reciprocating |
| 5722.5 Hrs as of last inspection | Engine Manufacturer: | CONT MOTOR |
| Installed, not activated | Engine Model/Series: | IO-550-D |
| | Rated Power: | 300 Horsepower |
| On file | Operating Certificate(s) Held: | None |
| | 180 K 1977 Normal Tailwheel April 18, 2017 Annual 5722.5 Hrs as of last inspection Installed, not activated | 180 K Aircraft Category: 1977 Amateur Built: Normal Serial Number: Tailwheel Seats: April 18, 2017 Annual Certified Max Gross Wt.: Engines: 5722.5 Hrs as of last inspection Installed, not activated Engine Manufacturer: Rated Power: On file Operating Certificate(s) |

Meteorological Information and Flight Plan

| Conditions at Accident Site: | Visual (VMC) | Condition of Light: | Day |
|----------------------------------|----------------------------------|--------------------------------------|------------------|
| Observation Facility, Elevation: | BLM,164 ft msl | Distance from Accident Site: | 0 Nautical Miles |
| Observation Time: | 16:56 Local | Direction from Accident Site: | 117° |
| Lowest Cloud Condition: | Clear | Visibility | 10 miles |
| Lowest Ceiling: | None | Visibility (RVR): | |
| Wind Speed/Gusts: | 10 knots / 15 knots | Turbulence Type Forecast/Actual: | / None |
| Wind Direction: | 260° | Turbulence Severity Forecast/Actual: | / N/A |
| Altimeter Setting: | 30.07 inches Hg | Temperature/Dew Point: | 32°C / 16°C |
| Precipitation and Obscuration: | No Obscuration; No Precipitation | | |
| Departure Point: | Belmar, NJ (BLM) | Type of Flight Plan Filed: | None |
| Destination: | Belmar, NJ (BLM) | Type of Clearance: | None |
| Departure Time: | 12:00 Local | Type of Airspace: | Class G |
| | | | |

Page 4 of 5 GAA17CA339

Airport Information

| Airport: | MONMOUTH EXECUTIVE BLM | Runway Surface Type: | Asphalt |
|----------------------|------------------------|---------------------------|-----------|
| Airport Elevation: | 153 ft msl | Runway Surface Condition: | Dry |
| Runway Used: | 32 | IFR Approach: | None |
| Runway Length/Width: | 7371 ft / 85 ft | VFR Approach/Landing: | Full stop |

Wreckage and Impact Information

| Crew Injuries: | 1 None | Aircraft Damage: | Substantial |
|---------------------|--------|-------------------------|---------------------------|
| Passenger Injuries: | | Aircraft Fire: | None |
| Ground Injuries: | N/A | Aircraft Explosion: | None |
| Total Injuries: | 1 None | Latitude, Longitude: | 40.185001,-74.122222(est) |

Administrative Information

| Investigator In Charge (IIC): | Swenson, Eric |
|-----------------------------------|---|
| Additional Participating Persons: | Joseph Martuge; FAA; Teterboro, NJ |
| Original Publish Date: | April 8, 2019 |
| Note: | This accident report documents the factual circumstances of this accident as described to the NTSB. |
| Investigation Docket: | https://data.ntsb.gov/Docket?ProjectID=95369 |

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

Page 5 of 5 GAA17CA339