



# **Aviation Investigation Final Report**

Location: Truman, Arkansas Accident Number: GAA18CA265

Date & Time: May 4, 2018, 15:20 Local Registration: N4170S

Aircraft: AIR TRACTOR INC AT 802 Aircraft Damage: Substantial

**Defining Event:** Miscellaneous/other **Injuries:** 1 None

Flight Conducted Under: Part 137: Agricultural

### **Analysis**

The pilot reported that, during an agricultural application flight, the airplane hit a pole. The pilot added that he subsequently landed in a bean field.

The airplane sustained substantial damage to the fuselage and rudder.

The pilot reported that there were no preaccident mechanical failures or malfunctions with the airplane that would have precluded normal operation.

### **Probable Cause and Findings**

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The pilot's failure to see and avoid a pole during an agricultural application flight.

#### **Findings**

Personnel issues Monitoring environment - Pilot

Aircraft Altitude - Not attained/maintained

**Environmental issues** Pole - Effect on operation

# **Factual Information**

# **History of Flight**

Maneuvering-low-alt flying	Miscellaneous/other (Defining event)
Maneuvering-low-alt flying	Collision with terr/obj (non-CFIT)
Landing	Off-field or emergency landing

#### **Pilot Information**

Certificate:	Commercial	Age:	65,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Single
Other Aircraft Rating(s):	None	Restraint Used:	Unknown
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 2 With waivers/limitations	Last FAA Medical Exam:	December 8, 2017
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	December 8, 2017
Flight Time:	(Estimated) 17000 hours (Total, all aircraft), 1600 hours (Total, this make and model), 16940 hours (Pilot In Command, all aircraft)		

# **Aircraft and Owner/Operator Information**

Aircraft Make:	AIR TRACTOR INC	Registration:	N4170S
Model/Series:	AT 802 A	Aircraft Category:	Airplane
Year of Manufacture:	2007	Amateur Built:	
Airworthiness Certificate:	Restricted (Special)	Serial Number:	802A-0278
Landing Gear Type:	Tailwheel	Seats:	1
Date/Type of Last Inspection:	March 7, 2018 Unknown	Certified Max Gross Wt.:	
Time Since Last Inspection:		Engines:	1 Turbo prop
Airframe Total Time:	5021.4 Hrs at time of accident	Engine Manufacturer:	P&W
ELT:	Not installed	Engine Model/Series:	PT6A-65AG
Registered Owner:		Rated Power:	
Operator:		Operating Certificate(s) Held:	Agricultural aircraft (137)

Page 2 of 4 GAA18CA265

# Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	KJBR,262 ft msl	Distance from Accident Site:	16 Nautical Miles
Observation Time:	20:39 Local	Direction from Accident Site:	358°
<b>Lowest Cloud Condition:</b>	Scattered / 2000 ft AGL	Visibility	10 miles
Lowest Ceiling:	Broken / 9000 ft AGL	Visibility (RVR):	
Wind Speed/Gusts:	12 knots /	Turbulence Type Forecast/Actual:	None / None
Wind Direction:	230°	Turbulence Severity Forecast/Actual:	N/A / N/A
Altimeter Setting:	30.04 inches Hg	Temperature/Dew Point:	24°C / 22°C
Precipitation and Obscuration:	Light - None - Rain		
Departure Point:	Harrisburg, AR	Type of Flight Plan Filed:	Company VFR
Destination:	Truman, AR	Type of Clearance:	Unknown
Departure Time:		Type of Airspace:	Class G

# Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	35.570278,-90.636108(est)

### **Administrative Information**

Investigator In Charge (IIC):	Swenson, Eric
Additional Participating Persons:	Douglas Ragsdale; FAA; Little Rock, AR
Original Publish Date:	October 24, 2018
Note:	This accident report documents the factual circumstances of this accident as described to the NTSB.
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=97209

Page 3 of 4 GAA18CA265

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

Page 4 of 4 GAA18CA265