



Aviation Investigation Final Report

Location: St. Mary's, Alaska Accident Number: GAA18CA567

Date & Time: September 20, 2018, 20:00 Local Registration: N8192D

Aircraft: Piper PA18 Aircraft Damage: Substantial

Defining Event: Miscellaneous/other **Injuries:** 2 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

The pilot of the tailwheel-equipped airplane reported that, during the landing at an off-airport dirt and grass landing area, the ground was very slippery. During the landing roll, the airplane struck a few holes and bumps, and the airplane rocked side to side. The airplane's left wing struck the ground and "pushed up," which caused the right wing to strike and catch the ground. The airplane ground looped to the right and came to rest in a nose-down attitude.

The airplane sustained substantial damage to the left wing.

The pilot reported that there were no preaccident mechanical failures or malfunctions with the airplane that would have precluded normal operation.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The pilot's selection of an unsuitable off-airport landing area, which resulted in a ground loop.

Findings

Personnel issues Decision making/judgment - Pilot

Environmental issues Rough terrain - Decision related to condition

Environmental issues Rough terrain - Effect on operation

Environmental issues Wet/muddy terrain - Decision related to condition

Environmental issues Wet/muddy terrain - Effect on operation

Page 2 of 5 GAA18CA567

Factual Information

History of Flight

Landing	Collision with terr/obj (non-CFIT)
Landing	Miscellaneous/other (Defining event)
Landing	Nose over/nose down

Pilot Information

Certificate:	Private	Age:	29,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Front
Other Aircraft Rating(s):	None	Restraint Used:	4-point
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Without waivers/limitations	Last FAA Medical Exam:	June 27, 2017
Occupational Pilot:	No	Last Flight Review or Equivalent:	March 17, 2018
Flight Time:	(Estimated) 350 hours (Total, all aircraft), 135 hours (Total, this make and model), 350 hours (Pilot In Command, all aircraft), 61 hours (Last 90 days, all aircraft), 15 hours (Last 30 days, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	Piper	Registration:	N8192D
Model/Series:	PA18 150	Aircraft Category:	Airplane
Year of Manufacture:	1957	Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	18-6130
Landing Gear Type:	Tailwheel	Seats:	2
Date/Type of Last Inspection:	September 16, 2017 Annual	Certified Max Gross Wt.:	1750 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:	3693 Hrs as of last inspection	Engine Manufacturer:	Lycoming
ELT:	Not installed	Engine Model/Series:	0-360-C4P
Registered Owner:		Rated Power:	180 Horsepower
Operator:	On file	Operating Certificate(s) Held:	None

Page 3 of 5 GAA18CA567

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	PASM,312 ft msl	Distance from Accident Site:	33 Nautical Miles
Observation Time:	04:02 Local	Direction from Accident Site:	203°
Lowest Cloud Condition:		Visibility	10 miles
Lowest Ceiling:	Broken / 1000 ft AGL	Visibility (RVR):	
Wind Speed/Gusts:	7 knots /	Turbulence Type Forecast/Actual:	None / None
Wind Direction:	230°	Turbulence Severity Forecast/Actual:	N/A / N/A
Altimeter Setting:	30.04 inches Hg	Temperature/Dew Point:	10°C / 9°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	St. Mary's, AK (ksm)	Type of Flight Plan Filed:	None
Destination:	St. Mary's, AK	Type of Clearance:	None
Departure Time:		Type of Airspace:	Class G

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	1 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	62.569999,-162.850006(est)

Administrative Information

Investigator In Charge (IIC):	Benhoff, Kathryn
Additional Participating Persons:	Harold Robertson; FAA; Anchorage, AK
Original Publish Date:	April 8, 2019
Note:	This accident report documents the factual circumstances of this accident as described to the NTSB.
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=98345

Page 4 of 5 GAA18CA567

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

Page 5 of 5 GAA18CA567