



Aviation Investigation Final Report

Location: McGrath, Alaska Accident Number: GAA18CA504

Date & Time: August 20, 2018, 08:30 Local Registration: N6727A

Aircraft: Piper PA18 Aircraft Damage: Substantial

Defining Event: Loss of control on ground **Injuries:** 2 None

Flight Conducted Under: Part 91: General aviation

Analysis

The pilot of the tailwheel-equipped airplane reported that, during takeoff from a gravel, dirt airstrip, a "rogue crosswind gust of wind" pushed the airplane to the right. The airplane struck a "bump," became airborne, continued drifting right, and landed hard in a creek.

The airplane sustained substantial damage to the fuselage.

The pilot reported that there were no preaccident mechanical failures or malfunctions with the airplane that would have precluded normal operation.

The pilot reported that the prevailing wind was light and variable and not gusting. The airplane was departing to the south.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The pilot's failure to maintain directional control during takeoff in a crosswind.

Findings

Aircraft Directional control - Not attained/maintained

Personnel issues Aircraft control - Pilot

Environmental issues Crosswind - Effect on operation

Page 2 of 5 GAA18CA504

Factual Information

History of Flight

Takeoff	Other weather encounter	
Takeoff	Loss of control on ground (Defining event)	
Takeoff	Miscellaneous/other	
Takeoff	Runway excursion	
Takeoff	Collision with terr/obj (non-CFIT)	

Pilot Information

Certificate:	Airline transport; Commercial; Flight engineer; Flight instructor	Age:	72,Male
Airplane Rating(s):	Single-engine land; Single-engine sea; Multi-engine land	Seat Occupied:	Front
Other Aircraft Rating(s):	None	Restraint Used:	3-point
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	Airplane single-engine; Instrument airplane	Toxicology Performed:	No
Medical Certification:	Class 1 Without waivers/limitations	Last FAA Medical Exam:	June 5, 2018
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	December 8, 2017
Flight Time:	(Estimated) 21618 hours (Total, all aircraft), 4509 hours (Total, this make and model), 16853 hours (Pilot In Command, all aircraft), 81 hours (Last 90 days, all aircraft), 10 hours (Last 30 days, all aircraft), 1 hours (Last 24 hours, all aircraft)		

Page 3 of 5 GAA18CA504

Aircraft and Owner/Operator Information

Aircraft Make:	Piper	Registration:	N6727A
Model/Series:	PA18 150	Aircraft Category:	Airplane
Year of Manufacture:	1981	Amateur Built:	
Airworthiness Certificate:	Restricted (Special)	Serial Number:	18-8109031
Landing Gear Type:	Tailwheel	Seats:	2
Date/Type of Last Inspection:	April 19, 2018 Annual	Certified Max Gross Wt.:	1750 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:	2621 Hrs at time of accident	Engine Manufacturer:	Lycoming
ELT:	C91 installed, activated, aided in locating accident	Engine Model/Series:	O-320-A2B
Registered Owner:		Rated Power:	160 Horsepower
Operator:	On file	Operating Certificate(s) Held:	None
Operator Does Business As:	Alaska Dall Sheep Guides, LLC.	Operator Designator Code:	

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	PAFW,1060 ft msl	Distance from Accident Site:	25 Nautical Miles
Observation Time:	17:01 Local	Direction from Accident Site:	230°
Lowest Cloud Condition:	Few / 2000 ft AGL	Visibility	10 miles
Lowest Ceiling:	Overcast / 10000 ft AGL	Visibility (RVR):	
Wind Speed/Gusts:	3 knots /	Turbulence Type Forecast/Actual:	None / None
Wind Direction:	360°	Turbulence Severity Forecast/Actual:	N/A / N/A
Altimeter Setting:	30.03 inches Hg	Temperature/Dew Point:	12°C / 11°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	McGrath, AK	Type of Flight Plan Filed:	None
Destination:	Farewell, AK (0AA4)	Type of Clearance:	None
Departure Time:	08:30 Local	Type of Airspace:	Class G

Page 4 of 5 GAA18CA504

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	1 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	62.7975,-152.930831(est)

Administrative Information

Investigator In Charge (IIC):Benhoff, KathrynAdditional Participating Persons:Bruce Cummings; FAA; Anchorage, AKOriginal Publish Date:March 18, 2019Note:This accident report documents the factual circumstances of this accident as described to the NTSB.Investigation Docket:https://data.ntsb.gov/Docket?ProjectID=98139

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

Page 5 of 5 GAA18CA504