



DCA18CA272

Aviation Investigation Final Report

Location: Philadelphia, Pennsylvania Accident Number:

Date & Time: August 24, 2018, 19:55 Local Registration: EI-LBT

Aircraft: Boeing 757 Aircraft Damage: None

Defining Event: Ground handling event **Injuries:** 1 Serious, 177 None

Flight Conducted Under: Part 129: Foreign

Analysis

On August 24, 2018, about 2350 eastern daylight time, Aer Lingus flight 114, a Boeing 757-200, EI-LBT, had a ground service employee suffer a serious injury while engaged in pushback from the gate at Philadelphia International Airport (KPHL), Philadelphia, Pennsylvania. There were no injuries to 177 passengers and crew onboard. The airplane was not damaged. The flight was operated as a Title 14 *Code of Federal Regulations* Part 129 scheduled international passenger flight from KPHL to Dublin Airport (EIDW), Dublin, Ireland.

According to the operator, the ground service employee was connected to the airplane via a headset and was engaged in push-back from gate A6. At some point, the service employee fell down and the nose wheel ran over his right leg, causing a serious injury. The flight crew reported that the pushback was nearly complete and were about halfway through the 90 degree turn onto the taxi line, when the airplane jerked to a stop. There was general confusion for several minutes before they were informed of what happened.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The ground service employee's inadvertent fall near the nose wheel during pushback.

Findings

Personnel issues

Incorrect action selection - Ground crew

Page 2 of 5 DCA18CA272

Factual Information

History of Flight

Pushback/tow-engine not oper Ground handling event (Defining event)

Pilot Information

Certificate:	Airline transport	Age:	63,Male
Airplane Rating(s):	Multi-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	5-point
Instrument Rating(s):	Airplane	Second Pilot Present:	Yes
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 1 With waivers/limitations	Last FAA Medical Exam:	June 7, 2018
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	October 5, 2018
Flight Time:	25000 hours (Total, all aircraft), 5000 hours (Total, this make and model)		

Co-pilot Information

Certificate:	Airline transport	Age:	40,Male
Airplane Rating(s):	Multi-engine land	Seat Occupied:	Right
Other Aircraft Rating(s):	None	Restraint Used:	5-point
Instrument Rating(s):	Airplane	Second Pilot Present:	Yes
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:		Last FAA Medical Exam:	
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	April 12, 2018
Flight Time:	6897 hours (Total, all aircraft), 2307 hours (Total, this make and model)		

Page 3 of 5 DCA18CA272

Aircraft and Owner/Operator Information

Aircraft Make:	Boeing	Registration:	EI-LBT
Model/Series:	757 200	Aircraft Category:	Airplane
Year of Manufacture:	1998	Amateur Built:	
Airworthiness Certificate:	Transport	Serial Number:	28170
Landing Gear Type:	Retractable - Tricycle	Seats:	
Date/Type of Last Inspection:		Certified Max Gross Wt.:	115666 lbs
Time Since Last Inspection:		Engines:	
Airframe Total Time:		Engine Manufacturer:	
ELT:		Engine Model/Series:	
Registered Owner:		Rated Power:	
Operator:		Operating Certificate(s) Held:	Foreign air carrier (129)

Meteorological Information and Flight Plan

Conditions at Accident Site:	Unknown	Condition of Light:	Night
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
Lowest Cloud Condition:		Visibility	
Lowest Ceiling:		Visibility (RVR):	
Wind Speed/Gusts:	/	Turbulence Type Forecast/Actual:	/
Wind Direction:		Turbulence Severity Forecast/Actual:	1
Altimeter Setting:		Temperature/Dew Point:	
Precipitation and Obscuration:			
Departure Point:	Philadelphia, PA (PHL)	Type of Flight Plan Filed:	IFR
Destination:	Dublin, OF (EIDW)	Type of Clearance:	IFR
Departure Time:	23:50 Local	Type of Airspace:	

Page 4 of 5 DCA18CA272

Airport Information

Airport:	Philadelphia International PHL	Runway Surface Type:	
Airport Elevation:	36 ft msl	Runway Surface Condition:	Unknown
Runway Used:		IFR Approach:	None
Runway Length/Width:		VFR Approach/Landing:	None

Wreckage and Impact Information

Crew Injuries:	10 None	Aircraft Damage:	None
Passenger Injuries:	167 None	Aircraft Fire:	None
Ground Injuries:	1 Serious	Aircraft Explosion:	None
Total Injuries:	1 Serious, 177 None	Latitude, Longitude:	39.874168,-75.242225

Administrative Information

Investigator In Charge (IIC):	Lovell, John		
Additional Participating Persons:			
Original Publish Date:	June 3, 2021	Investigation Class:	4
Note:	This accident report documents the factual circumstances of this accident as described to the NTSB.		
Investigation Docket:	https://data.ntsb.gov/Docket?	ProjectID=98174	

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

Page 5 of 5 DCA18CA272