



Aviation Investigation Final Report

Location: Fairbanks, Alaska Accident Number: GAA17CA147

Date & Time: February 18, 2017, 17:08 Local Registration: N185AE

Aircraft: Cessna A185 Aircraft Damage: Substantial

Defining Event: Loss of visual reference **Injuries:** 1 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

The pilot reported that, during the first landing of a currency flight, he "never realized he was low on the approach" and that the airplane impacted a snow-covered area short of the asphalt runway and nosed over. He added that the flight was conducted in "reduced light conditions" and that he "did not recognize the conditions as being flat light."

The vertical stabilizer sustained substantial damage.

The pilot reported that there were no preaccident mechanical malfunctions or failures with the airplane that would have precluded normal operation.

The National Weather Service reported that the sun set about 25 minutes after the accident.

The Federal Aviation Administration Chart Supplement stated, in part, that the landing runway was equipped with a precision approach path indicator.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The pilot's failure to maintain an appropriate glidepath to the runway and to use the vertical guidance system.

Findings

Personnel issues Aircraft control - Pilot

Personnel issues Use of available resources - Pilot

Aircraft Descent/approach/glide path - Not attained/maintained

Environmental issues Snowy/icy terrain - Effect on equipment

Environmental issues (general) - Effect on personnel

Page 2 of 5 GAA17CA147

Factual Information

History of Flight

Approach-VFR pattern final	Loss of visual reference (Defining event)	
Approach-VFR pattern final	Collision with terr/obj (non-CFIT)	

Pilot Information

Certificate:	Private	Age:	64,Male
Airplane Rating(s):	Single-engine land; Single-engine sea; Multi-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	4-point
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Waiver time limited special	Last FAA Medical Exam:	March 14, 2016
Occupational Pilot:	No	Last Flight Review or Equivalent:	September 1, 2015
Flight Time:	(Estimated) 1952 hours (Total, all aircraft), 46 hours (Total, this make and model), 1888 hours (Pilot In Command, all aircraft), 2 hours (Last 90 days, all aircraft), 0 hours (Last 30 days, all aircraft), 0 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	Cessna	Registration:	N185AE
Model/Series:	A185 F	Aircraft Category:	Airplane
Year of Manufacture:	1973	Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	18502125
Landing Gear Type:	Tailwheel	Seats:	4
Date/Type of Last Inspection:	September 1, 2016 Annual	Certified Max Gross Wt.:	3350 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:	2853.5 Hrs at time of accident	Engine Manufacturer:	Continental
ELT:	C91 installed, not activated	Engine Model/Series:	IO-520-D24
Registered Owner:		Rated Power:	300 Horsepower
Operator:	On file	Operating Certificate(s) Held:	None

Page 3 of 5 GAA17CA147

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	PAFA,439 ft msl	Distance from Accident Site:	0 Nautical Miles
Observation Time:	02:53 Local	Direction from Accident Site:	0°
Lowest Cloud Condition:	Few / 5500 ft AGL	Visibility	10 miles
Lowest Ceiling:	Broken / 12000 ft AGL	Visibility (RVR):	
Wind Speed/Gusts:	5 knots /	Turbulence Type Forecast/Actual:	/ None
Wind Direction:	200°	Turbulence Severity Forecast/Actual:	/ N/A
Altimeter Setting:	29.62 inches Hg	Temperature/Dew Point:	-14°C / -18°C
Precipitation and Obscuration:	No Obscuration; No Precipita	ation	
Departure Point:	Fairbanks, AK (FAI)	Type of Flight Plan Filed:	None
Destination:	Fairbanks, AK (FAI)	Type of Clearance:	VFR
Departure Time:		Type of Airspace:	Class D

Airport Information

Airport:	FAIRBANKS INTL FAI	Runway Surface Type:	Asphalt
Airport Elevation:	439 ft msl	Runway Surface Condition:	Ice;Snow
Runway Used:	20L	IFR Approach:	None
Runway Length/Width:	6501 ft / 100 ft	VFR Approach/Landing:	Stop and go;Traffic pattern

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	64.815002,-147.856384(est)

Page 4 of 5 GAA17CA147

Administrative Information

Investigator In Charge (IIC): Gerhardt, Adam

Additional Participating Persons: William Mallula; FAA/ FSDO; Fairbanks, AK

Original Publish Date: June 7, 2017

Note: This accident report documents the factual circumstances of this accident as described to

the NTSB.

Investigation Docket: https://data.ntsb.gov/Docket?ProjectID=94746

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

The Independent Safety Board Act, as codified at 49 U.S.C. Section 1154(b), precludes the admission into evidence or use of any part of an NTSB report related to an incident or accident in a civil action for damages resulting from a matter mentioned in the report. A factual report that may be admissible under 49 U.S.C. § 1154(b) is available here.

Page 5 of 5 GAA17CA147