



Aviation Investigation Final Report

Location: Northway, Alaska Accident Number: GAA18CA541

Date & Time: September 5, 2018, 16:25 Local Registration: N413CC

Aircraft: CUB CRAFTERS INC CC18 Aircraft Damage: Substantial

Defining Event: Birdstrike **Injuries:** 2 None

Flight Conducted Under: Part 91: General aviation - Other work use

Analysis

The pilot reported that, during straight-and-level flight, a large bird struck the airplane's right wing. The airplane's control became degraded, and the pilot chose an off-airport landing site and landed the airplane without further incident.

The airplane sustained substantial damage to the right wing.

The pilot reported that there were no preaccident mechanical failures or malfunctions with the airplane that would have precluded normal operation.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The airplane's collision with a bird during straight-and-level flight.

Findings

Environmental issues

Animal(s)/bird(s) - Effect on operation

Factual Information

History of Flight

Enroute	Birdstrike (Defining event)
Landing	Off-field or emergency landing

Pilot Information

Certificate:	Airline transport; Commercial; Flight instructor	Age:	64,Male
Airplane Rating(s):	Single-engine land; Single-engine sea; Multi-engine land	Seat Occupied:	Front
Other Aircraft Rating(s):	Helicopter	Restraint Used:	4-point
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	Airplane single-engine	Toxicology Performed:	No
Medical Certification:	Class 2 With waivers/limitations	Last FAA Medical Exam:	March 22, 2018
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	April 6, 2018
Flight Time:	(Estimated) 20499 hours (Total, all aircraft), 664 hours (Total, this make and model), 20174 hours (Pilot In Command, all aircraft), 152 hours (Last 90 days, all aircraft), 36 hours (Last 30 days, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	CUB CRAFTERS INC	Registration:	N413CC
Model/Series:	CC18 180	Aircraft Category:	Airplane
Year of Manufacture:	2013	Amateur Built:	
Airworthiness Certificate:	Normal; Restricted (Special)	Serial Number:	CC18-0065
Landing Gear Type:	Tailwheel	Seats:	2
Date/Type of Last Inspection:	August 20, 2018 Annual	Certified Max Gross Wt.:	2300 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:	740.6 Hrs as of last inspection	Engine Manufacturer:	Lycoming
ELT:	C126 installed, not activated	Engine Model/Series:	0-360-C4P
Registered Owner:		Rated Power:	180 Horsepower
Operator:		Operating Certificate(s) Held:	None

Page 2 of 4 GAA18CA541

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	PABN,2880 ft msl	Distance from Accident Site:	14 Nautical Miles
Observation Time:	00:53 Local	Direction from Accident Site:	296°
Lowest Cloud Condition:		Visibility	10 miles
Lowest Ceiling:	Overcast / 5000 ft AGL	Visibility (RVR):	
Wind Speed/Gusts:	5 knots /	Turbulence Type Forecast/Actual:	None / None
Wind Direction:	310°	Turbulence Severity Forecast/Actual:	N/A / N/A
Altimeter Setting:	30.28 inches Hg	Temperature/Dew Point:	12°C / 4°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Chisana, AK (CZN)	Type of Flight Plan Filed:	Company VFR
Destination:	Gulkana, AK (GKN)	Type of Clearance:	None
Departure Time:		Type of Airspace:	Class G

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	1 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	62.300277,-142.53334(est)

Administrative Information

Investigator In Charge (IIC):	Swenson, Eric
Additional Participating Persons:	Pete Alexakis; FAA; Fairbanks, AK
Original Publish Date:	March 18, 2019
Note:	This accident report documents the factual circumstances of this accident as described to the NTSB.
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=98269

Page 3 of 4 GAA18CA541

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

Page 4 of 4 GAA18CA541