



Aviation Investigation Final Report

Location: Phoenix, Arizona Accident Number: GAA18CA338

Date & Time: June 12, 2018, 11:00 Local Registration: N2094B

Aircraft: Luscombe 8 Aircraft Damage: Substantial

Defining Event: Loss of control on ground **Injuries:** 1 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

The pilot of the tailwheel-equipped airplane reported that, during landing, the airplane ballooned, He then added power and "lost control on the second touchdown." The airplane landed, exited the runway to the left, and came to rest inverted.

The airplane sustained substantial damage to the left wing.

The pilot reported that there were no preaccident mechanical failures or malfunctions with the airplane that would have precluded normal operation.

The automated weather observation station located on the airport reported that, about the time of the accident, the wind was from 190° at 3 knots. The airplane landed on runway 25R.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The pilot's improper landing flare and subsequent failure to maintain directional control during landing.

Findings

| Personnel issues | Aircraft control - Pilot |
|-------------------|----------------------------|
| reisoillei issues | All Clait Colltion - Filot |

Aircraft Directional control - Not attained/maintained

Aircraft Landing flare - Not attained/maintained

Page 2 of 5 GAA18CA338

Factual Information

History of Flight

| Landing | Abnormal runway contact |
|---------|--------------------------------------------|
| Landing | Loss of control on ground (Defining event) |
| Landing | Runway excursion |
| Landing | Nose over/nose down |

Pilot Information

| Certificate: | Private | Age: | 81,Male |
|---------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------|--------------------|
| Airplane Rating(s): | Single-engine land | Seat Occupied: | Left |
| Other Aircraft Rating(s): | Glider | Restraint Used: | 3-point |
| Instrument Rating(s): | Airplane | Second Pilot Present: | No |
| Instructor Rating(s): | None | Toxicology Performed: | No |
| Medical Certification: | Class 3 Without waivers/limitations | Last FAA Medical Exam: | September 21, 2017 |
| Occupational Pilot: | No | Last Flight Review or Equivalent: | September 27, 2017 |
| Flight Time: | (Estimated) 3228 hours (Total, all aircraft), 1 hours (Total, this make and model), 30 hours (Last 90 days, all aircraft), 24 hours (Last 30 days, all aircraft), 1 hours (Last 24 hours, all aircraft) | | |

Page 3 of 5 GAA18CA338

Aircraft and Owner/Operator Information

| Luscombe | Registration: | N2094B |
|--------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 8 A | Aircraft Category: | Airplane |
| 1949 | Amateur Built: | |
| Normal | Serial Number: | 6521 |
| Tailwheel | Seats: | 2 |
| May 12, 2018 Annual | Certified Max Gross Wt.: | 1260 lbs |
| | Engines: | 1 Reciprocating |
| 4010 Hrs as of last inspection | Engine Manufacturer: | Continental |
| Installed, activated, did not aid in locating accident | Engine Model/Series: | A65 |
| | Rated Power: | 65 Horsepower |
| On file | Operating Certificate(s) Held: | None |
| | 8 A 1949 Normal Tailwheel May 12, 2018 Annual 4010 Hrs as of last inspection Installed, activated, did not aid in locating accident | 8 A Aircraft Category: 1949 Amateur Built: Normal Serial Number: Tailwheel Seats: May 12, 2018 Annual Certified Max Gross Wt.: Engines: 4010 Hrs as of last inspection Engine Manufacturer: Installed, activated, did not aid in locating accident Engine Model/Series: On file Operating Certificate(s) |

Meteorological Information and Flight Plan

| Conditions at Accident Site: | Visual (VMC) | Condition of Light: | Day |
|----------------------------------|----------------------------------|-----------------------------------------|------------------|
| Observation Facility, Elevation: | KDVT,1455 ft msl | Distance from Accident Site: | 0 Nautical Miles |
| Observation Time: | 17:53 Local | Direction from Accident Site: | 234° |
| Lowest Cloud Condition: | Clear | Visibility | 10 miles |
| Lowest Ceiling: | None | Visibility (RVR): | |
| Wind Speed/Gusts: | 3 knots / | Turbulence Type Forecast/Actual: | / None |
| Wind Direction: | 190° | Turbulence Severity Forecast/Actual: | / N/A |
| Altimeter Setting: | 29.84 inches Hg | Temperature/Dew Point: | 36°C / -5°C |
| Precipitation and Obscuration: | No Obscuration; No Precipitation | | |
| Departure Point: | CHANDLER, AZ (CHD) | Type of Flight Plan Filed: | None |
| Destination: | Phoenix, AZ (DVT) | Type of Clearance: | Unknown |
| Departure Time: | 10:00 Local | Type of Airspace: | Class D |
| | | | |

Page 4 of 5 GAA18CA338

Airport Information

| Airport: | PHOENIX DEER VALLEY DVT | Runway Surface Type: | Asphalt |
|----------------------|-------------------------|----------------------------------|---------------------------|
| Airport Elevation: | 1478 ft msl | Runway Surface Condition: | Dry |
| Runway Used: | 25R | IFR Approach: | None |
| Runway Length/Width: | 4500 ft / 75 ft | VFR Approach/Landing: | Full stop;Traffic pattern |

Wreckage and Impact Information

| Crew Injuries: | 1 None | Aircraft Damage: | Substantial |
|---------------------|--------|-------------------------|---------------------------|
| Passenger Injuries: | | Aircraft Fire: | None |
| Ground Injuries: | N/A | Aircraft Explosion: | None |
| Total Injuries: | 1 None | Latitude, Longitude: | 33.689723,-112.07917(est) |

Administrative Information

| Investigator In Charge (IIC): | Benhoff, Kathryn |
|-----------------------------------|-----------------------------------------------------------------------------------------------------|
| Additional Participating Persons: | |
| Original Publish Date: | November 5, 2018 |
| Note: | This accident report documents the factual circumstances of this accident as described to the NTSB. |
| Investigation Docket: | https://data.ntsb.gov/Docket?ProjectID=97455 |

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

Page 5 of 5 GAA18CA338