



Aviation Investigation Final Report

Location: Perris, California Accident Number: GAA16CA464

Date & Time: September 3, 2016, 13:00 Local Registration: N7296C

Aircraft: North American SNJ Aircraft Damage: Substantial

Defining Event: Loss of control on ground **Injuries:** 2 None

Flight Conducted Under: Part 91: General aviation

Analysis

The pilot of the tailwheel equipped airplane reported that during the landing roll out with the tailwheel down, the tail of the airplane lifted back into the air, at that time he attempted to abort the landing. The pilot further reported that when the airplane became airborne the left wing dropped, then the right, both of which he countered. Subsequently, the left wing dropped again and struck the ground. The airplane exited the runway to the left and came to rest on its nose. The airplane sustained substantial damage to the left wing and aileron.

After the accident, witnesses reported to the pilot that a dust devil had touched down in front of the airplane during the landing.

The pilot reported that there were no pre impact mechanical failures or malfunctions with the airframe or engine that would have precluded normal operation.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The pilot's inability to compensate for a dust devil during an aborted landing, which resulted in the left wing contacting the ground, a runway excursion, and the airplane coming to rest in a nose-down attitude.

Findings

Aircraft Directional control - Attain/maintain not possible

Personnel issues Aircraft control - Pilot

Environmental issues Dust devil/whirlwind - Ability to respond/compensate

Page 2 of 5 GAA16CA464

Factual Information

History of Flight

Landing-aborted after touchdown	Other weather encounter
Landing-aborted after touchdown	Dragged wing/rotor/float/other
Landing-aborted after touchdown	Loss of control on ground (Defining event)
Landing-aborted after touchdown	Runway excursion
Landing-aborted after touchdown	Nose over/nose down

Pilot Information

Certificate:	Commercial	Age:	45,Male	
Airplane Rating(s):	Single-engine land	Seat Occupied:	Front	
Other Aircraft Rating(s):	None	Restraint Used:	4-point	
Instrument Rating(s):	None	Second Pilot Present:	No	
Instructor Rating(s):	None Toxicology Performed: No			
Medical Certification:	Class 2 Without waivers/limitations	Last FAA Medical Exam:	December 3, 2015	
Occupational Pilot:	No	Last Flight Review or Equivalent:	December 2, 2015	
Flight Time:	(Estimated) 620 hours (Total, all aircraft), 53.4 hours (Total, this make and model), 580 hours (Pilot In Command, all aircraft), 29.1 hours (Last 90 days, all aircraft)			

Passenger Information

Certificate: Age: Male Airplane Rating(s): Seat Occupied: Rear Other Aircraft Rating(s): Restraint Used: 4-point Instrument Rating(s): Second Pilot Present: No Instructor Rating(s): Toxicology Performed: No Medical Certification: Last FAA Medical Exam:				
Other Aircraft Rating(s): Restraint Used: 4-point Instrument Rating(s): Second Pilot Present: No Instructor Rating(s): Toxicology Performed: No	Certificate:		Age:	Male
Instrument Rating(s): Second Pilot Present: No Instructor Rating(s): Toxicology Performed: No	Airplane Rating(s):		Seat Occupied:	Rear
Instructor Rating(s): Toxicology Performed: No	Other Aircraft Rating(s):		Restraint Used:	4-point
	Instrument Rating(s):		Second Pilot Present:	No
Medical Certification: Last FAA Medical Exam:	Instructor Rating(s):		Toxicology Performed:	No
	Medical Certification:		Last FAA Medical Exam:	
Occupational Pilot: UNK Last Flight Review or Equivalent:	Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:	Flight Time:			

Page 3 of 5 GAA16CA464

Aircraft and Owner/Operator Information

Aircraft Make:	North American	Registration:	N7296C
Model/Series:	SNJ 5	Aircraft Category:	Airplane
Year of Manufacture:	1944	Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	84979
Landing Gear Type:	Retractable - Tailwheel	Seats:	2
Date/Type of Last Inspection:	January 19, 2016 Annual	Certified Max Gross Wt.:	
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:	5590 Hrs	Engine Manufacturer:	P&W
ELT:	Installed, not activated	Engine Model/Series:	R1340 - AN1
Registered Owner:		Rated Power:	600 Horsepower
Operator:	On file	Operating Certificate(s) Held:	Commercial air tour (136)

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	KRIV,1536 ft msl	Distance from Accident Site:	8 Nautical Miles
Observation Time:	19:58 Local	Direction from Accident Site:	349°
Lowest Cloud Condition:	Clear	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	2 knots /	Turbulence Type Forecast/Actual:	/ Clear air
Wind Direction:		Turbulence Severity Forecast/Actual:	/ N/A
Altimeter Setting:	29.87 inches Hg	Temperature/Dew Point:	24°C / 13°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Perris, CA (L65)	Type of Flight Plan Filed:	None
Destination:	Perris, CA (L65)	Type of Clearance:	VFR
Departure Time:		Type of Airspace:	Class G

Page 4 of 5 GAA16CA464

Airport Information

Airport:	PERRIS VALLEY L65	Runway Surface Type:	Asphalt
Airport Elevation:	1413 ft msl	Runway Surface Condition:	Dry
Runway Used:	15	IFR Approach:	None
Runway Length/Width:	5100 ft / 50 ft	VFR Approach/Landing:	Full stop

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	1 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	33.76361,-117.218612(est)

Administrative Information

Investigator In Charge (IIC):	Swenson, Eric
Additional Participating Persons:	Ronald Allen; FAA; Riverside, CA
Original Publish Date:	December 5, 2016
Note:	This accident report documents the factual circumstances of this accident as described to the NTSB.
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=93953

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

Page 5 of 5 GAA16CA464