

# **Aviation Investigation Final Report**

**Location:** Hunter, New York **Accident Number:** GAA18CA515

Date & Time: August 9, 2018, 19:10 Local Registration: N26LD

Aircraft: DELL LAWRENCE Kitfox Aircraft Damage: Substantial

**Defining Event:** Loss of control on ground **Injuries:** 1 None

Flight Conducted Under: Part 91: General aviation - Personal

#### **Analysis**

A Federal Aviation Administration inspector reported that the pilot of the tailwheel-equipped airplane made a precautionary landing on a field because of low fuel. During the landing roll, the airplane nosed over.

The airplane sustained substantial damage to the rudder and vertical stabilizer.

# **Probable Cause and Findings**

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The pilot's inadequate in-flight fuel management, which necessitated an off-airport precautionary landing, and his failure to maintain airplane control during the landing roll on rough terrain.

# **Findings**

Personnel issues Aircraft control - Pilot

Aircraft (general) - Not attained/maintained

**Environmental issues** Rough terrain - Effect on operation

Personnel issues Use of equip/system - Pilot

Aircraft Fuel - Fluid management

Page 2 of 5 GAA18CA515

# **Factual Information**

# **History of Flight**

**Landing** Off-field or emergency landing

Landing-flare/touchdown Loss of control on ground (Defining event)

Landing-flare/touchdown Nose over/nose down

#### **Pilot Information**

Certificate:	Private	Age:	64,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Unknown
Other Aircraft Rating(s):	None	Restraint Used:	Unknown
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 With waivers/limitations	Last FAA Medical Exam:	December 1, 2016
Occupational Pilot:	No	Last Flight Review or Equivalent:	
Flight Time:	(Estimated)		

# **Aircraft and Owner/Operator Information**

Aircraft Make:	DELL LAWRENCE	Registration:	N26LD
Model/Series:	Kitfox Super Spor	Aircraft Category:	Airplane
Year of Manufacture:	2010	Amateur Built:	Yes
Airworthiness Certificate:	Other; Experimental (Special)	Serial Number:	KA08184136
Landing Gear Type:	Tricycle	Seats:	2
Date/Type of Last Inspection:	Unknown	Certified Max Gross Wt.:	
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:		Engine Manufacturer:	Continental
ELT:		Engine Model/Series:	0-200 Series
Registered Owner:		Rated Power:	
Operator:	On file	Operating Certificate(s) Held:	None

Page 3 of 5 GAA18CA515

# Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	KALB,292 ft msl	Distance from Accident Site:	33 Nautical Miles
Observation Time:	22:51 Local	Direction from Accident Site:	38°
<b>Lowest Cloud Condition:</b>	Few / 21000 ft AGL	Visibility	10 miles
Lowest Ceiling:		Visibility (RVR):	
Wind Speed/Gusts:	10 knots /	Turbulence Type Forecast/Actual:	None / None
Wind Direction:	290°	Turbulence Severity Forecast/Actual:	N/A / N/A
Altimeter Setting:	29.8 inches Hg	Temperature/Dew Point:	26°C / 15°C
Precipitation and Obscuration:			
Departure Point:	Jamestown, NY (JHW )	Type of Flight Plan Filed:	None
Destination:	Hudson, NY (1B1 )	Type of Clearance:	None
Departure Time:		Type of Airspace:	Class G

# Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	42.316665,-74.26667(est)

# **Administrative Information**

Investigator In Charge (IIC):	Nepomuceno, Eleazar
Additional Participating Persons:	Timothy Shaver; FAA; Albany, NY
Original Publish Date:	March 20, 2020
Note:	This accident report documents the factual circumstances of this accident as described to the NTSB.
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=98180

Page 4 of 5 GAA18CA515

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

Page 5 of 5 GAA18CA515