



Aviation Investigation Final Report

Location: Americus, Georgia Accident Number: GAA19CA078

Date & Time: November 28, 2018, 10:15 Local Registration: N843WA

Aircraft: Air Tractor AT 502 Aircraft Damage: Substantial

Defining Event: Low altitude operation/event **Injuries:** 1 None

Flight Conducted Under: Part 137: Agricultural

Analysis

The pilot reported that, during an agricultural application flight, he surveyed a field before spraying and saw multiple power lines and poles. While spraying the field and after turning, about 20 ft above the ground, he pulled up and immediately felt "a massive jerk" and saw a "flash" due to the airplane's nose striking a power wire. The airplane entered a descending turn to an open field adjacent to the spray field. The pilot pushed the power lever forward but did not get a response. During the forced landing, the right wing struck a tree, the airplane rotated 180°, and the left wing and empennage impacted the ground.

The airplane sustained substantial damage to the left wing and fuselage.

The pilot reported that there were no preaccident mechanical failures or malfunctions with the airplane that would have precluded normal operation.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The pilot's failure to see and avoid a power line during an agricultural application flight.

Findings

Personnel issues Monitoring environment - Pilot

Aircraft Altitude - Not attained/maintained

Environmental issues Wire - Effect on operation

Environmental issues Tree(s) - Contributed to outcome

Page 2 of 5 GAA19CA078

Factual Information

History of Flight

Maneuvering-low-alt flying	Low altitude operation/event (Defining event)	
Landing	Off-field or emergency landing	

Pilot Information

Certificate:	Commercial	Age:	27,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Front
Other Aircraft Rating(s):	None	Restraint Used:	4-point
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 2 With waivers/limitations	Last FAA Medical Exam:	May 11, 2018
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	January 12, 2017
Flight Time:	(Estimated) 2537 hours (Total, all aircraft), 400 hours (Total, this make and model), 2537 hours (Pilot In Command, all aircraft), 250 hours (Last 90 days, all aircraft), 100 hours (Last 30 days, all aircraft), 3 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Air Tractor	Registration:	N843WA
AT 502 Undesignat	Aircraft Category:	Airplane
1988	Amateur Built:	
Restricted (Special)	Serial Number:	502-0011
Tailwheel	Seats:	1
October 29, 2018 100 hour	Certified Max Gross Wt.:	8000 lbs
	Engines:	1 Turbo prop
14124.6 Hrs as of last inspection	Engine Manufacturer:	P&W
Not installed	Engine Model/Series:	PT6A-34
	Rated Power:	750 Horsepower
	Operating Certificate(s) Held:	Agricultural aircraft (137)
	AT 502 Undesignat 1988 Restricted (Special) Tailwheel October 29, 2018 100 hour 14124.6 Hrs as of last inspection	AT 502 Undesignat Aircraft Category: 1988 Amateur Built: Restricted (Special) Serial Number: Tailwheel Seats: October 29, 2018 100 hour Certified Max Gross Wt.: Engines: 14124.6 Hrs as of last inspection Not installed Engine Manufacturer: Rated Power: Operating Certificate(s)

Page 3 of 5 GAA19CA078

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	KACJ,468 ft msl	Distance from Accident Site:	7 Nautical Miles
Observation Time:	15:15 Local	Direction from Accident Site:	52°
Lowest Cloud Condition:	Clear	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	5 knots /	Turbulence Type Forecast/Actual:	None / None
Wind Direction:	340°	Turbulence Severity Forecast/Actual:	N/A / N/A
Altimeter Setting:	30.2 inches Hg	Temperature/Dew Point:	5°C / -9°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Americus, GA (ACJ)	Type of Flight Plan Filed:	None
Destination:	Americus, GA (ACJ)	Type of Clearance:	None
Departure Time:	09:45 Local	Type of Airspace:	Class G

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	32.039722,-84.294166(est)

Administrative Information

Investigator In Charge (IIC):	Benhoff, Kathryn
Additional Participating Persons:	Danny Cox; FAA; Atlanta, GA
Original Publish Date:	September 26, 2019
Note:	This accident report documents the factual circumstances of this accident as described to the NTSB.
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=98698

Page 4 of 5 GAA19CA078

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

Page 5 of 5 GAA19CA078