



# **Aviation Investigation Final Report**

Location: Salina, Kansas Accident Number: GAA19CA042

Date & Time: October 26, 2018, 14:30 Local Registration: N822KS

Aircraft: Cessna 172 Aircraft Damage: Substantial

**Defining Event:** Hard landing **Injuries:** 1 None

Flight Conducted Under: Part 91: General aviation - Instructional

#### **Analysis**

The solo student pilot reported that, while performing a touch-and-go landing, upon touchdown, the airplane landed hard and bounced. He added full power to go around, determined that the airplane was flying normally, and continued in the traffic pattern. He landed the airplane a second time, and it bounced a little, and he then taxied the airplane to the ramp without further incident.

The airplane sustained substantial damage to the fuselage.

The student reported that there were no preaccident mechanical failures or malfunctions with the airplane that would have precluded normal operation.

#### **Probable Cause and Findings**

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The student pilot's improper landing flare, which resulted in a hard, bounced landing.

# **Findings**

Aircraft	Landing flare - Not attained/maintained	
Personnel issues	Aircraft control - Student/instructed pilot	

Page 2 of 5 GAA19CA042

# **Factual Information**

# **History of Flight**

Landing	Hard landing (Defining event)
Landing	Attempted remediation/recovery
Landing	Miscellaneous/other

### **Student pilot Information**

·			
Certificate:	Student	Age:	18,Male
Airplane Rating(s):	None	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	Lap only
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 1 With waivers/limitations	Last FAA Medical Exam:	June 18, 2018
Occupational Pilot:	No	Last Flight Review or Equivalent:	
Flight Time:	(Estimated) 21.5 hours (Total, all aircraft), 21.5 hours (Total, this make and model), 0.4 hours (Pilot In Command, all aircraft), 21.5 hours (Last 90 days, all aircraft), 9.6 hours (Last 30 days, all aircraft)		

# **Aircraft and Owner/Operator Information**

Aircraft Make:	Cessna	Registration:	N822KS
Model/Series:	172 R	Aircraft Category:	Airplane
Year of Manufacture:	1998	Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	17280545
Landing Gear Type:	Tricycle	Seats:	4
Date/Type of Last Inspection:	August 24, 2018 Annual	Certified Max Gross Wt.:	2450 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:	7488 Hrs as of last inspection	Engine Manufacturer:	Lycoming
ELT:	C126 installed, not activated	Engine Model/Series:	IO-360-L2A
Registered Owner:		Rated Power:	180 Horsepower
Operator:		Operating Certificate(s) Held:	Pilot school (141)

Page 3 of 5 GAA19CA042

### **Meteorological Information and Flight Plan**

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	KSLN,1289 ft msl	Distance from Accident Site:	1 Nautical Miles
Observation Time:	19:53 Local	Direction from Accident Site:	200°
<b>Lowest Cloud Condition:</b>	Clear	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	4 knots /	Turbulence Type Forecast/Actual:	None / None
Wind Direction:	320°	Turbulence Severity Forecast/Actual:	N/A / N/A
Altimeter Setting:	29.88 inches Hg	Temperature/Dew Point:	17°C / 9°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Salina, KS (SLN )	Type of Flight Plan Filed:	None
Destination:	Salina, KS (SLN )	Type of Clearance:	VFR
Departure Time:	14:00 Local	Type of Airspace:	Class D

# **Airport Information**

Airport:	SALINA RGNL SLN	Runway Surface Type:	Asphalt
Airport Elevation:	1288 ft msl	<b>Runway Surface Condition:</b>	Dry
Runway Used:	36	IFR Approach:	None
Runway Length/Width:	4301 ft / 75 ft	VFR Approach/Landing:	Touch and go

# Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	38.784999,-97.645835(est)

Page 4 of 5 GAA19CA042

#### **Administrative Information**

Investigator In Charge (IIC): Benhoff, Kathryn

Additional Participating Persons: Megan Sayre; FAA; Wichita, KS

Original Publish Date: June 5, 2019

Note: This accident report documents the factual circumstances of this accident as described to

the NTSB.

Investigation Docket: <a href="https://data.ntsb.gov/Docket?ProjectID=98579">https://data.ntsb.gov/Docket?ProjectID=98579</a>

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

The Independent Safety Board Act, as codified at 49 U.S.C. Section 1154(b), precludes the admission into evidence or use of any part of an NTSB report related to an incident or accident in a civil action for damages resulting from a matter mentioned in the report. A factual report that may be admissible under 49 U.S.C. § 1154(b) is available <a href="here">here</a>.

Page 5 of 5 GAA19CA042