
Example

Three Joints RPP Manipulator





OUTPUTS

Min q(2)=0Max q(2)=2

Min q(3) = 0

 $\max q(3)=4$

