

Koy to Accosement



LOW



MEDILIM



COMPANY NAME: BEAVER FLOORCARE

CLIENT: APPLE

SITE: APPLE R255 TOUCHWOOD SOLIHULL

ACTIVITY: STONE FLOOR MAINTENANCE & RE-FINISHING

DATE OF RISK ASSESSMENT: 14th November 2017

ПСП

**AUTHOR: D.CAMPTON** 

LOW Minor Impact	MEDIUM  Moderate Impact	HIGH Disaster
	•	
PERSONS/PROPERTY	CONTROLLED RISK	SUMMARY OF PROTECTIVE & PREVENTIVE
AT RISK		MEASURES
De com Demonsol		Mark asharkulad autoida of tradina timos
	LOW	Work scheduled outside of trading times.
Site Personnel		Extensive Staff Training in restoration/ cleaning techniques
		Training in Site Housekeeping
		Need for working in manageable areas
		Avoidance of trailing cables etc
		Use of Hazard Warning Signage at all times
		<ul> <li>Areas cordoned off as required - barriers, barrier tape, signs</li> </ul>
		Spill procedures established
		Safety footwear worn by technicians
Beaver Personnel	I OW	Training provided in chemical use.
	2011	Use of non-hazardous chemicals whenever possible
		Special Training in use of Ardex R65P
Ballaling Fabric		Dispenser pumps , gloves used to prevent skin contact
		PPE to be used - masks, glasses, gloves ,protective clothing
		Protective masking to areas wherever required
		· ·
		Eye Wash in First Aid Kits carried on Site.
	Minor Impact Damage quickly repaired PERSONS/PROPERTY	Minor Impact Damage quickly repaired  PERSONS/PROPERTY AT RISK  Beaver Personnel Site Personnel Site Personnel Site Personnel Site Personnel

Restoration and Maintenance of Carpet, Marble, Vinyl, Rubber and Wood

Reg. Office The Barn, Oldberrow Manor, Ullenhall Lane, Ullenhall, Warwickshire B95 5PF Tel: 01564 742095 Fax: 01564 742853

Beaver Floorcare Ltd.: Registered in England No. 6695922 info@beaverfloorcare.co.uk www.beaverfloorcare.co.uk www.beaverfloorcare.co.uk



CLIENT:







COMPANY NAME: BEAVER FLOORCARE

APPLE

SITE: APPLE R255 TOUCHWOOD SOLIHULL

ACTIVITY: STONE FLOOR MAINTENANCE & RE-FINISHING

DATE OF RISK ASSESSMENT: 14th November 2017 AUTHOR: D.CAMPTON

when works completed.

Key to Assessment	LOW	MEDIUM	HIGH	
	Minor Impact	Moderate Impact	Disaster	
	Damage quickly repaired	Partial Loss of Operations	Very Serious Consequences	
HAZARD	PERSONS/PROPERTY	CONTROLLED RISK	SUMMARY OF PROTECTIVE & PREVENTIVE	
	AT RISK		MEASURES	
Mercentaglestel	Beaver Personnel	LOW	Training in Manual Handling to another correct	
Musculoskeletal	Beaver Personnei	LOW	Training in Manual Handling to ensure correct	
Disorders			<ul> <li>lifting of cleaning equipment, furniture etc.</li> <li>Use of provided wheels to assist with furniture moving.</li> </ul>	
- Transporting cleaning equipment			Training in correct use of cleaning machinery -e.g height etc	
- Moving furniture at site			adjustment of rotary machines to ensure no torque	
- Using cleaning/reprocessing equpt			Regular checks to machines including vibration etc	
- Working awkwardly e.g. on knees			Try to avoid awkward working , if not , ensure adequate	
Working awkwarary e.g. on knees			rest periods. Knee pads provided.	
			Safety shoes worn by staff to prevent foot damage.	
			carety enece from system to provent feet damage.	
Electrical Hazards	Beaver Personnel	LOW	Machinery used with RCD's to prevent electrocution, shocks &	
- shocks	Site Premises		any interruption to supply	
			Staff trained in the safe use of electrical equipment	
			Regular PAT Testing & checks in accordance with	
			Provision & Use of Equipment at Work Regs. 1998	
			Masking to supply points and data ports.	
Noise	Beaver Personnel	LOW	Noise levels monitored - ear plugs provided	
Damage to Site / Mall	Site Premises	LOW	Filtration to sedimentation tanks to prevent suspended calcium	
Damage to Site / Imaii	Fixtures & Fittings		deposits from blocking drains	
	Tixtures & Tittings		All due care and protective measures taken to ensure no	
			splashing or impact damage to fixtures & fittings	
			Extra care and protective measures to be taken when working	
			Mallside to ensure no splashing or damage to Mall floor	
			Mallside area to be inspected & signed off by Supervisor	
			Manage and to be inspected a digited on by capetvide	