Project Snagging Report



Produced By: Accelerate
For: BNPPRE Belgrave House
Date:19th January 2018

Building: Belgrave House

Building Manager: William Ball

Accelerate Project Lead: Gary Morgan

Beaver Floor Care Project Lead: Tom Campton

Project: Ground Stone Floor Restoration Project

Start Date: 8th January 2018

End Date: 19th January 2018

Phase: 1 of 1

Snagged Item Description

Brass strip in main reception front x 2 scuffed from restoration process. Also, to investigate staining around joint is this water ingress, if so expected drying time?


Snag



Stone restoration process appears different around the metal strip at the rear of the BGH front reception desk.

Edges appear to have been missed leaving an arch with a clearly visible dirt line.

From a more distant view on photo 2, the same appears all along this metal detailing strip.



Various Grouting Issues, Front and rear reception Belgrave House.

Images of various black areas of grouting that still need to be replaced and blended to the appearance of the floor.

In terms of the finish to the floor, this element has a particularly negative effect on the final finish.



There are two holes yet to be filled and color matched to the stone flooring, these are both present in the front reception area to Belgrave House. All six passenger lift cars still require finishing, grouting, cracks and color matching. The clean has been completed but not sealant or shine final finish applied, is this due to the outstanding works to be finished?



Snagged Item Description	Snag	

Accelerate Corn Exchange Business Centre Market Place Hadleigh lpswich IP7 5DN T: 01206 369009; www.acceleratecleaning.com













