







COMPANY NAME: BEAVER FLOORCARE

CLIENT: APPLE

SITE: APPLE R334 ST DAVIDS CARDIFF
ACTIVITY: BACK OF HOUSE FLOOR TREATMENT

DATE OF RISK ASSESSMENT: 12th October 2017

AUTHOR: D.CAMPTON

| Key to Assessment | LOW Minor Impact Damage quickly repaired | MEDIUM Moderate Impact Partial Loss of Operations | HIGH Disaster Very Serious Consequences | | | | |
|---|--|---|--|--------|-----------------------------|-----------------|---|
| | | | | | | | |
| | | | | HAZARD | PERSONS/PROPERTY AT RISK | CONTROLLED RISK | SUMMARY OF PROTECTIVE & PREVENTIVE MEASURES |
| Slips , Trips and Falls | Beaver Personnel | LOW | Work scheduled outside of trading times. Future is a Staff Training in restauration (cleaning techniques). | | | | |
| during restoration & maintenance activities | Site Personnel | | Extensive Staff Training in restoration/ cleaning techniquesTraining in Site Housekeeping | | | | |
| (No heights or ladder | | | Need for working in manageable areas Avaidance of trailing applies ata | | | | |
| work undertaken) | | | Avoidance of trailing cables etc Use of Hazard Warning Signage at all times | | | | |
| | | | Areas cordoned off as required - barriers, barrier tape, signs | | | | |
| | | | Spill procedures established | | | | |
| | | | Safety footwear worn by technicians | | | | |
| Use of Cleaning | Beaver Personnel | LOW | Training provided in chemical use. | | | | |
| Chemicals | Site Personnel | | Use of non-hazardous chemicals whenever possible | | | | |
| | Building Fabric | | Special Training in use of sealing chemicals | | | | |
| - skin problems | | | Dispenser pumps , gloves used to prevent skin contact | | | | |
| - eye contamination | | | PPE to be used - masks, glasses, gloves ,protective clothing | | | | |
| - inhalation of chemical | | | Protective masking to areas wherever required | | | | |
| vapours | | | Eye Wash in First Aid Kits carried on Site. | | | | |
| | | | | | | | |









COMPANY NAME:

ACTIVITY:

BEAVER FLOORCARE
APPLE

CLIENT: A
SITE: A

APPLE R334 ST DAVIDS CARDIFF
BACK OF HOUSE FLOOR TREATMENT

DATE OF RISK ASSESSMENT: 12th October 2017 AUTHOR: D.CAMPTON

| Key to Assessment | LOW | MEDIUM | HIGH |
|-------------------|-------------------------|----------------------------|---------------------------|
| | Minor Impact | Moderate Impact | Disaster |
| | Damage quickly repaired | Partial Loss of Operations | Very Serious Consequences |

| HAZARD | PERSONS/PROPERTY AT RISK | CONTROLLED RISK | SUMMARY OF PROTECTIVE & PREVENTIVE MEASURES |
|---|--|-----------------|--|
| Musculoskeletal Disorders - Transporting cleaning equipment - Moving furniture at site - Using cleaning/reprocessing equpt - Working awkwardly e.g. on knees | Beaver Personnel | LOW | Training in Manual Handling to ensure correct lifting of cleaning equipment, furniture etc. Use of provided wheels to assist with furniture moving. Training in correct use of cleaning machinery -e.g height etc adjustment of rotary machines to ensure no torque Regular checks to machines including vibration etc Try to avoid awkward working, if not, ensure adequate rest periods. Knee pads provided. Safety shoes worn by staff to prevent foot damage. |
| Electrical Hazards - shocks Noise | Beaver Personnel Site Premises Beaver Personnel | LOW | Machinery used with RCD's to prevent electrocution, shocks & any interruption to supply Staff trained in the safe use of electrical equipment Regular PAT Testing & checks in accordance with Provision & Use of Equipment at Work Regs. 1998 Masking to supply points and data ports. Noise levels monitored - ear plugs provided |
| Damage to Site | Site Premises Fixtures & Fittings | LOW | All due care and protective measures taken to ensure no splashing or impact damage to fixtures & fittings Extra care and protective measures to be taken when working on all surfaces |

Restoration and Maintenance of Carpet, Marble, Vinyl, Rubber and Wood