

Koy to Accosement



LOW



MEDILIM



COMPANY NAME : BEAVER FLOORCARE

CLIENT: APPLE

SITE: APPLE R313 VICTORIA SQUARE BELFAST

ACTIVITY: STONE FLOOR MAINTENANCE & RE-FINISHING

DATE OF RISK ASSESSMENT: 14th November 2017

ПСП

**AUTHOR: D.CAMPTON** 

Key to Assessment	LOW Minor Impact Damage quickly repaired	MEDIUM  Moderate Impact  Partial Loss of Operations	HIGH  Disaster  Very Serious Consequences				
				HAZARD	PERSONS/PROPERTY	CONTROLLED RISK	SUMMARY OF PROTECTIVE & PREVENTIVE
AT RISK		MEASURES					
Oline Toine and Falls	Danisa Danasa d	1.011	Mank ask ask led autoide of trading times				
Slips , Trips and Falls	Beaver Personnel	LOW	Work scheduled outside of trading times.				
during restoration &	Site Personnel		Extensive Staff Training in restoration/ cleaning techniques				
maintenance activities			Training in Site Housekeeping				
( No heights or ladder			Need for working in manageable areas				
work undertaken )			Avoidance of trailing cables etc				
			Use of Hazard Warning Signage at all times				
			<ul> <li>Areas cordoned off as required - barriers, barrier tape, signs</li> </ul>				
			Spill procedures established				
			Safety footwear worn by technicians				
Use of Cleaning	Beaver Personnel	LOW	Training provided in chemical use.				
Chemicals	Site Personnel	2011	Use of non-hazardous chemicals whenever possible				
Offerficals	Building Fabric		Special Training in use of Ardex R65P				
- skin problems	Banding Fabric		Dispenser pumps , gloves used to prevent skin contact				
'			PPE to be used - masks, glasses, gloves ,protective clothing				
- eye contamination - inhalation of chemical							
			Protective masking to areas wherever required  Fig. Week in First Aid Kits payried on Sits.				
vapours			Eye Wash in First Aid Kits carried on Site.				

Restoration and Maintenance of Carpet, Marble, Vinyl, Rubber and Wood

Reg. Office The Barn, Oldberrow Manor, Ullenhall Lane, Ullenhall, Warwickshire B95 5PF Tel: 01564 742095 Fax: 01564 742853

Beaver Floorcare Ltd.: Registered in England No. 6695922 info@beaverfloorcare.co.uk www.beaverfloorcare.co.uk www.beaverfloorcare.co.uk



CLIENT:







COMPANY NAME: BEAVER FLOORCARE

APPLE

SITE: APPLE R313 VICTORIA SQUARE BELFAST

ACTIVITY: STONE FLOOR MAINTENANCE & RE-FINISHING

DATE OF RISK ASSESSMENT: 14th November 2017 AUTHOR: D.CAMPTON

Key to Assessment	LOW	MEDIUM	HIGH
	Minor Impact	Moderate Impact	Disaster
	Damage quickly repaired	Partial Loss of Operations	Very Serious Consequences

HAZARD	PERSONS/PROPERTY AT RISK	CONTROLLED RISK	SUMMARY OF PROTECTIVE & PREVENTIVE MEASURES
Musculoskeletal Disorders  - Transporting cleaning equipment - Moving furniture at site - Using cleaning/reprocessing equpt - Working awkwardly e.g. on knees	Beaver Personnel	LOW	<ul> <li>Training in Manual Handling to ensure correct lifting of cleaning equipment, furniture etc.</li> <li>Use of provided wheels to assist with furniture moving.</li> <li>Training in correct use of cleaning machinery -e.g height etc adjustment of rotary machines to ensure no torque</li> <li>Regular checks to machines including vibration etc</li> <li>Try to avoid awkward working, if not, ensure adequate rest periods. Knee pads provided.</li> <li>Safety shoes worn by staff to prevent foot damage.</li> </ul>
Electrical Hazards - shocks	Beaver Personnel Site Premises	LOW	<ul> <li>Machinery used with RCD's to prevent electrocution, shocks &amp; any interruption to supply</li> <li>Staff trained in the safe use of electrical equipment</li> <li>Regular PAT Testing &amp; checks in accordance with Provision &amp; Use of Equipment at Work Regs. 1998</li> <li>Masking to supply points and data ports.</li> </ul>
Noise	Beaver Personnel	LOW	Noise levels monitored - ear plugs provided
Damage to Site / Mall	Site Premises Fixtures & Fittings	LOW	<ul> <li>Filtration to sedimentation tanks to prevent suspended calcium deposits from blocking drains</li> <li>All due care and protective measures taken to ensure no splashing or impact damage to fixtures &amp; fittings</li> <li>Extra care and protective measures to be taken when working Mallside to ensure no splashing or damage to Mall floor</li> <li>Mallside area to be inspected &amp; signed off by Supervisor when works completed.</li> </ul>