NAME	BIKE NO	. TO BE FIXED	REG NUMBERS
JOSEPH	29	BIN, NEW RAP	NO REG
		RIGHT EXHAUST COVER DAMEGED	
		FRONT LEFT MUD FLOP COVER CRACKED LOWER	
STANLEY	34	FRONT VISOR SCRACHED	NO PLATES
		FRONT TENDERS CRACKED BOTH SIDES	
		RIGHT EXHAUST COVER CRACKED LOOSE	
		FRONT CLUSTER COVER - WHITE CRACKED	
BLESSING	27	LEFT BRAKE HANDLE CRACKED - BROKEN	NO PLATES
51133		LEFT MIRROR CRACKED - NO PLATES	NOTERIES
MOFOE	31	BIN NEEDS TO BE WRAPPED	NO PLATES
		COMPLETE VISOR MISSING	NOTERIES
		FRONT MUD FLAP CRACKED	
	 	MINOR SURGES ON STEPS	
	 	RIGHT ACCERALATOR -STUCK	
HESTINGS	26		NO DEC
HESTINGS	20	RIGHT MORROR ATTACHMENT BROKEN	NO REG
	-	NEW BIN WRAP	NO DEC
LUCAC	15	POOR WHEEL BEARING -FIXED BY LEE	NO REG
LUCAS	_	FRONT FENDER - MINOR SCRAPES	ND 327725
ROBERT	50	NO DISK	
		LEFT MIRROR CRACKED	
		RIGHT EXHAUST COVER SCRAPED	
		FRONT MUD FLAP NEDDS SPRAYING	
		RIGHT PUNELS DAMAGED + LEFT PANELS	
MUSHAMBE	44	NEW LEAD FOR BEAN NEEDED	ND 328057
,		NEW FRONT RIGHT MORROR NEEDED	
		RIGHT PANEL LOWER SMALL SCRACHED	
	ALI 7A	⊥ IN + SUZUKI BRAKERS NEED SPRAYING R	_ IGH
BENJAMIN	1	LEFT INDICATOR WATER	ND 329026
DENJAMM	70	LEFT FRONT BOTTOM PANEL SCRACHED	140 323020
		LEFT FRONT MIRROR CRACKED	
		LEFT FRONT WIRROR CRACKED	
EDWARD/RASHID	24 ZAIN	BIN NEW RAP NEEDED	NO REG
-		RIGHT PANEL SCRACHED	
		RIGHT EXHAUST SCRACHED	NO REG
MALUSI	30		NO REG
FELIX	32	WATER LEAKAGE BY BATTRIE	NO REG
		NEW BIN RAP	
BRIGHT	37	FRONT MED FLAP CRACKED	ND 199327
		FRONT RIGHT PANEL - ACCIDENT	
PAUL	22	NEW BIN RAP	NO REG
		S MALUSI AND BRIGHT	
	1X MEDIL		
	IXLARGE	BRIGHT	14/09/2020
			1

Mushambe 14/09/26262 Bik (44) - NO 328057 - New lid For ben needed - New Front Right Minu needed - Right land lower Small scienteles All ZAIN + SUZUKI BRACKETS novel Spraying Bernamin - left indicator Water

Bike 40 - left front bottom Panel Scratcher

NO. 329026 - left front Mirror Cracland. Et Weiro Kashid - Bin New Wing Meddes
Bike 74 zin - Right Rapels Scratchan
- No Reg. - Right Exhaust Scratchan Molusi - No leg -Bile (FO) they - felix Rice Br)
No reey - Worker leakage by buttery
- New har Wrop' Bright 37) - front Mud flap (ranker) - Front Cynt Panel - Accident ND 19 9327 PAUL (22) NOW BON WIND - No pg.

	Joseph Bin - new Way	
	No Ré6- La Right exhaust cover damagen-	
1	No REG- Lo Right exhaust over damaged- BKE (29) C Front Hat left mud Flip Cover cracked-lower	We have again,
-	Stroky Calchal	in the designation
1	Stanley - Front Visor Scratched. Bike 3 (34) Front Fender's Scraped - Both Sides - Right enhant Caer Cracked - lose - Front Chaster Guer - White cracked	·
	- Right exhaust Carl Carlon - hope	
	- Front Chyster Cover - White cracked	-
	- 110 Mallo	
-	Plossing 1	
-	Pike (27) - Right left boke hande cracked - broken left mirror cracked - No Nates	
	10 + miror cracked 1/0 fates	
	Motoe - Bin new to be wormened No Pite	er manager desirations
	Motoe — Bin news to be wropped. — No Plates This (3) — Conflete Visor missing, — Front Mud Flup Stacked. — Minor Surges on Steps	
	- Front Mad Flap Stacky.	2231 1
**************************************	- Minor Surgeo on Steps	
***	-Righ accelerator - stuck.	Part was
	Hestings - Regly + Micros Alchaet bles	
l l	Bile (26) - New Bin Wrop affectment barkers - No reg - Roy When Baring **	
Tangen, viscondinospera e eq	- No rey - Ror When Baring &	**************************************
		administratory database pp
	Bille (13) - left Minor Scrapes	
	Ry-N032725	and the same to the same to
	Robert - No disc	
	NO 32 8061 - left Mirror Cracker	The second secon
	Bule (50) - Right exhaust (our sope Scraped	
	- Trank think the	** ** =