Sentinel Safety

See Risk. Prevent Harm.

Overview

Inspection identified a loose railing condition.

Risk Evaluation

Fall hazard from elevated surface presents a high-risk condition requiring corrective action (Score: 5).

Top Risk Priorities

1. Fall hazard from elevated surface — HIGH (Score: 5)

Immediate Actions Required

IMMEDIATE ACTION REQUIRED: Remove personnel from exposure and secure the hazard area until corrective measures are completed.

Priority Actions

1. Eliminate hazard at source (engineering control).
2. Install temporary fall protection or barriers.
3. Restrict access to affected area.
4. Inspect surrounding structures for similar conditions.

Standards

Applicable regulatory standards include: MSHA 56.11001.

Corrective Actions

Repair or replace damaged railing immediately. Install compliant guardrails meeting MSHA requirements. Restrict access to the affected area until repairs are completed. Conduct inspection of all elevated surfaces for similar hazards.

Compliance Note

Potential regulatory exposure exists under applicable standards: MSHA 56.11001.