

INSITE

Inspection Report

Field Safety Inspection Record

KG-4E Verification Site

KG-4E LOTO-01

Inspection date: August 21, 2026

Inspector: KG4E Verification Inspector

Findings documented: 1

Report generated: August 21, 2026

Executive Summary

1

FINDINGS

1

CRITICAL / HIGH

1

OPEN ACTIONS

Completed

STATUS

RISK DISTRIBUTION

Critical		0
High		1
Moderate		0
Low		0

INSPECTION RECORD

SITE / FACILITY

KG-4E Verification Site

INSPECTION

KG-4E LOTO-01

INSPECTION DATE

August 21, 2026

INSPECTOR

KG4E Verification Inspector

REGULATORY CONTEXT

OSHA - General Industry (29 CFR 1910)

ASSESSMENT

This inspection documented 1 finding: 1 High. 1 finding rated Critical or High requires prioritized corrective action and should be assigned an owner and a closure date without delay. 1 corrective action was logged for this inspection, of which 1 remains open.

BASIS AND LIMITATIONS

Regulatory context: OSHA - General Industry (29 CFR 1910) — set for this inspection. HazLenz AI output is advisory and requires qualified human review; this report reflects findings as reviewed at the time of generation.

Findings Summary

Concise reference of every finding documented in this inspection.

#	HAZARD	RISK	STATUS	ACTION STATUS
1	Lockout Tagout	High	Finalized	Open

Detailed Findings

Finding 1 — Lockout Tagout

WHAT WAS OBSERVED

a maintenance technician is servicing the conveyor while it is still energized and no lock is applied.

Risk:

High

Severity 4 · Likelihood 3 · Risk score 12

APPLICABLE STANDARD

29 CFR 1910.147 — Control of hazardous energy

HazLenz standard summary: Standard matched using hazard classification, operational context, exposure pathways, and contextual risk indicators. (Supported by high-authority consensus standard: ANSI/ASSP (American Society of Safety Professionals) - ANSI/ASSP Z244.1)

QUALIFIED-PERSON REVIEW

Accepted — KG-4E verification: the qualified reviewer accepted the HazLenz assessment without edit.

RECOMMENDED CORRECTIVE ACTION

Control Lockout Tagout Exposure

Immediate: Immediate hazard control required to prevent contact/exposure to Lockout Tagout hazard.

Permanent: Address systemic factors to prevent recurrence.

Verification: Confirm the hazard control effectively removes the exposure.

Status: Open · Priority: Urgent

Assigned To:

NOTES

Corrective Action Summary

Consolidated view of all corrective actions from this inspection for management follow-up.

FINDING	ACTION	OWNER	DUE	STATUS
#1	Control Lockout Tagout Exposure	Unassigned	—	Open