

INSITE

Inspection Report

Field Safety Inspection Record

KG-4E Verification Site

KG-4E MSHA-01

Inspection date: August 21, 2026

Inspector: KG4E Verification Inspector

Findings documented: 1

Report generated: August 21, 2026

Executive Summary

1

FINDINGS

1

CRITICAL / HIGH

1

OPEN ACTIONS

Completed

STATUS

RISK DISTRIBUTION

Critical		0
High		1
Moderate		0
Low		0

INSPECTION RECORD

SITE / FACILITY

KG-4E Verification Site

INSPECTION

KG-4E MSHA-01

INSPECTION DATE

August 21, 2026

INSPECTOR

KG4E Verification Inspector

REGULATORY CONTEXT

MSHA (30 CFR)

ASSESSMENT

This inspection documented 1 finding: 1 High. 1 finding rated Critical or High requires prioritized corrective action and should be assigned an owner and a closure date without delay. 1 corrective action was logged for this inspection, of which 1 remains open.

BASIS AND LIMITATIONS

Regulatory context: MSHA (30 CFR) — set for this inspection. HazLenz AI output is advisory and requires qualified human review; this report reflects findings as reviewed at the time of generation.

Findings Summary

Concise reference of every finding documented in this inspection.

#	HAZARD	RISK	STATUS	ACTION STATUS
1	SHADOW GOVERNED LEAK	High	Finalized	Open

Detailed Findings

Finding 1 — SHADOW GOVERNED LEAK

WHAT WAS OBSERVED

a haul truck at the surface mine is backing without a functional backup alarm

Risk:

High

Severity 4 · Likelihood 3 · Risk score 12

APPLICABLE STANDARD

30 CFR 56.9100

HazLenz standard summary: Standard matched using hazard classification, operational context, exposure pathways, and contextual risk indicators.

QUALIFIED-PERSON REVIEW

Accepted — SHADOW mode active — governedDeliveryState GOVERNED_VERIFIED_TEXT, governedFallbackReason GOVERNANCE_FILTER_EMPTY, release federal-core-2026-07-30.1, mismatch GRANULARITY_DIFFERENCE (BLOCKING), correlationId 74b77cdb, telemetry allowlist cutover.

RECOMMENDED CORRECTIVE ACTION

Return the reverse-activated alarm to service

Immediate: park the unit and restrict reversing movements.

Permanent: repair or replace the reverse-activated signal alarm.

Verification: pre-operational check recorded for three consecutive shifts.

Due: 09/09/2026 · Status: Open · Priority: High

Assigned To: KG4E Verification Inspector

NOTES

Corrective Action Summary

Consolidated view of all corrective actions from this inspection for management follow-up.

FINDING	ACTION	OWNER	DUE	STATUS
#1	Return the reverse-activated alarm to service	KG4E Verification Inspector	09/09/2026	Open