

INSITE

Inspection Report

Field Safety Inspection Record

KG-4E Verification Site

KG-4E MULTI-01

Inspection date: August 21, 2026

Inspector: KG4E Verification Inspector

Findings documented: 2

Report generated: August 21, 2026

Executive Summary

2

FINDINGS

0

CRITICAL / HIGH

2

OPEN ACTIONS

Completed

STATUS

RISK DISTRIBUTION

Critical		0
High		0
Moderate		2
Low		0

INSPECTION RECORD

SITE / FACILITY

KG-4E Verification Site

INSPECTION

KG-4E MULTI-01

INSPECTION DATE

August 21, 2026

INSPECTOR

KG4E Verification Inspector

REGULATORY CONTEXT

OSHA - General Industry (29 CFR 1910)

ASSESSMENT

This inspection documented 2 findings: 2 Moderate. No Critical or High findings were identified. The moderate-risk findings below should be tracked through corrective action and verified on closure. 2 corrective actions were logged for this inspection, of which 2 remain open.

BASIS AND LIMITATIONS

Regulatory context: OSHA - General Industry (29 CFR 1910) — set for this inspection. HazLenz AI output is advisory and requires qualified human review; this report reflects findings as reviewed at the time of generation.

Findings Summary

Concise reference of every finding documented in this inspection.

#	HAZARD	RISK	STATUS	ACTION STATUS
1	SHADOW GOVERNED LEAK	Moderate	Finalized	Open
2	SHADOW GOVERNED LEAK	Moderate	Finalized	Open

Detailed Findings

Finding 1 — SHADOW GOVERNED LEAK

WHAT WAS OBSERVED

the unguarded pulley sits beside an open floor hole

FULL SOURCE OBSERVATION (SHARED ACROSS THIS INSPECTION'S FINDINGS)

The unguarded pulley sits beside an open floor hole, and the nearby drum of solvent is unlabeled.

Risk:

Moderate

Severity 2 · Likelihood 4 · Risk score 8

APPLICABLE STANDARD

29 CFR 1910.212(a)(1) — Machine guarding - types of guarding methods

HazLenz standard summary: Candidate only, qualified review required: One or more methods of machine guarding must be provided to protect the operator and other employees in the machine area from hazards such as those created by point of operation, ingoing nip points, rotating parts, and flying chips and sparks; the rule gives barrier guards, two-hand tripping devices and electronic safety devices as examples of guarding methods (29 CFR 1910.212(a)(1)). Guards must be affixed to the machine where possible and secured elsewhere if attachment to the machine is not possible, and the guard must not itself offer an accident hazard (1910.212(a)(2)). Point-of-operation guarding requirements are addressed separately at 1910.212(a)(3). HazLenz basis: Candidate only; missing: moving or accessible energy.

QUALIFIED-PERSON REVIEW

Accepted — SHADOW mode active — governedDeliveryState GOVERNED_VERIFIED_TEXT,
governedFallbackReason GOVERNANCE_FILTER_EMPTY, release federal-core-2026-07-30.1, mismatch
GRANULARITY_DIFFERENCE (BLOCKING), correlationId 74b77cdb, telemetry allowlist cutover.

RECOMMENDED CORRECTIVE ACTION

Correct the co-located hazards in the pump room

Immediate: barricade the floor opening and de-energize the drive.

Permanent: fit a fixed guard to the pulley, install a compliant floor-hole cover, and label the solvent drum.

Verification: re-inspect all three conditions after correction.

Due: 08/31/2026 · Status: Open · Priority: Urgent

Assigned To: KG4E Verification Inspector

NOTES

Finding 2 — SHADOW GOVERNED LEAK

WHAT WAS OBSERVED

the nearby drum of solvent is unlabeled

FULL SOURCE OBSERVATION (SHARED ACROSS THIS INSPECTION'S FINDINGS)

The unguarded pulley sits beside an open floor hole, and the nearby drum of solvent is unlabeled.

Finding 2 — SHADOW GOVERNED LEAK (continued)

Risk:

Moderate

Severity 2 · Likelihood 3 · Risk score 6

APPLICABLE STANDARD

29 CFR 1910.1200 — Hazard communication

HazLenz standard summary: Employers must ensure that each container of hazardous chemicals in the workplace is labeled, tagged or marked with either the full shipped-container information required by 29 CFR 1910.1200(f)(1)(i)-(v), or with the product identifier plus words, pictures or symbols giving at least general information about the chemical's hazards which, together with the other information available under the employer's hazard communication program, conveys the specific physical and health hazards (1910.1200(f)(6)). This workplace-labeling duty is distinct from 1910.1200(f)(1), which places the duty to label containers leaving the workplace on the chemical manufacturer, importer or distributor. Employers may use signs, placards, process sheets, batch tickets, operating procedures or other written materials in lieu of affixing labels to individual stationary process containers, provided the alternative identifies the containers and conveys the required information (1910.1200(f)(7)), and portable containers into which chemicals are transferred for the immediate use of the employee performing the transfer need not be labeled (1910.1200(f)(8)). HazLenz basis: Supported by submitted evidence for OSHA hazard communication labeling; qualified review remains required.

QUALIFIED-PERSON REVIEW

Accepted — SHADOW mode active — governedDeliveryState GOVERNED_VERIFIED_TEXT,
governedFallbackReason GOVERNANCE_FILTER_EMPTY, release federal-core-2026-07-30.1, mismatch
GRANULARITY_DIFFERENCE (BLOCKING), correlationId 74b77cdb, telemetry allowlist cutover.

RECOMMENDED CORRECTIVE ACTION

Control Hazard Communication Exposure

Immediate: Immediate hazard control required to prevent contact/exposure to Hazard Communication hazard.

Permanent: Address systemic factors to prevent recurrence.

Verification: Confirm the hazard control effectively removes the exposure.

Status: Open · Priority: High

Assigned To: _____

NOTES

Corrective Action Summary

Consolidated view of all corrective actions from this inspection for management follow-up.

FINDING	ACTION	OWNER	DUE	STATUS
#2	Control Hazard Communication Exposure	Unassigned	—	Open
#1	Correct the co-located hazards in the pump room	KG4E Verification Inspector	08/31/2026	Open