

SAFETY INSITE

Inspection Report

Field Safety Inspection Record

VALIDATION-276-REPORT-1789331913811 Simple Site

Full Inspection

Inspection date: September 13, 2026

Inspector: Validation 276 a

Findings documented: 1

Report generated: September 13, 2026

Executive Summary

1

FINDINGS

0

CRITICAL / HIGH

1

OPEN ACTIONS

Completed

STATUS

RISK DISTRIBUTION

Critical		0
High		0
Moderate		1
Low		0

INSPECTION RECORD

SITE / FACILITY

VALIDATION-276-REPORT-1789331913811 Simpl...

INSPECTION

Full Inspection

INSPECTION DATE

September 13, 2026

INSPECTOR

Validation 276 a

REGULATORY CONTEXT

OSHA - General Industry (29 CFR 1910)

ASSESSMENT

This inspection documented 1 finding: 1 Moderate. No Critical or High findings were identified. The moderate-risk findings below should be tracked through corrective action and verified on closure. 1 corrective action was logged for this inspection, of which 1 remains open.

BASIS AND LIMITATIONS

Regulatory context: OSHA - General Industry (29 CFR 1910) — set for this inspection. HazLenz AI output is advisory and requires qualified human review; this report reflects findings as reviewed at the time of generation.

Findings Summary

Concise reference of every finding documented in this inspection.

#	HAZARD	RISK	STATUS	ACTION STATUS
1	Electrical	Moderate	Finalized	Open

Detailed Findings

Finding 1 — Electrical

WHAT WAS OBSERVED

the cover plate is missing from a 480-volt disconnect panel in the compressor room

Risk:

Moderate

Severity Serious · Likelihood Possible · Reviewer-confirmed · HazLenz analysis: Critical

APPLICABLE STANDARD

29 CFR 1910.303(g)(2)(i)

HazLenz standard summary: Standard matched using hazard classification, operational context, exposure pathways, and contextual risk indicators. (Supported by high-authority consensus standard: NFPA (National Fire Protection Association) - NFPA 70E Standard for Electrical Safety)

QUALIFIED-PERSON REVIEW

Edited — Reviewer-confirmed on the Standard 5x5 matrix: severity 3 x likelihood 3 = 9.

RECOMMENDED CORRECTIVE ACTION

Verify and correct reviewed condition

Immediate: Control Electrical Exposure: Immediate hazard control required to prevent contact/exposure to Electrical hazard.

Permanent:

Verification:

Due: 09/20/2026 · Status: Open · Priority: High

Assigned To: _____

NOTES

Corrective Action Summary

Consolidated view of all corrective actions from this inspection for management follow-up.

FINDING	ACTION	OWNER	DUE	STATUS
#1	Control Electrical Exposure: Immediate hazard control required to prevent contact/exposure to Electrical hazard.	Unassigned	09/20/2026	Open