

# Safety InSite Inspection Report

Inspection: Full Inspection

Inspection ID: 623fb075-9607-4f37-a38d-fbe67e60526a

Version: 3

Completed: 2026-08-03T16:14:49.758Z

## Observations and Findings

Observation: An unguarded rotating shaft is accessible beside the operator walkway while the machine is running.

Finding: Machine Guarding

Status: finalized

Human review: edited — Reviewer confirmed material exposure after observing accessible rotating energy.

## Corrective Actions

Verify and correct reviewed condition (open)

Immediate: Pause affected work and restrict access around the exposed rotating\_shaft until guarding and mechanical\_rotation exposure controls are reviewed.

Permanent: Install permanent, secure guarding over the exposed rotating\_shaft to completely eliminate the rotating equipment entanglement hazard.

Verification: Perform a formal inspection and functional verification by a competent person before removing interim controls or resuming normal operations.

HazLenz output is advisory and requires qualified human review.