

INSITE

Inspection Report

Field Safety Inspection Record

Closure Report A 1786925553191

Closure Report A 1786925553191

Inspection date: August 16, 2026

Inspector: matrix-closure

Findings documented: 1

Report generated: August 16, 2026

Executive Summary

METRIC	VALUE
Total findings	1
Critical / High risk findings	0
Open corrective actions	1
Inspection status	Completed

Risk Distribution

Critical	0
High	0
Moderate	0
Low	0

1 finding(s) do not yet have an established risk rating.

Summary

Findings from this inspection are currently rated low risk based on available evidence and should still be tracked through closure.

Inspection Information

FIELD	DETAIL
Site / facility	Closure Report A 1786925553191
Inspection	Closure Report A 1786925553191
Inspection date	August 16, 2026
Inspector	matrix-closure
Status	Completed

Findings Summary

Concise reference of every finding documented in this inspection.

#	HAZARD	RISK	STATUS	ACTION STATUS
1	Machine Guarding	Not rated	Finalized	Open

Detailed Findings

Finding 1 — Machine Guarding

WHAT WAS OBSERVED

An employee reached through an unguarded rotating pulley on a running conveyor drive while the machine remained energized.

FINDING

Install a fixed guard over the rotating pulley before the conveyor returns to service.

QUALIFIED-PERSON REVIEW

Accepted — Confirmed during direct inspection: An employee reached through an unguarded rotating pulley on a running conveyor d

RECOMMENDED CORRECTIVE ACTION

Install conveyor pulley guard

Install a fixed guard over the rotating pulley before the conveyor returns to service.

Due: 08/31/2026 · Status: Open · Priority: High

Corrective Action Summary

Consolidated view of all corrective actions from this inspection for management follow-up.

FINDING	ACTION	OWNER	DUE	STATUS
#1	Install conveyor pulley guard	Unassigned	08/31/2026	Open

HazLenz AI output is advisory and requires qualified human review. This report reflects findings as reviewed at the time of generation.