

INSITE

Inspection Report

Field Safety Inspection Record

Real-Shape Risk Check 1786926146526

Real-Shape Risk Check 1786926146526

Inspection date: August 16, 2026

Inspector: matrix-closure

Findings documented: 1

Report generated: August 16, 2026

Executive Summary

METRIC	VALUE
Total findings	1
Critical / High risk findings	1
Open corrective actions	1
Inspection status	Completed

Risk Distribution

Critical	0
High	1
Moderate	0
Low	0

Summary

This inspection identified findings requiring prioritized corrective action. Critical and High findings should be assigned an owner and closure date without delay.

Inspection Information

FIELD	DETAIL
Site / facility	Real-Shape Risk Check 1786926146526
Inspection	Real-Shape Risk Check 1786926146526
Inspection date	August 16, 2026
Inspector	matrix-closure
Status	Completed

Findings Summary

Concise reference of every finding documented in this inspection.

#	HAZARD	RISK	STATUS	ACTION STATUS
1	Electrical	High	Finalized	Open

Detailed Findings

Finding 1 — Electrical

WHAT WAS OBSERVED

Exposed energized bus bars in an open electrical panel accessible to workers.

FINDING

De-energize and cover the panel immediately.

RISK

HIGH

QUALIFIED-PERSON REVIEW

Accepted — Confirmed exposed energized bus bars during direct inspection.

RECOMMENDED CORRECTIVE ACTION

De-energize and cover panel

De-energize and cover the panel immediately.

Due: 08/19/2026 · Status: Open · Priority: High

Corrective Action Summary

Consolidated view of all corrective actions from this inspection for management follow-up.

FINDING	ACTION	OWNER	DUE	STATUS
#1	De-energize and cover panel	Unassigned	08/19/2026	Open

HazLenz AI output is advisory and requires qualified human review. This report reflects findings as reviewed at the time of generation.