

INSITE

Inspection Report

Field Safety Inspection Record

Riverside Distribution Center (mswc92jx)

ReportA — Riverside Distribution Center

Inspection date: August 16, 2026

Inspector: Report P2 Tester

Findings documented: 1

Report generated: August 16, 2026

Executive Summary

METRIC	VALUE
Total findings	1
Critical / High risk findings	1
Open corrective actions	1
Inspection status	Completed

Risk Distribution

Critical	0
High	1
Moderate	0
Low	0

Summary

This inspection identified findings requiring prioritized corrective action. Critical and High findings should be assigned an owner and closure date without delay.

Inspection Information

FIELD	DETAIL
Site / facility	Riverside Distribution Center (mswc92jx)
Inspection	ReportA — Riverside Distribution Center
Inspection date	August 16, 2026
Inspector	Report P2 Tester
Status	Completed

Findings Summary

Concise reference of every finding documented in this inspection.

#	HAZARD	RISK	STATUS	ACTION STATUS
1	Machine Guarding	High	Finalized	Open

Detailed Findings

Finding 1 — Machine Guarding

WHAT WAS OBSERVED

Worker observed operating a bench grinder with the wheel guard removed, exposing the abrasive wheel at the point of operation.

FINDING

Bench grinder point-of-operation guard was removed and not reinstalled, exposing the operator to direct contact with the rotating abrasive wheel.

RISK

HIGH

Severity 4 · Likelihood 3 · Score 12

APPLICABLE STANDARD

29 CFR 1910.212(a)(3)(ii)

HazLenz standard summary: Standard matched using hazard classification, operational context, exposure pathways, and contextual risk indicators. (Supported by high-authority consensus standard: ANSI (American National Standards Institute) - ANSI B11.19)

QUALIFIED-PERSON REVIEW

Accepted — Reviewed and confirmed by qualified inspector.

RECOMMENDED CORRECTIVE ACTION

Reinstall point-of-operation guard on bench grinder

Reinstall and verify the wheel guard on the bench grinder before further use; inspect guard fasteners for damage.

Owner: Maintenance Lead · Due: 08/22/2026 · Status: Open · Priority: High

Corrective Action Summary

Consolidated view of all corrective actions from this inspection for management follow-up.

FINDING	ACTION	OWNER	DUE	STATUS
#1	Reinstall point-of-operation guard on bench grinder	Maintenance Lead	08/22/2026	Open

HazLenz AI output is advisory and requires qualified human review. This report reflects findings as reviewed at the time of generation.