
Installation of Hyperlite LCD-VNS (non swivel) Mount

Plan View showing how the bracket slides into the extrusion




Remove hanger hooks from cross bar and slide the assembly into the extrusion from top or bottom, tighten into place using wingnuts

Mount the screen on the hanger assembly using the hooks and tighten the thumb screws to secure it in place



Apply hanger hooks to rear of screen using top 2 holes only



IOLKS

DESIGN:

DATE:

REFERENCE:

© Trussworks 2010