



SUBJECT: Index for Container Service Bulletins

BULLETIN NO: Index

DATE: January 22, 2003

Bulletin No.	Subject
C-001	Procedure for Converting Thermo King CF-II Container Units from R-12 to R-401B (MP66)
C-002	Compressors Oils
C-003	New Pocket Reference Cards
C-004	Unit Sight Glass Balls Sticking on HFC Units, Thermo King P/N 66-7420
C-005	Refrigeration System Cleanup When Compressor Oil is Contaminated (Dark or Discolored)
C-006	Copeland Bypass Oil Filter (Thermo King P/N 66-7462) — Change Requirements
C-007	Thermo King Expansion Valve (TXV) Setting: After Unit Conversion from R-12 to R-134a; All Units Factory Equipped with R-134a; All Units Including Standard R-12 Units
C-008	Thermo King Refrigeration System Cleanup Procedure
C-009	Leak Checking Compressor Shaft Seal on Thermo King X426 and X430 Compressors
C-010	µP-A+ Controller Configuration Setting and Minimum Software Version Requirement
C-011	CF-II Sight Glass Moisture Indicators with R-134a and R-404A
C-012	Operating Instructions for Communications Tester/Amplifier (P/N 204-901) with Power Cable/Battery Connector (P/N204-937)
C-013	Operating Instructions for Communications Tester/Amplifier (P/N 204-901) with Power Cable/Battery Connector (P/N204-938)
C-014	µP-G Controller Unit Operating Information for CG-II Generator Sets
C-015	CF-II Heaters
C-016	CF-II Condenser Coil Cleaning
C-017	Measuring Compressor Crankshaft End Play on Thermo King X426 and X4340 Compressors Used in CF-II and CF-III Container Refrigeration Units
C-018	Supply (Discharge) Air Sensor Position in Sensor Tube on CSR-40, CRR-40, TNE 508 and TNE 508 SC1 Units
C-019	PVC Breather Vent on se 2.2 Engines
C-020	Revised Operating Instructions for Communications Tester/Amplifier (P/N 204-901)
C-021	CSR and CRR Leak Charts
C-022	Operating Instructions for µP-D Tester, P/N 204-911
C-023	Use Separate, Dedicated Service Tools for HCFC/CFC Refrigerants and HFC Refrigerants
C-024	µP-D Controller Emergency Bypass Procedure
C-025	Normal Operating System Pressures for CSR Units
C-026	Auto-Restart Operation on Smart Generator Sets
C-027	Sealed Expansion Valve on Sea-Land CSR Units
C-028	New Dehydrator, P/N 66-9015, for All CF-II Series Units
C-029	CSR Versus CRR Service Guide and Refrigeration System Service Procedures
C-030	Injection Pump Timing Bolt Change to Provide Positive Fuel Shutoff on CG and SG (Smart) Generator Sets
C-031	Thermo King 11.71 (or above) Software Release
C-032	Check Mounting Bolt Torque of Suction Flange Connections on CRR Units with “29K” in the Serial Number (xxx29Kxxx)
C-033	Procedures for Belt Tension Adjustment on Thermo King Gensets

MGR
☐

SALES
☐

SERVICE
☐

PARTS
☐

USE ONLY **THERMO KING** FACTORY APPROVED REPLACEMENT PARTS

314 West 90th Street, Minneapolis, Minnesota 55420

Bulletin No.	Subject
C-034	Use the Thermo King EXTRANET Site on the World Wide Web to View and Download Files for Container Products
C-035	PC-PAC V3.3 Upgrade Now Available from the Public File Download Center at the Thermo King EXTRANET Site
C-036	Thermo King Container Service Cold Line: 1-800-227-2506
C-037	µP-D Controller Replacement
C-038	Unit and Customer Configuration Settings for µP-D Controller
C-039	Unit Health Check for CSR Hermetic Refrigeration Systems
C-040	Real Time Clock Batteries on µP-A, µP-A+ and µP-D Controllers Not in Service
C-041	Manual Emergency Mode Operation or Replacement of MP-3000 Controllers
C-042	Replacement Procedure for New Style Power Cord for Scroll Compressor
C-043	Setting µP-G Version 020 Software for Use on Gensets Equipped with Isuzu or Yanmar Engines
C-044	Extended Maintenance Interval (EMI 3000) Package for Gensets Equipped with Yanmar Engines
C-045	Replacing the Keyboard Decal on MP-3000, MPC2000ID and MPC2000 Controllers
C-046	MP3000 Software Changes
C-047	CRRPS and CSRPS Unit Field Refrigerant Charges
C-048	MP3000 Controller Replacements
C-049	RMM Slave Modems Failures
C-050	Unit Sensor Replacements
C-051	MP3000 Main Relay Board Replacements
C-052	New 3DS Copeland Compressor
C-053	Humidity Sensors
C-054	Replacement MP-3000 Display Assembly
C-055	MP-3000 / MPC2000ID Test Kit
C-056	Flashing MP-3000 Software in AFAM+ Units
C-057	Using MP-3000 / MPC2000ID Test Kit
C-058	CRR, CSR and MAGNUM TXV Replacements
C-059	Scroll Compressor Replacements