



SERVICE BULLETIN



SUBJECT: Replacement MP-3000 Display Assembly

BULLETIN NO: C 054-1

DATE: October 8, 2002

The following information relates to the availability of a replacement display assembly for the MP-3000 series controllers. If the LED or LCD display fails, it is recommended to replace the display assembly instead of the entire controller. This will be a requirement for controller repairs under Warranty. It is recommended for all field repairs where the display is at fault.

NOTE: Display assembly works in the MP-3000 controllers ONLY.

A Warranty Repair Code (Job Code) has been established for this type of claim:

Job Code 5263



Part Number for the Display Assembly: 41-4919

MGR
☐

SALES
☐

SERVICE
☐

PARTS
☐