

LEFT ARM

Diagram illustrating the assembly of the **LEFT ARM**. The main assembly shows parts **D11**, **D14**, **D13**, and **D12** connected by a line. A callout shows the assembly of **D16** and **PC1**. Another callout shows the assembly of **I8** and **D125**, which is then connected to **I9**.

