REFINITIV Annotations:

Toyota Motor Engineering & Manufacturing Recalls 2010-2016 4Runner, 2003-2006 Tundra, 2003-2013 Corolla, 2009-2010 Corolla Matrix. NHTSA Campaign Number: 19V741000 Manufacturer Toyota Motor Engineering & Manufacturing Components AIR BAGS Potential Number of Units Affected 928,203 Summary Toyota Motor Engineering & Manufacturing (Toyota) is recalling certain 2010-2016 4Runner, 2003-2006 Tundra, 2003-2013 Corolla, 2009-2010 Corolla Matrix, 2004-2005 RAV4, 2002-2007 Seguoia, 2011-2013 Sienna, 2008-2012 Scion xB, 2008-2009 Lexus IS-F, 2007-2012 Yaris and Lexus ES350, 2010-2017 Lexus GX460, 2002-2010 Lexus SC430, 2006-2012 Lexus IS250 and IS350 and 2010-2015 Lexus IS250C and IS350C vehicles. These vehicles had their driver or passenger frontal air bag inflators previously replaced under a prior recall using inflators of the same design. The inflators may explode due to propellant degradation occurring after long-term exposure to high absolute humidity, temperature and temperature cycling. Remedy Toyota will notify owners. Depending on the vehicle model, dealers will replace the driver or front passenger air bag inflator or the air bag assembly using an alternate inflator, free of charge. The recall is expected to begin November 15, 2019. Owners may contact Toyota customer service at 1-888-270-9371 or Lexus customer service at 1-800-255-3987. Toyota's numbers for this recall are JOA, JOB, and JOC. Lexus' numbers for this recall are JLI, JLJ, and JLK. Notes Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov. Source: NHTSA.

QWAM Annotations:

Toyota Motor Engineering & Manufacturing Recalls 2010-2016 4Runner, 2003-2006 Tundra, 2003-2013 Corolla, 2009-2010 Corolla Matrix. NHTSA Campaign Number: 19V741000 Manufacturer Toyota Motor Engineering & Manufacturing Components AIR BAGS Potential Number of Units Affected 928,203 Summary Toyota Motor Engineering & Manufacturing (Toyota) is recalling certain 2010-2016 4Runner, 2003-2006 Tundra, 2003-2013 Corolla, 2009-2010 Corolla Matrix, 2004-2005 RAV4, 2002-2007 Sequoia, 2011-2013 Sienna, 2008-2012 Scion xB, 2008-2009 Lexus IS-F, 2007-2012 Yaris and Lexus ES350, 2010-2017 Lexus GX460, 2002-2010 Lexus SC430, 2006-2012 Lexus IS250 and IS350 and 2010-2015 Lexus IS250C and IS350C vehicles. These vehicles had their driver or passenger frontal air bag inflators previously replaced under a prior recall using inflators of the same design. The inflators may explode due to propellant degradation occurring after long-term exposure to high absolute humidity, temperature and temperature cycling. Remedy Toyota will notify owners. Depending on the vehicle model, dealers will replace the driver or front passenger air bag inflator or the air bag assembly using an alternate inflator, free of charge. The recall is expected to begin November 15, 2019. Owners may contact Toyota customer service at 1-888-270-9371 or Lexus customer service at 1-800-255-3987. Toyota's numbers for this recall are JOA, JOB, and JOC. Lexus' numbers for this recall are JLI, JLJ, and JLK. Notes Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov. Source: NHTSA.