

QP No. QP-QA_-007	Issue Date 15-09-2026	Revision No. R02	Date 15-09-2026	Name SPECguard TEST
Quality Assurance and Quality Control Procedure				
COSO				

DOCUMENT CONTROL AND PURPOSE

This procedure defines the requirements for controlled inspection, verification, recording, and reporting of the applicable engineering activity.

TABLE OF CONTENTS

1. Purpose	1
2. Scope	2
3. Quality Requirements	3
4. Inspection Procedure	4
5. Nonconformance Control	5
6. Acceptance Criteria	6
7. Records and Reporting	7

Document status: Controlled test document for SpecGuard inspection benchmarking.

QP No. QP-QA_-007	Issue Date 15-09-2026	Revision No. R02	Date 15-09-2026	Name SPECguard TEST
Quality Assurance and Quality Control Procedure				
COSO				

1. Purpose

All inspection activities shall be performed using approved instruments and documented against the current revision of the applicable procedure.

Inspection personnel shall verify identification, condition, measurements, documentation, and acceptance criteria before releasing the item.

Any deviation from the specified requirement shall be recorded as a finding and reviewed according to the applicable quality process.

QP No. QP-QA_-007	Issue Date 15-09-2026	Revision No. R02	Date 15-09-2026	Name SPECguard TEST
Quality Assurance and Quality Control Procedure				
				COSO

2. Scope

All inspection activities shall be performed using approved instruments and documented against the current revision of the applicable procedure.

Inspection personnel shall verify identification, condition, measurements, documentation, and acceptance criteria before releasing the item.

Any deviation from the specified requirement shall be recorded as a finding and reviewed according to the applicable quality process.

Inspection Acceptance Table

Parameter	Requirement	Result
Pressure	10 bar	PASS
Temperature	80 C	PASS
Visual condition	No visible damage	PASS
Documentation	Current revision	PASS

QP No. QP-QA_-007	Issue Date 15-09-2026	Revision No. R02	Date 15-09-2026	Name SPECguard TEST	COSO
Quality Assurance and Quality Control Procedure					

3. Quality Requirements

3.1 The inspection sequence shall follow the approved work instruction.

Inspection personnel shall verify identification, condition, measurements, documentation, and acceptance criteria before releasing the item.

Any deviation from the specified requirement shall be recorded as a finding and reviewed according to the applicable quality process.

Referenced Figures

- Figure 1 — Inspection Flow
- Figure 2 — Equipment Identification
- Figure 3 — Measurement Arrangement

QP No. QP-QA_-007	Issue Date 15-09-2026	Revision No. R02	Date 15-09-2026	Name SPECguard TEST	COSO
Quality Assurance and Quality Control Procedure					

SIGNATURE AND APPROVAL

Approval / Signature

Prepared By SPECguard TEST	Reviewed By QA/QC	Approved By AUTHORITY
--	---------------------------------	-------------------------------------