

部门文件发布审批表

发布日期	2025 年 6 月 23 日	执行日期	2025 年 6 月 23 日
文件类别		经办人	余天栋
文件用途	明确大总成换修标准		
文件清单	DFMIEC-CV 大总成换修标准管理细则		
会签意见:			
售后服务分部	王艳龙		
运营管理分部	李云山		
东南亚一区	邹逸		
东南亚二区	范少阳		
非洲 RHQ	李门磊		
美洲 RHQ	张中宇		
西亚 RHQ	邹逸		
中亚 RHQ	李哲夫		
俄罗斯 CV 业务部	陈果		
分管领导	柯树		

DFMIEC-CV 大总成换修标准管理细则

DFMIEC-CV Major Assembly Replacement and
Repair Standards Management Rules

DFMIEC 商用车海外营销部	售后服务分部 After-sales Service Division 保修业务管理文件 Warranty Business Management Document	共 5 页 第 1 页 Page 1 of 5
		发布时间: 2025 年 6 月 23 日 Release date: June 23, 2025
		日期: 2025 年 6 月 23 日 Date: June 23, 2025
编制 Prepared by	签字: 余本东 Signature:	日期: 2025 年 6 月 23 日 Date: June 23, 2025
审核 Reviewed by	签字: 王艳东 Signature:	日期: 2025 年 6 月 23 日 Date: June 13, 2025
批准 Approved by	签字: 王艳东 Signature:	日期: 2025 年 6 月 23 日 Date: June 23, 2025

大总成换修标准管理细则

Major Assembly Replacement and Repair Standards Management Rules

1、目的

1. Purpose

为明确总成换修标准，向服务站提供大总成换修准则，特制定本管理规定。

These management rules are specially formulated to define the standards for major assembly replacement and repair and to provide service stations with clear guidelines for such replacements and repairs.

2、适用范围

2. Scope of application

本办法适用于中国东风汽车工业进出口有限公司 CV 营销部、CV 海外服务站（以下简称服务站）及相关供应商关于大总成换修业务。

These management rules apply to the major assembly replacement and repair operations conducted by DFMIEC CV Marketing Department, CV Overseas Service Stations (hereinafter referred to as the Service Station) and related suppliers.

3、术语

3. Terms and definitions

(1) 五大总成：发动机、变速箱、车桥、驾驶室、缓速器。

(1) Five major assemblies: engine, transmission, axle, cab, and retarder.

(2) 其他大总成：单次维修材料费合计超过 5000 元的维修项目（不含五大总成）。

(2) Other major assemblies: repair items with a total repair material cost of more than CNY 5,000 (excluding five major assemblies).

4、原则

4. Principles

能够修复处理的不换总成，无法修复的优先更换原因件上一层级小总成，更换小总成无法解决的更换大总成。

Assemblies that can be repaired should not be replaced. If repair is not feasible, priority should be given to replacing the next higher assembly. Only when replacing the

next higher assembly cannot resolve the issue should the major assembly be replaced.

5、五大总成换修标准

5. Standards for replacement and repair of five major assemblies

(1) 五大总成换修标准

(1) Standards for replacement and repair of five major assemblies

总成 Assembly	总成分类 Category	更换标准 Replacement standard	修复方式 Repair method
发动机 Engine	发动机总成 Engine assembly	1、公路用车 3 万公里且 3 个月内（以先到为准），非公路用车 1 万公里且 2 个月内（以先到为准）出现缸体、缸盖、曲轴中二件或以上损坏。 Two or more of the cylinder block, cylinder head, and crankshaft are damaged within 30,000 km or 3 months (whichever comes first) for on-road vehicles or within 10,000 km or 2 months (whichever comes first) for off-road vehicles. 2、修复总费用超过总成价值 60%的。The total repair cost exceeds 60% of the assembly's value.	符合任一情况即可更换发动机总成或基础机总成 If any of the above conditions are met, replace the engine assembly or base assembly.
变速箱 Transmission	变速箱总成 Transmission assembly	1、公路用车 3 万公里且 3 个月内，非公路用车 1 万公里且 2 个月内出现变速箱一轴、二轴、中间轴全部损坏，或者有一件及以上连同壳体损坏。 The input shaft, output shaft, and intermediate shaft of the transmission are all damaged or one or more of them along with the housing is (are) damaged within 30,000 km or 3 months (whichever comes first) for on-road vehicles or within 10,000 km or 2 months (whichever comes first) for off-road vehicles. 2、修复总费用超过总成价值 60%的。 The total repair cost exceeds 60% of the assembly's value.	更换变速箱总成 Replace the transmission assembly
驾驶室 Cab	驾驶室空壳 Cab body	1、公路用车 6 个月内，非公路用车 3 个月内驾驶室本体（底板、顶盖、侧围、前围、后围等不可拆分部位）三个及以上部位同时开裂 1.The three or more structural parts of the cab body (e.g., floor, roof panel, side walls, front wall, rear wall and non-detachable parts) are cracked simultaneously within 6 months for on-road vehicles or within 3 months for off-road vehicles.	更换驾驶室空壳 Replace the cab body

车桥 Axle	驱动桥总成 Drive axle assembly	1、公路用车 3 万公里且 3 个月内，非公路用车 1 万公里且 2 个月内，桥壳和主减同时损坏。 The axle housing and main reducer are both damaged within 30,000 km or 3 months for on-road vehicles or within 10,000 km or 2 months for off-road vehicles. 2、修复总费用超过总成价值 60%的。The total repair cost exceeds 60% of the assembly's value.	更换桥总成，其余情况更换损坏零件 If any of the above conditions are met, replace the axle assembly. In other cases, only replace the damaged parts.
缓速器 Retarder	缓速器总成 Retarder assembly	1、缓速器壳体开裂（非外力）。 2、缓速器工作腔结合面漏油、渗油（非热交换器与缓速器壳体结合面、非缓速器与变速箱结合面）。 1. The retarder housing cracks (without external force applied). 2. There is oil leakage or seepage at the working chamber joint surface of the retarder (excluding the joint surfaces between the heat exchanger and the retarder housing, and between the retarder and the transmission).	符合任一情况更换缓速器总成 If any of the above conditions are met, replace the retarder assembly

6、申请与审批流程

6. Application and approval process

(1) 申请条件：单次维修材料费大于 5000 元时，服务站须在 DMS 系统提交《大总成申请单》。

(1) Application conditions: If the material cost for a single repair exceeds CNY 5,000, the service station must submit a *Major Assembly Application Form* through the DMS.

(2) 审批层级：

(2) Approval hierarchy:

① 5000 元 < 单次维修材料费 ≤ 50000，服务站提交《大总成申请单》→ 服务经理终审（2 小时内）。

① CNY 5,000 < single repair material cost ≤ CNY 50,000: The service station submits the *Major Assembly Application Form* → Final review by Service Manager (within 2 hours).

② 50000 < 单次维修材料费，服务站提交《大总成申请单》→ 服务经理审核（2 小时内）→ 售后服务总监终审（2 小时内）。

② CNY 50,000 < Single repair material cost: The service station submits the *Major Assembly Application Form* → Review by Service Manager (within 2 hours) → Final

review by After-Sales Service Director (within 2 hours).

7、其他要求

7. Other requirements

针对其他特殊情况，一事一议处理。

Special cases shall be handled on a case-by-case basis.

8、本办法自 2025 年 9 月 1 日起施行。

8. These rules shall come into effect from September 1, 2025.

9、本办法由 DFMIEC CV 售后服务分部负责解释。

9. The DFMIEC CV After-Sales Service Department is responsible for the interpretation of these rules.

