
AX_X_TO_BOOL_2
I1
CNF
C
AX_X_TO_BOOL
IN
I2
AX_IN
AX_X_TO_BOOL_3
CNF
C
AX_X_TO_BOOL
IN
I3
AX_IN
AX_X_TO_BOOL_4
CNF
I4
C
AX_X_TO_BOOL
IN
AX_IN
F_BOOL_TO_UINT_12
REQ
CNF
B
F_BOOL_TO_UINT
IN
OUT
F_BOOL_TO_UINT_13
REQ
CNF
B
F_BOOL_TO_UINT
IN
OUT
F_BOOL_TO_UINT_14
REQ
CNF
B
F_BOOL_TO_UINT
IN
OUT
Uebung_087_AX
Beispiel für F_DEMUX mit Plug and Socket
REQ
CNF
Si
ADD_3
Q1
Q2
Q3
Q4