

Instante	Sensor	Máquina	Valor
t1	1	1	$S^1M^1(t1)$
t1	1	2	$S^1M^2(t1)$
t1	1	3	$S^1M^3(t1)$
⋮	⋮	⋮	⋮
t1	2	1	$S^2M^1(t1)$
t1	2	2	$S^2M^2(t1)$
t1	2	3	$S^2M^3(t1)$
⋮	⋮	⋮	⋮
t2	1	1	$S^1M^1(t2)$
t2	1	2	$S^1M^2(t2)$
t2	1	3	$S^1M^3(t2)$

S → Sensor

M → Máquina