
- 1. Draw the indicator scale of a gravity control permanent magnet moving coil type analog ammeter with the range 0-10 A.
- 2. How to increase the rotating torque of the following induction type instrument? What will happen if you supply DC current to coil  $P_1$  and  $P_2$ ?



3. How to increase the range of an electrodynamometer type ammeter and voltmeter? Explain your answer.