	FFTOU	CARRY (p1)	IS_ZERO (p2)	T0/000	-FLAG_SET	-MAR_LOAD	-WE				-LOAD A		HALT	$\overline{}$	SUB/-ADD	-LOAD_B	DISP	INC	-PC_OUT	-PC_LOAD	ADDRESS [X_X_p1_p2 OPCODE 0_t2_t1_t0]	HEXA ADDRESS	EEPROM_1	EEPROM_2	
	FETCH	X		T0(000)		0	1	1	1	1	1	1	0	0	0	1	0	0	0	1	[XXXX XXXX 0000]	XX0	BF	11	
		Х	X	T1(001)	1	1	1	0	1	0	1	1	0	0	0	1	0	1	1	1	[XXXX XXXX 0001]	XX1	EB	17	
1	HALT	X	Х	T2(010)	4	1	1	1	1	1	4	1	1	0	0	1	0	0	1	1	[XXXX 0000 0010]	X02	FF	93	
•	0000	X	X	T3(011)	_	1	-	_	-	1	1	-	0	0	0	1		0	1	1	[XXXX 0000 0010]	X03	FF	13	
	0000	_	-	T4(100)	_	+	1		1	1	1	1	0	-			0			_	[XXXX 0000 0011]	X04	1111	13	
		Х	X	14(100)		1		1	1				U	0	0	1	0	0	1	1		Λ04	FF	13	
2	LOAD X	Х	Y	T2(010)	1	0	1	1	0	1	1	1	0	0	0	1	0	0	1	1	[XXXX 0001 0010]	X12	B7	13	
_	0001	X	X	T3(011)	_	1	1		1	1	0	1	0	0	0	<u>'</u>	0	0	1	1	[XXXX 0001 0010]	X13	ED		
	0001	X	X	T4(100)		1	1	1	1	1	1	1	0	0	0	1	0	0	1	1	[XXXX 0001 0011]	X14	FF	13	
		^	^	14(100)	-	•	•	•	•	•	•		-	-	U	•	U	U	•	•	[XXXX 0001 0100]	A14		13	
3	ADD X	Х	Х	T2(010)	1	0	1	1	0	1	1	1	0	0	0	1	0	0	1	1	[XXXX 0010 0010]	X22	B7	13	
	0010	х	х	T3(011)	_	1	1	0	1	1	1	1	0	0	0	0	0	0	1	1	[XXXX 0010 0011]	X23	EF	О3	
		X	X	T4(100)		1	1	1	1	1	0	1	0	1	0	1	0	0	1	1	[XXXX 0010 0100]	X24	7D	53	
				()																					
4	SUB X	Х	Х	T2(010)	1	0	1	1	0	1	1	1	0	0	0	1	0	0	1	1	[XXXX 0011 0010]	X32	B7	13	
	0011	Х	Х	T3(011)	1	1	1	0	1	1	1	1	0	0	0	0	0	0	1	1	[XXXX 0011 0011]	X33	EF	О3	
		Х	Х	T4(100)	_	1	1	1	1	1	0	1	0	1	1	1	0	0	1	1	[XXXX 0011 0100]	X34	7D	73	
5	DISP	Х	Х	T2(010)	1	1	1	1	1	1	1	0	0	0	0	1	1	0	1	1	[XXXX 0100 0010]	X42	FE	1B	
	O100	Х	Х	T3(011)	1	1	1	1	1	1	1	1	0	0	0	1	0	0	1	1	[XXXX 0100 0011]	X43	FF	13	
		Х	Х	T4(100)	_	1	1	1	1	1	1	1	0	0	0	1	0	0	1	1	[XXXX 0100 0100]	X44	FF	13	
6	STORE X	Х	Х	T2(010)	1	0	1	1	0	1	1	1	0	0	0	1	0	0	1	1	[XXXX 0101 0010]	X52	B7	13	
	O101	Х	Х	T3(011)	1	1	0	1	1	1	1	0	0	0	0	1	0	0	1	1	[XXXX 0101 0011]	X53	DE	13	
		Х	Х	T4(100)	1	1	1	1	1	1	1	1	0	0	0	1	0	0	1	1	[XXXX 0101 0100]	X54	FF	13	
7	LOAD IMM X	Х	Х	T2(010)	1	1	1	1	0	1	0	1	0	0	0	1	0	0	1	1	[XXXX 0110 0010]	X62	F5	13	
	O110	Х	Х	T3(011)	_	1	1	1	1	1	1	1	0	0	0	1	0	0	1	1	[XXXX 0110 0011]	X63	FF	13	
		Х	Х	T4(100)	1	1	1	1	1	1	1	1	0	0	0	1	0	0	1	1	[XXXX 0110 0100]	X64	FF	13	
8	INC X	X	Х	T2(010)	1	1	1	1	0	1	1	1	0	0	0	0	0	0	1	1	[XXXX 0111 0010]	X72	F7		
	0111	Х	Х	T3(011)	0	1	1	1	1	1	0	1	0	1	0	1	0	0	1	1	[XXXX 0111 0011]	X73	7D	53	

		CARRY (p1)	IS_ZERO (p2)		-FLAG_SET	-MAR_LOAD	-WE	-IR OUT	-IR_LOAD	-LOAD_A	-ENABLE_A	HALT	ALU_OUT	SUB/-ADD	-LOAD_B	DISP	PC_INC	-PC_OUT	-PC_LOAD	ADDRESS [X_X_p1_p2 OPCODE 0_t2_t1_t0]	HEXA ADDRESS	EEPROM_1	EEPROM_2	
	OPCODE + 4BIT NUM	X	X	T4(100)	1	1	1	1 1	1	1	1	0	0	0	1	0	0	1	1	[XXXX 0111 0100]	X74	FF	13	
9	DEC X	Х	Х	T2(010)		1	1	1 0	1	1	1	0	0	0	0	0	0	1	1	[XXXX 1000 0010]	X82	F7	О3	
	1000	Х	X	T3(011)		1	1	1 1	1	0	1	0	1	1	1	0	0	1	1	[XXXX 1000 0011]	X83	7D	73	
	OPCODE + 4BIT NUM	Х	X	T4(100)	1	1	1	1 1	1	1	1	0	0	0	1	0	0	1	1	[XXXX 1000 0100]	X84	FF	13	
10	JUMP X	Х	X	T2(010)		1	1	1 0	1	1	1	0	0	0	1	0	0	1	0	[XXXX 1001 0010]	X92	F7	12	
	1001	X	X	T3(011)		1	1	1 1	1	1	1	0	0	0	1	0	0	1	1	[XXXX 1001 0011]	X93	FF	13	
		X	X	T4(100)	1	1	1	1 1	1	1	1	0	0	0	1	0	0	1	1	[XXXX 1001 0100]	X94	FF	13	
																					_			
11	JUMP CAR X	1	X	T2(010)		1	1	1 0	+	1	1	0	0	0	1	0	0	1	0	[XX1X 1010 0010]	[XX1X]A2	F7		2,3,6,7,A,B.E.F
	1010	0	X	T2(010)	_	1	1	1 1	1	1	1	0	0	0	1	0	0	1	1	[XX0X 1010 0010]	[XX0X]A2	FF		0,1,4,5,8,9,C,D
		Х	X	T3(011)	1	1	1	1 1	1	1	1	0	0	0	1	0	0	1	1	[XXXX 1010 0011]	XA3	FF	13	
		Х	X	T4(100)	1	1	1	1 1	1	1	1	0	0	0	1	0	0	1	1	[XXXX 1010 0100]	XA4	FF	13	
12	JUMP IFZ X	Х	1	T2(010)	_	1	1	1 0	1	1	1	0	0	0	1	0	0	1	0	[XXX1 1011 0010]	[XXX1]B2	F7		1,3,5,7,9,B,D,F
	1011	X	0	T2(010)	1	1	1	1 1	1	1	1	0	0	0	1	0	0	1	1	[XXX0 1011 0010]	[XXX0]B2	FF	13	0,2,4,6,8,A,C,E
		Х	X	T3(011)	1	1	1	1 1	1	1	1	0	0	0	1	0	0	1	1	[XXXX 1011 0011]	XB3	FF	13	
		Х	X	T4(100)	1	1	1	I 1	1	1	1	0	0	0	1	0	0	1	1	[XXXX 1011 0100]	XB4	FF	13	