
Inputs
TC-holder ELA
per model
Equipment manuals
Removals per model
Battery SOH, SOC, kT
Configuration
Removed and
added loads
Duty per phase,
RX/TX pairing
Circuits, breakers
Analysis
Phase loads
Circuit loads
Sequential battery
depletion (CASA,
Peukert), net change
Criteria, outputs
R1a to R3 with
source paragraph
AML matrix
Tornado (method),
Monte Carlo (physical)