## **Carriage Gear Cover:**

If swarf enters the carriage gears the low torque stepper will probably lose steps or even stalls. To prevent swarf entering the gears I made a gear cover out of 6 mm Trespa, however I think it would have been easier to make it out of thin (0.4 mm) metal sheet.

