STANDARD

METROLOGY EDITION

by MetraSlate

Standard by MetraSlate: Metrology Edition

Pilot / Early Access

Equipment. Customer Work. Technical Records.

LABORATORY OPERATIONS

From Customer Request to Reviewed Certificate

Manage the calibration and the business around it.

Standard by MetraSlate: Metrology Edition connects customer requests, estimates, equipment intake, assignments, approved templates, measurements and reference standards with uncertainty, review, certificates and invoicing.

Customer service can follow the job. Technicians can work from its technical basis. Reviewers can inspect how the result was reached. Managers can connect completed work with quality, cost and the account balance.

Metrology is the first Standard edition, developing Asset's general equipment and business foundation for calibration laboratories.

REQUEST, ESTIMATE AND INTAKE

Give Each Instrument a Clear Next Step

Request and Estimate

Record the customer, site, instruments and requested service. Retain the issued quotation revision, approved items and purchase-order context.

Equipment Intake

Connect receipt and custody to the instrument. Physical possession remains distinct from calibration progress.

Assigned Work


Organize service into instrument-level lines with the responsible team, location and next operating step. A hold on one instrument need not obscure the others.

Shared Progress

Customer service, laboratory staff and operations use the same order to investigate the work and explain what needs attention.

APPROVED TEMPLATES

Reuse the Method Without Losing the Run



Reuse approved model specifications and measurement points while each run retains its selected revision, instrument identity and evidence.

Demonstration with sample data.

MEASUREMENT RECORDS

Keep the Reading and Its Basis Together

A measurement needs enough context for another person to evaluate and review it.

Instrument and Method

Identify the instrument, selected procedure and approved datasheet revision. Preserve the points and specification used for the run.

Measurements

Record values and units, nominal or stimulus, as-found and as-left phases, and relevant adjustment or environmental context.

Reference Standards

Attribute the standards used and the contributions needed for the selected uncertainty model. Unresolved inputs require the applicable review or refusal.

Evaluation

Keep calculated uncertainty, limits, TUR, guardband and the selected decision rule with the result.

WORKED UNCERTAINTY EXAMPLE

Follow the Calculation From Inputs to Result

Three independent contributions, in volts. Sensitivity coefficients are 1.

Contribution	Input and Treatment	Standard Uncertainty
Reference certificate	Expanded U = 0.020 V, k = 2	0.010000 V
Display resolution	Step = 0.010 V / sqrt(12)	0.002887 V
Repeatability	Established standard uncertainty	0.004000 V

$$u_c = \sqrt{0.010000^2 + 0.002887^2 + 0.004000^2} = 0.01115\ \text{V}$$

At a selected k = 2: expanded U = 0.02230 V

Illustrative arithmetic. The method must justify independence, contributions and coverage. Finite degrees of freedom can require Student-t coverage.

UNCERTAINTY AND GUARDBANDING

Keep the Decision Rule With the Measurement

Resolve the Contributions

Use the attributed reference standards, applicable specifications, sensitivity and configured DUT-resolution treatment.

Inspect Uncertainty and TUR

Keep combined uncertainty, coverage, reported uncertainty and the selected TUR convention visible with the result.

Apply the Decision Policy

Retain specification limits, guardband and acceptance interval separately. The laboratory's configured policy determines the outcome.

Handle Missing Evidence

Missing standards or unresolved contributions follow explicit refusal or report-of-value handling. An incomplete budget must remain identifiable.

CMC BUDGETS

From Endpoint Budgets to a Capability Curve

Each endpoint has its own contributor budget. The fitted curve retains those inputs and results.

Low point	At x = 0 V: expanded U = 0.040 V.
High point	At x = 100 V: expanded U = 0.080 V.
Linear example	B1 = (0.080 - 0.040) / 100 = 0.0004; B0 = 0.040 V.

$U(x) = 0.0004x + 0.040\ V$

Illustrative linear fit. Two endpoints alone do not establish validity across the range. A calculated curve does not confer accreditation.

MetraSlate Demo Lab **DEMO-2026-00024**
Sample certificate · 24 measurement points
lab@example.test metraslate.com

Certificate Of Calibration

Date: 10/24/2026

Certificate No: **DEMO-2026-00024**

Rev 0

CUSTOMER
Sample Manufacturing Company
Demonstration account
Contact: Sample Quality Team

WORK ORDER
DEMO-WO-2026-01024

ITEM CALIBRATED
Control #: DEMO-00024
Asset ID: DMM-024
Gage type: Digital multimeter
Manufacturer: Example Instruments
Model No: DM-6000
Temp: 23.0 °C RH: 45 %RH
Demonstration laboratory

CALIBRATION
Description: Multifunction digital multimeter
Serial No: DEMO-24001
Received date: 10/23/2026
Performed by: Sample Technician
Received condition: Good
Returned condition: IN TOLERANCE
Cal. date: 10/24/2026
Cal. interval: 12 months
Cal. due date: 10/24/2027

SERVICE LEVEL
Calibration with uncertainty
Version: 1
Decision rule: Simple acceptance
Guardband method: None
TUR basis: Tolerance / expanded uncertainty
Coverage policy: k = 2
Agreed under: DEMO-EST-024
Accepted: 10/23/2026
Result: **Pass**

CALIBRATION NOTES
See the attached calibration data for the measured values.
Scope: FULL — points included 24, excluded 0
Basis: DC voltage, AC voltage, resistance and DC current

STANDARDS USED TO CALIBRATE EQUIPMENT

I.D.	MODEL	DESCRIPTION	CAL. DUE DATE
STD-DEMO-01	MC-6000	Multifunction calibrator · sample	09/30/2027

PROCEDURES USED IN THIS EVENT

PROCEDURE NAME	DESCRIPTION / REFERENCE
Multimeter calibration · sample	DEMO-DMM-01 · Rev 1 · 24 points

This certifies that the equipment identified above has been calibrated using applicable MetraSlate Demo Lab procedures, under that laboratory's quality management system.
Simple acceptance: readings are compared directly with the stated limits.
As Received Conditions: All 24 sample points are within the stated acceptance limits.
Action Taken: No adjustment. As-found readings are retained as the as-left results.
As Shipped Conditions: All 24 sample points are within the stated acceptance limits.
Remarks or special requirements: Questions about this certificate should be addressed to MetraSlate Demo Lab using the contact details above.

Notes: 1) This calibration report shall not be reproduced, except in full, and its results relate only to the item calibrated.
2) Calibration cycles, and the due dates that follow from them, are set by the customer.
3) Times shown in America/New_York.
4) Expanded uncertainty is reported with coverage factor k = 2. TUR is the tolerance half-width divided by expanded uncertainty.

STATUS	MEANING
Pass	The reported reading is within the stated acceptance limits.

Traceability Information: Synthetic demonstration data; no physical calibration is represented.

Print date: 10/24/2026

Calibrating technician

Sample Technician

10/24/2026 10:15 · Sample authorship

QC approval

Sample Reviewer

10/24/2026 11:00 · Sample review
Approved Signatory

CALIBRATION DATA

DC Voltage Measure

SET POINT	NOMINAL	AS FOUND	AS LEFT	LOW LIMIT	UPPER LIMIT	UNCERTAINTY	PASS/FAIL	TUR
-10 V	-10.0000 V	-9.9990 V	-9.9990 V	-10.0050 V	-9.9950 V	0.0010 V	Pass	5.0:1
-1 V	-1.00000 V	-1.00010 V	-1.00010 V	-1.00050 V	-0.99950 V	0.00010 V	Pass	5.0:1
-0.1 V	-0.10000 V	-0.09998 V	-0.09998 V	-0.10010 V	-0.09990 V	0.000020 V	Pass	5.0:1
0.1 V	0.10000 V	0.09998 V	0.09998 V	0.09990 V	0.10010 V	0.000020 V	Pass	5.0:1
1 V	1.00000 V	1.00010 V	1.00010 V	0.99950 V	1.00050 V	0.00010 V	Pass	5.0:1
10 V	10.0000 V	9.9990 V	9.9990 V	9.9950 V	10.0050 V	0.0010 V	Pass	5.0:1

AC Voltage Measure · 1 kHz

SET POINT	NOMINAL	AS FOUND	AS LEFT	LOW LIMIT	UPPER LIMIT	UNCERTAINTY	PASS/FAIL	TUR
0.1 V	0.1000 V	0.1002 V	0.1002 V	0.0990 V	0.1010 V	0.00020 V	Pass	5.0:1
1 V	1.0000 V	0.9990 V	0.9990 V	0.9950 V	1.0050 V	0.0010 V	Pass	5.0:1
10 V	10.000 V	10.010 V	10.010 V	9.950 V	10.050 V	0.010 V	Pass	5.0:1
50 V	50.000 V	49.950 V	49.950 V	49.750 V	50.250 V	0.050 V	Pass	5.0:1
100 V	100.00 V	100.10 V	100.10 V	99.50 V	100.50 V	0.10 V	Pass	5.0:1
230 V	230.000 V	229.770 V	229.770 V	228.850 V	231.150 V	0.23 V	Pass	5.0:1

Resistance Measure

SET POINT	NOMINAL	AS FOUND	AS LEFT	LOW LIMIT	UPPER LIMIT	UNCERTAINTY	PASS/FAIL	TUR
10 Ω	10.000 Ω	10.010 Ω	10.010 Ω	9.950 Ω	10.050 Ω	0.010 Ω	Pass	5.0:1
100 Ω	100.00 Ω	99.90 Ω	99.90 Ω	99.50 Ω	100.50 Ω	0.10 Ω	Pass	5.0:1
1 kΩ	1.0000 kΩ	1.0010 kΩ	1.0010 kΩ	0.9950 kΩ	1.0050 kΩ	0.0010 kΩ	Pass	5.0:1
10 kΩ	10.000 kΩ	9.990 kΩ	9.990 kΩ	9.950 kΩ	10.050 kΩ	0.010 kΩ	Pass	5.0:1
100 kΩ	100.00 kΩ	100.10 kΩ	100.10 kΩ	99.50 kΩ	100.50 kΩ	0.10 kΩ	Pass	5.0:1
1 MΩ	1.0000 MΩ	0.9990 MΩ	0.9990 MΩ	0.9950 MΩ	1.0050 MΩ	0.0010 MΩ	Pass	5.0:1

DC Current Measure

SET POINT	NOMINAL	AS FOUND	AS LEFT	LOW LIMIT	UPPER LIMIT	UNCERTAINTY	PASS/FAIL	TUR
100 µA	100.00 µA	100.10 µA	100.10 µA	99.50 µA	100.50 µA	0.10 µA	Pass	5.0:1
1 mA	1.0000 mA	0.9990 mA	0.9990 mA	0.9950 mA	1.0050 mA	0.0010 mA	Pass	5.0:1
10 mA	10.000 mA	10.010 mA	10.010 mA	9.950 mA	10.050 mA	0.010 mA	Pass	5.0:1
100 mA	100.00 mA	99.90 mA	99.90 mA	99.50 mA	100.50 mA	0.10 mA	Pass	5.0:1
1 A	1.0000 A	1.0010 A	1.0010 A	0.9950 A	1.0050 A	0.0010 A	Pass	5.0:1
5 A	5.0000 A	4.9950 A	4.9950 A	4.9750 A	5.0250 A	0.0050 A	Pass	5.0:1

— End of certificate —

CUSTOMER PORTAL AND INVOICING

Keep the Customer's Decision With the Job

Before Service

Authorized contacts select equipment, request quotations, approve the proposed work and provide purchase-order information.

During Service

Customers follow shared status, request collection and answer permitted decisions for the affected instrument.

After Release

Released certificates remain accessible from equipment and service history. Contacts can review the invoices and balances made available to their account.

Financial Follow-Through

Keep accepted terms, invoice lines, recorded receipts, credits and remaining balances connected. A recorded receipt is distinct from an external processor transaction.

OPERATING COSTS

Understand What the Work Costs the Business

Posted Financial Results

Journal movements support revenue, cost of service, expenses, net income and financial statements. Results depend on complete postings and account mapping.

Work and Quality

Review throughput, turnaround, first-pass results and returns. Trace a recurring issue to its records before assigning a cause.

Receivables

Inspect open balances, aging and due dates to identify the accounts requiring follow-up.

Costing in Development

Automatic per-job margin needs maintained labor rates, attended time, materials, reference-equipment allocation and overhead. Recorded run duration alone is not labor cost.

QUALITY AND TRACEABILITY

Trace a Suspect Standard to the Work It Supported

Find the Affected Work

Use actual reference-standard attribution and the relevant period to identify calibrations, instruments and released certificates for assessment.

Record the Judgment

Retain the technical reason and responsible person for each affected-item decision. A linked result is not automatically an invalid result.

Follow the Correction

Connect containment, cause, corrective actions and effectiveness review. Amendments or withdrawal follow the certificate's controlled record.

Finish the Follow-Up

Configured close checks identify unresolved actions, undecided items and customer notices still owed.

CURRENT SCOPE

Evaluate the Methods Your Laboratory Uses

Pilot / Early Access. Product images use sample data.

Calculation Scope	Supported contribution-based evaluation and CMC budgets are described here. General covariance, authored repeated-observation completion and a complete MSA suite are outside this offer's validated scope.
Connections	External execution, mail delivery and accounting connections need defined configuration and acceptance. Automated customer payment collection remains in development. A ready QuickBooks connector is not offered.
Adoption	Choose representative instruments, methods, users and failure cases. Agree migration, support, recovery, export and the outcomes required before broader rollout.

Bring one recurring job to metraslate.com/demo.