

Document No	:	MT-056-SOP-003	STANDARD OPERATING PROCEDURE
Effective Date	:	March 7, 2025	
Revision Status	:		Installation of Components on Base Gamma Sparc
Department : Engineering			

1. PURPOSE :


to find out how to assemble each piece of hardware on the Sparc Gamma, base section.






including what types of components are needed.

2. SCOPE :

This document outlines the step-by-step procedure for installing each component on the mechanical gamma sparc base section.

3. PROCEDURE DETAILS:

No.	Picture	Detail
1		making spacer holes on base (LED PCB).
2		spacer installation (0.5cm).

3		soldering LED on PCB color provision according to the picture .
4		Soldering the 6-pin JST in the direction of the arrow.
5		Soldering the 2-pin JST in the direction of the arrow.
6		Installation of a 10K resistor.
7		Installation of Push Button and 2-pin JST.
8		Install M4 Nut bolts on all 4 sides of the base.