NOTICE: This report is required by 49 CFR Part 195. Failure to report can result in a civil penalty not to exceed $100,000 for each violation for each day that such violation persists except that the maximum civil penalty shall not exceed $1,000,000 as provided in 49 USC 60122.

OMB NO: 2137-0047

EXPIRATION DATE 3/31/2024

U.S. Department of Transportation
Pipeline and Hazardous Materials
Safety Administration

ACCIDENT REPORT – HAZARDOUS LIQUID AND CARBON DIOXIDE PIPELINE SYSTEMS

Report Date 3/26/2026

No. 20260075
(DOT Use Only)

A federal agency may not conduct or sponsor, and a person is not required to respond to, nor shall a person be subject to a penalty for failure to comply with a collection of information subject to the requirements of the Paperwork Reduction Act unless that collection of information displays a current valid OMB Control Number. The OMB Control Number for this information collection is 2137-0047. Public reporting for this collection of information is estimated to be approximately 12 hours per response, including the time for reviewing instructions, gathering the data needed, and completing and reviewing the collection of information. All responses to this collection of information are mandatory. Send comments regarding this burden estimate or any other aspect of this collection of information, including suggestions for reducing this burden to: Information Collection Clearance Officer, PHMSA, Office of Pipeline Safety (PHP-30) 1200 New Jersey Avenue, SE, Washington, D.C. 20590.

INSTRUCTIONS

Important: *Please read the separate instructions for completing this form before you begin. They clarify the information requested and provide specific examples. If you do not have a copy of the instructions, you can obtain one from the PHMSA Pipeline Safety Community Web Page at* https://www.phmsa.dot.gov/pipeline/library/forms.

PART A – KEY REPORT INFORMATION

Report Type: *(select all that apply)* ☐ Original ☐ Supplemental ☐ Final
ORIGINAL

A1. Operator's OPS-issued Operator Identification Number (OPID): / / / / / / 40668

A2. Name of Operator: *auto-populated based on OPID* ENBRIDGE HOLDINGS (GRAY OAK) LLC

A3. Address of Operator:

A3a. *auto-populated based on OPID* 915 N ELDRIDGE PKWY, SUITE 1100
(Street Address)

A3b. *auto-populated based on OPID* HOUSTON ENBRIDGE HOLDINGS (GRAY OAK) LLC
(City)

A3c. State: *auto-populated based on OPID* / / / TX

A3d. Zip Code: *auto-populated based on OPID* / / / / / / - / / / / / 77079

A4. Earliest loca 2/27/2026 8:35 *k)* and date an accident reporting criterion was met:

/ / / / Hour / / Month / / Day / / / Year

A4a. Time Zone for local time (select only one) ○ Alaska ○ Eastern ○ Central ○ Hawaii-Aleutian ○ Mountain ○ Pacific. CENTRAL

A4b. Daylight Saving in effect? ○ Yes ○ No NO

A5. Location of Accident:

Latitude: / / / . / / / / / / 28.516772

Longitude: - / / / / . / / / / / / -98.188692

A6. Co CRUDE OIL *ne, based on predominant volume released)*

☐ Crude Oil

☐ Refined and/or Petroleum Product (non-HVL) which is a Liquid at Ambient Conditions

○ Gasoline (non-Ethanol) ○ Diesel, Fuel Oil, Kerosene, Jet Fuel

○ Mixture of Refined Products (transmix or other mixture)

○ Other ⇨ Name: _____

☐ HVL or Other Flammable or Toxic Fluid which is a Gas at Ambient Conditions

○ Anhydrous Ammonia

○ LPG (Liquefied Petroleum Gas) / NGL (Natural Gas Liquid)

○ Other HVL ⇨ Name: _____

☐ CO_2 (Carbon Dioxide)

☐ Biofuel / Alternative Fuel (including ethanol blends)

○ Fuel Grade Ethanol ○ Ethanol Blend ⇨ % Ethan _____

○ Biodiesel ⇨ Blend (e.g. B2, B20, B100): B/ / / / ○ Other ⇨ Name: _____

A7. Estimated volume of commodity released unintentionally: 1.5 / / / / , / / / / . / / / Barrels

A8. Estimated volume of intentional and/or controlled release/blowdown: / / / / Barrels
(only reported for HVL and CO_2 Commodities)

A9. Estimated volume of commodity recovered 1.5 / / / / , / / / / . / / / Barrels

Reproduction of this form is permitted

A10. Were there fatalities? ○ Yes ○ No NO If Yes, specify the number in each categor A10a. Operator employees 0 A10b. Contractor employees working for the Operator 0 / / / / / A10c. Non-Operator emergency responders 0 A10d. Workers working on the right-of-way, but NOT associated with this Operator 0 A10e. General public 0 / A10f. Total fatalities (sum of above) *calculated* 0	A11. Were there injuries requiring inpatient hospitalization? NO No If Yes, specify the number in each category: A11a. Operator employees / A11b. Contractor employees working for the Operator A11c. Non-Operator emergency responders / A11d. Workers working on the right-of-way, but NOT associated with this Operator A11e. General public / A11f. Total injuries (sum of above) *calculated* 0

Reproduction of this form is permitted

A12. formerly E8. What was the Operator's initial indication of the Failure? *(select only one)* LOCAL OPERATING PERSONNEL, INCLUDING CONTRACTORS

- ☐ CPM leak detection system
- ☐ SCADA-based information (such as alarm(s), alert(s), event(s), and/or volume calculations)
- ☐ Static Shut-in Test or Other Pressure or Leak Test
- ☐ Controller
- ☐ Air Patrol
- ☐ Notification from Public
- ☐ Notification from Third Party that caused the Accident
- ☐ Local Operating Personnel, including contractors
- ☐ Ground Patrol by Operator or its contractor
- ☐ Notification from Emer
- ☐ Other _____

A12a. formerly E8.a If "Controller", "Local Operating Personnel, including contractors", "Air Patrol", or "Ground Patrol by Operator or its contractor" is selected in Question 8, specify the following: *(select only one)*

OPERATOR EMPLOYEE

○ Operator employee ○ Contractor working for the Operator

2/27/2026 8:35

A13. ONSHORE TERMINAL/TANK FARM EQUIPMENT AND PIPING ime Operator identified failure /___/___/___/___ Hour ___ Month ___/___ Day /___/___/ Year

A14. formerly C2 Part of system involved in Accident: *(select only one)*

- ☐ Onshore Breakout Tank or Storage Vessel, Including Attached Appurtenances
- ☐ Onshore Terminal/Tank Farm Equipment and Piping
- ☐ Onshore Equipment and Piping Associated with Belowground Storage
- ☐ Onshore Pump/Meter Station Equipment and Piping
- ☐ Onshore Pipeline, Including Valve Sites
- ☐ Offshore Platform/Deepwater Port, Including Platform-mounted Equipment and Piping
- ☐ Offshore Pipeline, Including Riser and Riser Bend

ONSHORE

A15. *uto-populated based on A14* Was the origin of the Accident onshore?

○ Yes *(Complete Questions B3-B12)* ○ No *(Complete Questions B13-B15)*

NORMAL OPERATION, INCLUDES PAUSES BETWEEN BATCHES AND DURING MAINTENANCE

A16. e Operator identified failure *(select only one)*

- ○ Post-Construction Commissioning
- ○ Post-Maintenance/Repair
- ○ Routine Start-Up
- ○ Routine Shutdown
- ○ Normal Operation, include pauses between batches and during maintenance
- ○ Idle

NO

A17. form = Routine Start- tion, was the pipeline/facility shut down due to the Accident?

○ Yes ○ No ⇨ Explain: LINE WAS NOT RUNNING WHEN RELEASE OCCURRED _____

If Yes, complete Questions A17.a and A17.b: *(use local time, 24-hr clock)*

A17a. formerly A14.a Local tim n /___/___/___/___/ Hour /___/___/ Month /___/___/ Day /___/___/ Year

A17b. formerly A14.b Local time started /___/___/___/___/ Hour /___/___/ Month /___/___/ Day /___/___/ Year

**Supplemental Report required*

If A12 = Notification from Emergency Responder, skip A18.a through A18.c.

NO

A18a. Did the operator communicate with Local, State, or Federal Emergency Responders about the accident? ○ Yes ○ No

If No, skip A18b. and A18c

A18b. Which party initiated communication about the accident? Operator Local/State/Federal Emergency Responder

A18c. Local time of initial Operator and Local/State/Federal Emergency Responder communication

/___/___/___/___/ Hour /___/___/ Month /___/___/ Day /___/___/ Year

2/27/2026 8:35

A19. formerly A18.b Local time Operat ved on site /___/___/___/___/ Hour /___/___/ Month /___/___/ Day /___/___/ Year

2/27/2026 8:35

A20. Local time of confirmed discovery /___/___/___/___/ Hour /___/___/ Month /___/___/ Day /___/___/ Year

2/27/2026 14:02

A21a. formerly A7. Local time *(24-hr clock)* and date of initial operator report to the National Response Center:

/___/___/___/___/ Hour /___/___/ Month /___/___/ Day /___/___/ Year

1456002

A21b. formerly A6. Initial Operator National Response Center Report Number OR ○ NRC Notification Not Required OR ○ NRC Notification Required But Not Made

A21c. Additional NRC Report numbers submitted by the operator: 1456092 20260075

NO

A22. formerly A15. Did th ity ignite? ○ Yes ○ No If Yes, answer A22.a through d:

Reproduction of this form is permitted

A22a. Local time of ignition /___/___/___/___/ /___/___/ /___/___/ /___/___/
Hour Month Day Year

A22b. How was the fire extinguished?
O Operator/Contractor O Local/State/Federal Emergency Responder O Allowed to burn out O Other _____

A22c. Estimated volu fire (barrels): (must be less than or equal to A7)

A22d. formerly A16. Did the co lode? O Yes O No

If A14. is "Onshore Pipeline, Including Valve Sites" OR "Offshore Pipeline, Including Riser and Riser Bend", answer A23a through f:

A23a. Initial ac upstream of failure location O Valve Closure O Operational Control - mandatory text field
If Valve Closure, answer A23b and c:
A23b. Local _____ /___/___/___/ /___/___/
Hour Month Day Year
A23c. forme alve used to initially isolate release source:
O Manual O Automatic O Remotely Controlled

A23d. I ow downstream of failure location O Valve Closure O Operational Control - mandatory text field
If Valve Closure, answer A23.e and f:
A23e. Local time of valve closure /_____ _____ /___/___/ /___/___/
Hour Month Day Year
A nstream valve used to initially isolate release source:
O Manual O Automatic O Remotely Controlled O Check Valve

If A6 = Crude Oil , Refined and/or Petroleum Product (non-HVL) which is a Liquid at Ambient Conditions, or Biofuel / Alternative Fuel (including ethanol blends) AND A15. is Onshore, answer questions A24a and c: YES
A24a. Did the operator notify a "qualified individual" in the Onshore Oil Spill Response Plan? O Yes O No
If Yes, answer A24b.
2/27/2026 8:56
A24b. Local time the "qualified individual" was notified. /___/_____ _____ ___/___/ /___/___/
Hour Month Day Year
NO
A24c. Did the operator activate an Oil Spill Removal Organization (OSRO)? O Yes O N
If Yes, answer A24d and e:
A24d. Local time operator activated OSRO /___/___/___/___/ /_____ _____ _____/
Hour Month Day Year
A24e. Local time OSRO arrived on site /___/___/___/___/ /___/___/ /___/___/ /___/___/
Hour Month Day Year
0
A25. formerly A17. Number of general public evacuated: /___/___/___/,/___/___/___/

Reproduction of this form is permitted

PART B – ADDITIONAL LOCATION INFORMATION

B1. formerly B7. Pipeline/Facility name: CENTRAL JUNCTION TERMINAL

B2. formerly B8. Segment name/ID: LINE 1008

If **On** TX

B3. _____ 78071

B4. Zip Code: /___/___/___/___/___/ - /___/___/___/___/

B5. THREE RIVERS B6. LIVE OAK

County or Parish

MILEPOST

B7. Op ation: *(select only one)* ☐ Milepost *(specify in shaded area below)*

401 ☐ Survey Station No. *(specify in shaded area below)*

B8 /___/___/___/___/___/___/___/___/___/___/___/___/___/___/

B9. W Accident on Federal land? ○ Yes ○ No NO

B10. L ent: *(select only one)*

☐ Totally contained on Operator-controlled property ☐ Pipeline right-of-way

erator-controlled property, but then flowed or migrated off the property

ABOVEGROUND

B11. OTHER *(select only one)*

☐ appurtenances

☐ Underground ⇨ Specify: ○ Under soil ○ Under a building ○ Under pavement ○ Exposed due to excavation

Exposed due to loss of cover ○ In underground enclosed space (e.g., vaul

TEMPORARY VENDOR INJECTION LINE

B11a r (in): /___/,/___/___/___/ OR ○ Unknown

☐ Aboveground ⇨ Specify: ○ Typical aboveground facility piping or appurtenance ○ Overhead crossing ○ Inside a building

○ In or spanning an open ditch ○ Inside other enclosed space ○ Other _____ TEMPORARY VENDOR INJECTION LINE

☐ Transition Area Specify: ○ Soil/air interface ○ Wall sleeve ○ Pipe support or other close contact area

TEMPORARY VENDOR INJECTION LINE

NO

B12. Did the Accid in a crossing?: ○ Yes ○ No y ty

NO

☐ Bridge crossing Specify: ○ Cased ○ Uncased

☐ Railroad crossing *(select all that apply)* ○ Cased ○ Uncased ○ Bor NO NO

☐ Road crossing *(select all that apply)* ○ Cased ○ Uncased ○ Bored

☐ Water crossing NO

Specify: ○ ○ se

Name of body of water, if commonly known: _____

Approx. water depth (ft) at the point of the Accident: /_____/ OR ○ Unknown

(select only on) ○ Shoreline/Bank/Marsh crossing

○ Below water, pipe buried below bottom (NOT in bored/drilled crossing)

○ Below water, pipe in bored/drilled crossing

NO ○ Below water, pipe on or above bottom

Is this w et or more in length from high water mark to high water mark? ○ Yes ○ No

If **Offshore**:

B13. A t.) at the point of the Accident: /___/___/,/___/___/___/

B14. O ☐ In State waters

___ _____ k/Tract #: /_____/ Nearest Co _____

☐ On the Outer Continen (OCS) *(select only one)* ○ OCS – Alaska ○ OCS- Atlantic

○ OCS-Gulf of Mexico ○ OCS – Pacific

Specify: Area:_____ Block/Tract #: _____/

B15. *t only one)*

☐ Shoreline/Bank/Marsh crossing or shore approach

☐ Below water, pipe buried or jetted below seabed

☐ Below water, pipe on or above seabed

☐ Splash Zone of riser

☐ Portion of riser outside of Splash Zone, including riser bend

☐ Platform

Reproduction of this form is permitted

PART C – ADDITIONAL FACILITY INFORMATION

C1. Is the pipeline or facility: INTRASTATE

☐ Interstate
☐ Intrastate

C2. reserved

OTHER

C3. I Accident: *(select only one)*

☐ Pipe ⇨ Specify: ○ Pipe Body ○

If Pipe Body: Was this a puddle/ Yes No

C3a. Nominal Pipe Size: /___/___/./___/___/___ C3.b Wall thickness (in): _____

C3c. SMYS (Specified Minimum Yield Strength) of pipe (psi): /___/___/___/,/___/___/___/

C3d. n:_____ OR ○ Unknown

C3e. ⇨ Specify: ○ ERW - High Frequency ○ Single SAW ○ Flash Welded
○ ERW - Low Frequency ○ DSAW ○ Continuous Welded ○ Longitudinal ERW – Unknown Frequency
○ Furnace Butt Welded ○ Spiral Welded ○ Lap Welded ○ Seamless
○ Other, describe: _____

C3f. Pipe manufacturer:_____ OR ○ Unknown

C3g formerly C3.h Pipeline coating type at point of Accident
⇨ Specify: ○ Fusion Bonded Epoxy (FBE) ○ Coal Tar ○ Asphalt ○ Polyolefin ○ Extruded Polyethylene
○ Epoxy other plied Tape ○ Paint ○ Composite ○ None ○ Other, describe: _____

C3h. ○ Yes ○ No ○ Unknown

☐ Weld, i affected zone ⇨ Specify: ○ Pipe Girth Weld ○ Other Butt Weld ○ Fillet Weld
If Pipe Girth Weld is selected, complete items C3a through h above. Are any of the C3b though h values different on either side of the girth weld? ○ Yes ○ No
If Yes, enter the different value(s) below:

C3i. Wall thickness (in): /___/./___/___/___/

C3j. SMYS (Specified Minimum Yield Strength) of pipe (psi): /___/___/___/,/___/___/___/

C3k. _____ OR ○ Unknown

C3l. Pipe Seam ⇨ Specify: ERW - High Frequency ○ Single SAW ○ Flash Welded
○ ERW - Low Frequency ○ DSAW ○ Continuous Welded ○ ERW – Unknown Frequency
○ Furnace Butt Welde Welded ○ Seamless
○ Other, describe: _____

C3m. Pi _____ OR ○ Unknown

C3n. Pip ident
⇨ Specify: ○ Fusion Bonded Epoxy (FBE) ○ Coal Tar ○ Asphalt ○ Polyolef ○
○ Epox Tape ○ Paint ○ Composite ○ None ○ Other, describe: _____
○ No ○ Unknown

☐ Mai ⇨ Butterfly ○ Check ○ Gate ○ Plug ○ Ball ○ Globe ○ Othe _____

C3p. formerly C3.i Mainline valve manufacturer:_____OR ○ Unknown

○ Relief Valve – including thermal and pressure. Report tank relief valves under the Tank/Vessel, Relief Valve
○ Auxiliary or Other Valve – report auxiliary valves on tanks under Tank/Vessel, Appurtenance

☐ Pump, including auxili connections, and equipment, but excluding product drain lines and tubing.

C3q. Type of pump
- ϒ Positive displacement
- ϒ Centrifugal
- ϒ Gear
- ϒ Other (specify): _____

C3r. Type of service
- ϒ Mainline
- ϒ Injection
- ϒ Truck rack (if on te opy)
- ϒ Other (specify):_____

☐ Meter/Prover, including auxiliary piping, connections, and equipment, but excluding product drain lines and tubing.
☐ Scraper/Pig Trap, including auxiliary piping, connections, and equipment, but excluding product drain lines and tubing.
☐ Sump, including auxiliary piping, connections, and equipment, but excluding product drain lines and tubing.

Reproduction of this form is permitted

☐ Filter, Strainer, Separator, including auxiliary piping, connections, and equipment, but excluding product drain lines and tubing.
☐ Repair Sleeve or Clamp
☐ Tapping Equipment
☐ Tap Fitting (stopple, thread-o-ring, weld-o-let, etc.)
☐ Flange Assembly, including Gaskets
☐ Relief Lines and Relief Equipment
☐ Drain Lines
☐ Tubing, including Fittings
C3s. Tubing material
ϒ Stainless steel
ϒ Carbon steel
ϒ Copper
ϒ Other
C3t. Type of tubing
ϒ Rigid
ϒ Flexible
☐ Instrumentation, including Programmable Logic Controllers and Controls
☐ T pecify: ○ Single Bottom System ○ Double Bottom System ○ Tank Shell ○ Chime ○ Roof/Roof Seal
○ Roof Drain System ○ Mixer ○ Pr or Wall ○ Appurtenance
○ Relief Valve ○ Other, describe: _____
C3v. for f C2. Tank Type ○ Atmospheric ○ Pressurized
If C3v. = Pressurized:
C3v1. Tank ressure
C3v2. What is the set point of the primary pressure relief device on the tank? _____
C3v3. Did the thermal or pressure relief valve activate? ○ Yes
C3v4. Was the MOP of the tank exceeded? ○ Yes ○ No
If C3v = Atmospheric or Low Pressure:
C3v5. Safe-Fill-Level (in feet) at the time of the accident? _____
C3v6. Was the SafeFill-Level exceeded? ○ Yes ○ No
API_STD_OUT_OF_SERVICE_YEAR API_STD_OUT_OF_SRVC_NONE_IND
C3v7. formerly G1, 14.a Year of most recent API Std 653 Out-of-Service Inspection /___/___/___/___/ OR ○ None
C3v8. formerly G1, 14.b API Std 653 In- ○ No leted
TEMPORARY CHEMICAL INJECTION LINE
☐ Other_____mandatory text field_____
OTHER
2026
C4. Year item involved in Accident was installed: /_____ ○ Unknown
UNKNOWN
C4a. Year item involved in Accident was manufactured: _____ OR ○ Unknown

C5. Material involved in Accident: (*select only one*) CARBON STEEL
☐ Carbon Steel
☐ Material other than Carbon Steel ⇨ Specify: _____
LEAK
C6. Type nvolved: (*select only one*)
☐ I Puncture ⇨ Approx. size: /__/__/__/__/./__/in. (axial) by /__/__/__/__/./__/in. (circumferential)
CONNECTION FAILURE
☐ Select Type: ○ Pinhole ○ Crack ○ Connection Failure ○ Seal or Packing ○ Oth
CONNECTION FAILURE
☐ elect Orient umferential ○ Longitudinal ○ Other _____
Approx. siz _____ _ . (widest opening) by _____ _ length circumferentially or axially)
☐ Overfill or Overflow
☐ Other ⇨ Describe: _____
LEAK

PART D – ADDITIONAL CONSEQUENCE INFORMATION

D1. Wildlife impact: ○ Yes ○ No NO
D1a If Yes, specify all that apply:
☐ Fish/aquatic
☐ Birds
☐ Terrestrial
D2. Soil contamination: ○ Yes ○ No YES
D3. Long term impact assessment performed or planned: ○ Yes ○ No NO
D4. Anticipated remediation: ○ Yes ○ No (not needed) NO
hat apply: GROUNDWATER_REMED_IND
☐ Groundwate Vegetation ☐ Wildlife
D5. ○ Yes ⇨ (*Co elow*) ○ No
NO
D5a. Specify all that apply:
☐ Ocean/Seawater

Reproduction of this form is permitted

☐ Surface

☐ Groundwater NO

NO NO

☐ Private Well ○ Public Water Intake

D5b. Estimated amount released i : / / / /,/ / / /./ / / Barrels

D5c. Name of body of water, if commonly known: ENBRIDGE HOLDINGS (GRAY OAK) LLC

D6. At the location of this Accident, had the pipeline segment or facility been identified as one that "could affect" a High Consequence Area (HCA) as determined in the Operator's Integrity Management Program? ○ Yes ○ No NO

D7. Did the rel occur in one or more High Consequence Area (HCA)? ○ Yes ○ No

NO

D7a. If Y *elect all that apply)*

☐ Commercially Navigable Waterway
Was this HCA identified in the "could affect" determination for this Accident site in the Operator's Integrity Management Program?
○ Yes ○ No

☐ High Population Area
Was this HCA identified in the "could affect" determination for this Accident site in the Operator's Integrity Management Program?
○ Yes ○ No

☐ Other Populated Area
Was this HCA identified in the "could affect" determination for this Accident site in the Operator's Integrity Management Program?
○ Yes ○ No

☐ Unusually Sensitive Area (USA) – Drinking Water
Was this HCA identified in the "could affect" determination for this Accident site in the Operator's Integrity Management Program?
○ Yes ○ No

☐ Unusually Sensitive Area (USA) – Ecological
Was this HCA identified in the "could affect" determination for this Accident site in the Operator's Integrity Management Program?
○ Yes ○ No

D8. Estimated Property Damage:

D8a. Estimated cost of public and non-Operator private property damage $ / / 0 / / /

D8b. Estimated cost of commodity lost $ / / 141 / / /

D8c. Estimated cost of Operator's property damage & repairs $ / / 0 / / /

D8d. Estimated cost of emergency response $ / / / 1500 / / /

D8e. Estimated cost of environmental remediation $ / / / /,/ / / /,/ / / / 65000

D8f. Estimated other costs $ / / / /, 0 / / /

Describe 0

D8g. Total estimated property damage (sum of above) 66641 $ *calculated*

Injured Persons not included in A11 The number of persons injured, admitted to a hospital, and remaining in the hospital for at least one overnight are reported in A11. ***If a person is included in A11, do not include them in D9.***

0

D9. injuries requiring treatment in a medical facility but not requiring overnight in-patient hospitalization:

<u>If a person is included in D9, do not include them in D10.</u>

0 0

D10. Es injuries requiring treatment by EMTs at the site of accident:

Buildings Affected

0

D11. Numbe (evacuated or required repair):

0

D12. Numb (evacuated or required repair):

PART E – ADDITIONAL OPERATING INFORMATION	

Reproduction of this form is permitted

E1. Estimated pressure at the point and time of the Accident (psig): 353 / / /,/ / / /

If C3. Is Tank/Vessel and C3v. is Atmospheric, do not answer E2. and E3.

E2. Maximum Operating P COMPONENT DESIGN PRESSURE §195.406(A)(2) the point and time of the Accident (psig): 1480 / / /,/ / / /

E2a. Limiting fa OP (select only one):

- ○ Internal Design Pressure §195.406(a)(1)
- ○ Component Design Pressure §195.406(a)(2)
- ○ SubPart E Pressure Test §195.406(a)(3)
- ○ Excepted Component Pressure Test §195.406(a)(4)
- ○ Four Hour Test or Operation §195.406(a)(5)
- ○ Other; describe: COMPONENT DESIGN PRESSURE §195.406(A)(2)

E2b. Date MOP established 9/17/2019 NO

E2c. Was the MOP establishe tion? ○ Yes ○ No ○ Bi-Directional

If E2c = Yes, E2d. What is the date of the most recent surge analysis performed at the point of the Accident? _____

E3. Describe the pressure on the system or facility relating to the Accident: *(calculated)* PRESSURE DID NOT EXCEED MOP

- ☐ Pressure did not exceed MOP
- ☐ Pressure exceeded MOP, but did not exceed 110% of MOP
- ☐ Pressure exceeded 110% of MOP

NO

E4. Wa ting to the Accident operating under an established pressure restriction with pressure limits below those normally allowed by the MOP?

- ☐ No
- ☐ Yes ⇨ *(Complete 4.a and 4.b below)*

E4a. Did the pressure exceed this estab n? ○ Yes ○ No

E4b. Was this pressure restriction mand tate? ○ PHMSA ○ State ○ Not mandated

If A14. is "Onshore Pipeline, Including Valve Sites" OR "Offshore Pipeline, Including Riser and Riser Bend", complete E5 through E7

E5. formerly E5.c Answer E5 only when both A23a and A23d are Valve Closure
Length of segm en valves (ft): / / /

E6. formerly E5.d Is t ccommodate internal inspection tools?

- ☐ Yes
- ☐ No ⇨ Which physical features limit tool accommodation? *(select all that apply)*
  - ○ Changes in line pipe diameter
  - ○ Presence of unsuitable mainline valves
  - ○ Tight or mitered pipe bends
  - ○ Other passage restrictions (i.e. unbarred tee's, projecti
  - ○ Extra thick pipe wall (ap tic fl t
  - ○ Other Describe: _____

E7. formerly E5.e For thi l factors which significantly complicate the execution of an internal inspection tool run?

- ☐ No
- ☐ Yes ⇨ Which operational factors complicate execution? *(select all that apply)*
  - ○ Excessive debris or scale, wax, or other wall build-up
  - ○ Low operating pressure(s)
  - ○ Low flow or absence of flow
  - ○ Incompatible commodity
  - ○ Other ⇨ Describe: _____

> 20% SMYS REGULATED TRANSMISSION

E8. formerly E5.f Function of pipeline system: *(select only one)*

- ☐ > 20% SMYS Regulated Transmission
- ☐ ≤ 20% SMYS Regulated Transmission
- ☐ > 20% SMYS Regulated Gathering
- ☐ ≤ 20% SMYS Regulated Gathering

Reproduction of this form is permitted

E9. Was a Superv ta Acquisition (SCADA)-based system in place on the pipeline or facility involved in the Accident?

☐ No

☐ Yes ⇨ E9a. Was it operating at the time of the Accident? ○ Yes ○ No

E9b. Was it fully functional at the time of the Accident? ○ Yes ○ No

E9c. Did SCADA-based information (such as alarm(s), alert(s), event(s), and/or volume calculations) assist with the initial indication of the Accident? ○ Yes ○ No

E9d. Did SCADA-based information (such as alarm(s), alert(s), event(s), and/or volume calculations) assist with the confirmed discovery of the Accident? ○ Yes ○ No

E10. Was a CPM leak detection system in place on the pipeline or facility involved in the Accident?

☐ No

☐ Yes ⇨ E10a. Was it operating at the time of the Accident? ○ Yes ○ No

E10b. Was it fully functional at the time of the Accident? ○ Yes ○ No

E10c. Did CPM leak detection system information (such as alarm(s), alert(s), event(s), and/or volume calculations) assist with the initial indication of the Accident? ○ Yes ○ No

E10d. Did CPM leak detection system information (such as alarm(s), alert(s), event(s), and/or volume calculations) assist nfirmed discovery of the Accident? ○ Yes ○ No

E11. Was an investigation initiated into whether or not the controller(s) or control room issues were the cause of or a contributing factor to the Accident? *(select only one)*

☐ Yes, but the investigation of the control room and/or controller actions has not yet been completed by the Operator *(Supplemental Report required)*

☐ No, the facility was not monitored by a controller(s) at the time of the Accident

☐ No, the Operator did not find that an investigation of the controller(s) actions or control room issues was necessary due to: *(provide an tor did not investigate)*

_____

_____

_____

☐ Yes, specify investigation result(s): *(select all that apply)*

○ Investigation reviewed work schedule rotations, co vice (while working for the Operator) and other factors associated with fatigue

○ Investigation did NOT review continuous hours of service (while working for the Operator) and other factors associated with fatigue *(provide an explanation for why not)*

_____

_____

_____

○ Investigation identified no control room issues

○ Investigation identified no controller issues

○ Investigation identified incorrect controller action or controller error

○ Investigation identified that fa cted the controller(s) involved or impacted the involved controller(s) response

○ Investigation identified incorrect procedures

○ Investigation identified incorrect control room

○ Investigation ide e activities that affected control room operations, procedures, and/or controller response

○ Investigatio ther than those above ⇨ Describe: _____

Reproduction of this form is permitted

PART F – DRUG & ALCOHOL TESTING INFORMATION	

F1. As a result of this Accident, were any under the post-accident drug and alcohol testing requirements of DOT's Drug & Alcohol Testing regulations? NO

O No

O Yes ⇨ F1a. Specify how many were tested: / / /

F1b. Specify how many failed: / / /

F2. As a result of this Accident, were any Operator c nder the post-accident drug and alcohol testing requirements of DOT's Drug & Alcohol Testing regulations? NO

O No

O Yes ⇨ F2a. Specify how many were tested: / / /

F2b. Specify how many failed: / / /

PART G – APPARENT CAUSE	***Select only one box from PART G in the shaded column on the left representing the APPARENT Cause of the Accident, and answer the questions on the right. Describe secondary, contributing, or root causes of the Accident in the narrative (PART H).***

G EQUIPMEN T FAILURE EQUIPMENT FAILURE

*only one **sub-cause** can be picked from shaded left-hand column

☐ **n**

1. Results of visual examination:
   O Localized Pitting O General Corrosion
   O Other _____

2. Type of corrosion: *(select all that apply)*
   GALVANIC_CORROSION_IND ATMOSPHERE_CORROSION_IND STRAY_CURRENT_CORROSION_IND MICROBIOLOGICAL_CORROSION_IND SELECTIVE_SEAM_CORROSION_IND
   O Galvanic ray al O Selective Seam
   O Other _____

2a. If 2 is y O Alternat urrent AND
2b. Describe the stray current source: _____

3. The type(s) of corrosion selected in Question 2 is based on the following: *(select all that apply)*
   O O Det nalysis
   O Other _____

4. Was the failed item buried or submerged?
   O Yes ⇨ 4a. Was failed item considered to be under cathodic protection at the time of the Accident?
   O Yes ⇨ Year protection started:
   O

   4b. Was or disbonding of coating evident at the point of the Accident?
   O Yes O No

   4c. Has one or more Cat y been conducted at the point of the Accident? *(select all that apply)*
   CP_ANNUAL_SURVEY_IND
   O Yes, C cent year condu
   O Yes, Cl t recent year co _____
   OTHER_CP_SURVEY_IND
   O Yes, Other CP Survey ⇨ Most recent year conducted:/_____
   Describe other CP survey _____
   O No

   O No ⇨ 4d. Was the faile ted or painted? O Yes O No

5. Was there obse to the coating or paint in the vicinity of the corrosion?
   O Yes O No O N/A Bare/Ineffectively Coated Pipe

Reproduction of this form is permitted

☐ **Internal Corrosion**	6. Results of visual examination: O Locali al Corrosion O Not cut open O Other _____ 7. Cause of corrosion: *(select all that apply)* INT_CORROSIVE_COMMODITY_IND, INT_WATER_ACID_IND, INT_MICROBIOLOGICAL_IND O Corrosiv O op-out/Acid O Microbiological O O Other _____ , _____ 8. The cause(s) of corrosion selected in Question 7 is based on the following: *(select all that apply)* O Field exa ermi O Other_____ , _____ 9. Location of corrosion: *(select all that* PIPE_LOC_IND INT_DEAD_LEG_IND O Low point in pipe O E O Other_____ 10. Was the commodity treat itors or bioci 11. Was the int ve coating? O Yes O No 12. Were clean r other operations) routinely utilized? O Not ap e pipe O Yes O No 13. Were c inely utilized? O Not applicable - Not mainline pipe O Yes O No

G rce Damage - *only one **sub-cause** can be picked from shaded left-hand column	
☐ **Earth Movement, NOT due to Heavy Rains/Floods**	O Earthquake O O Landslide O Other _____
☐ **Heavy Rains/Floods**	2. /Scouring O Flotation O Mudslide O Other _____
☐ **Lightning**	3. hit O Secondary impact such as resulting nearby fires
☐ **Temperature**	4. Stress O Frost Heave O Frozen Components O Other _____
☐ **High Winds**	
☐ **Tree/Vegetation Root**	
☐ **Snow/Ice impact or Accumulation**	
☐ **Other Natural Force Damage**	5. Describe: _____

Complete the following if any Natural Force Damage sub-cause is selected.

6. Were the natural forces causing the Accident ncti he O No

6a. If Yes, specify: (*select all that apply*)

O Other _____ , _____

G3 ion Damage - *only one **sub-cause** can be picked from shaded left-hand column	
☐ **Excavation Damage by Operator (First Party)**	
☐ **Excavation Damage by Operator's Contractor (Second Party)**	
☐ **Excavation Damage by Third Party**	
☐ **Previous Damage due to Excavation Activity**	

Complete the following if Excavation Damage by Third Party is selected as the sub-cause.

1. Did the Operator get prior notification of the excavation activity? O Yes O No

Reproduction of this form is permitted

1a. If Yes, Notification received from: *(select all that apply)* O One-Call System O Excavator O Contractor O Landowner

1b. Per the primary Accident Investigator results, did State law exempt the excavator from notifying the one-call center?

O Yes O No O Unknown

If yes, answer 1c through 1e.

t one of the following:

O Excavator is exempt

O Activity is exempt and did not exceed the limits of the exemption

O Activity is ex

O Other man

1d. Exempting authority: _____

1e. Exempting criteria: _____

Complete the following mandatory CGA-DIRT Program questions if any Excavation Damage sub-cause is selected.

2. Do you want PHMSA to upload the following information to CGA-DIRT (www.cga-dirt.com)? O Yes O No

3. Right vent occ *ll that apply)*

☐ ify: O tate Highway O County Road O Interstate Highway O Other

☐ ify: O er O Private Business O Private Easement

☐ Pipeline Property/Easement

☐ Power/Transmission Line

☐ Railroad

☐ Dedicated Public Utility Easement

☐ Federal Land NO

☐ Unknown/Other

4 Was the facility part of a Joint Trench? O Yes O No

5. Did this event involve a Cross Bore? O Yes O No

6. Measured Depth from Grade

O Embedded in Concrete/Asphalt Pavement O <18" /46 cm O 18" – 36" /46 cm – 91 cm O > 36" / 91 cm

O Measured depth From Grade_____in/cm

7. Type of excavator: *(select only one)*

O Contractor O County O Developer O Farmer O Municipality O Occupant

O Railroad O State O Utility O Unknown/Other

8. Ty ment: *(select only one)*

O Auger O Backhoe/Trackhoe O Boring O Drilling O Directional Drilling

O Explosives O Farm Equipment O Grader/Scraper O Hand Tools O Milling Equipment

O Probing Device O Trencher O Vacuum Equipment O Bulldozer O Unknown/Other

9. Type of work performed: *(select only one)*

O Agriculture O Cable TV O Curb/Sidewalk O Building Construction O Building Demolition

O Drainage O Driveway O Electric O Engineering/Surveying O Fencing

O Grading O Irrigation O Landscaping O Liquid Pipeline O Milling

O Natural Gas O Pole O Public Transit Authority O Railroad Maintenance O Road Work

O Sewer (Sanitary/Storm) O Site Development O Steam O Storm Drain/Culvert O Street Light

O Telecommunications O Traffic Signal O Traffic Sign O Water O Waterway Improvement

O Data not collected O Unknown/Other

10. Was the One-Call Center notified? O Yes O N on 11

*10a. If Yes, specify ticket number: / / /

Notification Issue

☐ No notification made to the One-Call Center/811

☐ Excavator dug outside area described on ticket
☐ Excavator dug prior to valid start date/time
☐ Excavator dug after valid ticket expired
☐ Excavator provided incorrect notification information

Excavation Issue

☐ Excavator dug prior to verifying marks by test-hole (pothole)
☐ Excavator failed to maintain clearance after verifying marks
☐ Excavator failed to protect/shore/support facilities
☐ Improper backfilling practices
☐ Marks faded or not maintained
☐ Improper excavation practice not listed above

Locating Issue

Facility not marked due to:
☐ Abandoned facility
☐ Incorrect facility records/maps
☐ Locator error
☐ No response from operator/contract locator
☐ Incomplete marks at damage location
☐ Tracer wire issue
☐ Unlocatable Facility

Facility marked inaccurately due to:
☐ Abandoned facility
☐ Incorrect facility records/maps
☐ Locator error
☐ Tracer wire issue

Miscellaneous Root Causes

☐ Deteriorated facility
☐ One Call Center Error
☐ Previous damage
☐ Root Cause not listed (comment required) EQUIPMENT FAILURE _____

_____
_____

G4 - e Force Damage - *only one **sub-cause** can be picked from shaded left-hand column	
☐ **Nearby Industrial, Man-made, or Other Fire/Explosion as Primary Cause of Accident**	
☐ **Damage by Car, Truck, or Other Motorized Vehicle/Equipment NOT Engaged in Excavation**	1. Vehicle/Equipment operated by: *(select only one)* ○ Operator ○ Operator's Contractor ○ Third Party If this sub-section is picked, please complete questions 5-11 below
☐ **Damage by Boats, Barges, Drilling Rigs, or Other Maritime Equipment or Vessels Set Adrift or Which Have Otherwise Lost Their Mooring**	2. Se the following IF an extreme weather e ○ Hurricane ○ Tropical Storm o ○ Other _____
☐ **Routine or Normal Fishing or Other Maritime Activity NOT Engaged in Excavation**	

Reproduction of this form is permitted

☐ **Electrical Arcing from Other Equipment or Facility**	
☐ **Previous Mechanical Damage NOT Related to Excavation**	
☐ **Intentional Damage**	3. Specify: ○ Vandalism ○ Terrorism ○ Theft of transpor heft of equipment ○ Other _____
☐ **Other Outside Force Damage**	4. Describe: _____

Complete the following if Damage by Car, Truck, or Other Motorized Vehicle/Equipment NOT Engaged in Excavation sub-cause is selected.

5. Was the driver of the vehicle or equipment issued one or more citations related to the accident? ○ Yes ○ No ○ Unknown

If 5 is Yes, what was the nature of the citations (select all that apply)

5a. Excessive Speed
5b. Reckless Driving
5c. Driving Under the Infl
ribe: _____

6. ontrol of the vehicle at the time of the collision? ○ Yes ○ No ○ Unknown

7. Esti of the vehicle at the time of impact (miles per hour)?_____or ○ Unknown

8. Typ one) ○ Motorcycle/ATV ○ Passenger Car ○ Small Truck ○ Bus ○ Large Truck

9. Where rom to hit the pipeline facility? (select only one)
○ Roadway ○ Driveway ○ Parking Lot ○ Loading Dock ○ Off-Road

10. Shortest distance from answer in 9. to the damaged pipeline facility (in feet): ._____

11. At the time of the accident, were protections installed to protect the damaged pipeline facility from vehicular damage? ○ Yes ○ No

If 11 is Yes, specify type of protection (s

11a. Bollards/Guard Posts
11b. Barricades – inclu in instructions
11c. Guard Rails
11d. Other, describe: _____

Reproduction of this form is permitted

G5 - Material Failure of Pipe or Weld	**Use this section to report material failures ONLY IF the "Item Involved in Accident" (from PART C, Question 3) is "Pipe" or "Weld."** *Only one **sub-cause** can be picked from shaded left-hand column

1. The sub-cause selected below is based on the following: *(select all that apply)*

☐ Field Examination ☐ Determined by Metallurgical Analysis ☐ Other Analysis_____

☐ Su uspected; Still Under Investigation *(Supplemental Report required)* +

☐ **Design-, Construction-, Installation-, or Fabrication-related**	2. List contributing factors: *(select al* ☐ Fatigue- or Vibration-related: ○ Mechanically-induced pri s during transport of pipe) ○ Mechanical Vibration ○ Pressure-related ○ Thermal ○ _____ ☐ Mecha ☐ Other _____
☐ **Original Manufacturing-related (NOT girth weld or other welds formed in the field)**	
☐ **Environmental Cracking-related**	3. Specify: ○ Stress Corrosion Cracking ○ Sulfide Stress Cracking ○ Hydrogen Stress Cracking ○ Hard Spot ○ Other _____

Complete the following if any Material Failure of Pipe or Weld sub-cause is selected.

4. Additional factors: *(select all that apply)* ○ Dent ○ Gouge ○ Pipe Bend ○ A

○ Laminati kle ○ ○
○ Other _____

Reproduction of this form is permitted

G6 nt Failure - *only one **sub-cause** can be picked from shaded left-hand column

THREADED CONNECTION/COUPLING FAILURE

☐ **Malfunction of Control/Relief Equipment**	1. Specify:) ○ Control Valve ○ Instrumentation ○ ○ Communications ○ Block Valve ○ Check Valve ○ Relief Valve ○ Power Failure ○ Stopple/Control Fitting ○ ESD Syste ○ Other _____
☐ **Pump or Pump-related Equipment**	2. Specify: Seal/Packing Failure ○ Body Failure ○ Crack in Body ○ Appurtenance Failure ○ Other _____
☐ **Threaded Connection/Coupling Failure**	THREADED FITTING 3. Specify: ○ Pipe Nipple Valve Threads ○ Mechanical Coupling ○ Threaded Pipe Collar ○ ○ Other _____
☐ **Non-threaded Connection Failure**	4. Specify: O-Ring Gas ○ eal) or Packing ○ Other _____
☐ **Defective or Loose Tubing or Fitting**	
☐ **Failure of Equipment Body (except Pump), Tank Plate, or other Material**	_____
☐ **Other Equipment Failure**	5. Describe: _____

Complete the following if any Equipment Failure sub-cause is selected.

6. Additional factors that contributed to the equipment failure: *(select all that apply)*
   - ○ Excessive vibration
   - ○ Overpressurization
   - ○ No support or loss of support
   - ○ Manufacturing defect
   - ○ Loss of electricity
   - ○ Improper installation
   - ○ Improper maintenance
   - ○ Mismatched items (different manufacturer for tubing and tubing fittings)
   - ○ Dissimilar metals
   - ○ Breakdown of soft goods due to compatibility issues with transported commodity
   - ○ Valve vault or valve can contributed to the release
   - ○ Alarm/status failure
   - ○ Misalignment
   - ○ Thermal stress
   - ○ Erosion/Abnormal Wear YES
   - ○ Other _____ UNDER INVESTIGATION

Reproduction of this form is permitted

G7 Operation - *only one **sub-cause** can be picked from shaded left-hand column

☐ **Damage by Operator or Operator's Contractor NOT Related to Excavation and NOT due to Motorized Vehicle/Equipment Damage**	
☐ **Tank, Vessel, or Sump/Separator Allowed or Caused to Overfill or Overflow**	1. Specify: Valve misalignment ○ Incorrect reference data/calculation ○ Miscomm te monitoring ○ Other_____
☐ **Valve Left or Placed in Wrong Position, but NOT Resulting in a Tank, Vessel, or Sump/Separator Overflow or Facility Overpressure**	
☐ **Pipeline or Equipment Overpressured**	
☐ **Equipment Not Installed Properly**	
☐ **Wrong Equipment Specified or Installed**	
☐ **Other Incorrect Operation**	2. Describe: _____

Complete the following if any Incorrect Operation sub-cause is selected.

3. Was this Accident related to: *(select all that apply)*
   - ○ Inadequate procedure
   - ○ No procedure established
   - ○ Failure to follow p
   - ○ Other: _____

4. What category type was the activity that caused the Accident:
   - ○ Construction
   - ○ Commissioning
   - ○ Decommissioning
   - ○ Right-of-Way activities
   - ○ Routine maintenance
   - ○ Other maintenance
   - ○ Normal operating conditions
   - ○ ns (abnormal operations or emergencies)

5. Was the task(s) that led to the Accident identified as a covered task in your Operator Qualification Program? ○ Yes ○ No

   5a. If Yes, were the individuals performing the task(s) qualified for the task(s)?
   - ○ Yes, they were qualified for the task(s)
   - ○ No, but they were performing the task(s) under the direction and observation of a qualified individual
   - ○ No, they were not qualified for the task(s) nor were they performing the task(s) under the direction and observation of a qualified individual

G8 – Other Accident Cause - *only one **sub-cause** can be picked from shaded left-hand column

☐ **Miscellaneous**	1. Describe: _____
☐ **Unknown**	2. Specify: ○ Investigation complete, cause of Accident comment field: _____ ○ Still under investigation, cause of Accident to be determined* *(*Supplemental Report required)*

PART J – COMPLETED INTEGRITY INSPECTIONS	Formerly at multiple locations in Part G

Reproduction of this form is permitted

Complete the following if the "Item Involved in Accident" (from PART C, Question 3) is Pipe or Weld and the "Cause" (from Part G) is:
Corrosion (any subCause in Part G1); or
Previous Damage due to Excavation Activity (subCause in Part G3); or
Previous Mechanical Damage NOT Related to Excavation (subCause in Part G4); or
Materi Weld (any subCause in Part G5)

J1. Have internal inspection tools collected data at the point of the Accident?
O Yes O No

J1a. If Yes, for each tool and technology used provide the information below for the most recent and previous tool runs:

O Axial Magnetic Flux Leakage
Most recent run Year: _____
Most recent run Propu ethered
Most recent run Attune O Metal Loss O Hard Spots O Girth Weld Anomalies
O Other Describe: _____
If Met e): O High Resolution O Standard Resolution
O Other Describe: _____
Previous run Year: _____
Previous run Propulsion Method (select only one): O Free Swimming O Tethered
Previous run At ne): O Metal Loss O Hard Spots O Girth Weld Anomalies
O Other Describe: _____
If Me ne): O High Resolution O Standard Resolution
O Other Describe: _____

O Circumferential/Transverse kage
Most recent run Year: _____
Most recent run Propulsion Method (select only one): O Free Swimming O Tethered
Most ct only one): O High Resolution O Standard Resolution
O Other Describe: _____
Previous run Year: _____
Previous run Propulsion Method (select only one): O Free Swimming O Tethered
Previo ly one): O High Resolution O Standard Resolution
O Other Describe: _____

O Ultrasonic
Most recent run Year: _____
Most recent run Propulsion Method (select only on
Most rece O Wall Measurement O Crack
O Other Describe: _____
If Attuned tal Loss Resolution (select only one):
O Standard Resolution O Other Describe: _____
Previous run Year: _____
Previous run Propulsion Method (select only one): Free Swimming Tethered
Mos O Wall Measurement O Crack
O Other Describe: _____
If Att al Loss Resolution (select only one):
O Standard Resolution O Other Describe: _____

O Geometry/Deformation
Most recent run Year: _____
Most recent run Propulsion Method (select only one): O Free Swimming O Tethered
Mos t only one): O High Resolution O Standard Resolution
O Other Describe: _____
Mos s (select only one): O Inside ILI Cups O No Cups
Previous run Year: _____
Previous run Propulsion Method (select only one): O Free Swimming O Tethered
Previ y one): O High Resolution O Standard Resolution
O Other Describe: _____
Previ elect only one): O Inside ILI Cups O No Cups

Reproduction of this form is permitted

○ Electromagnetic Acoustic Tr
Most recent run Year: _____
Most recent run Propulsion Method (select only one): ○ Free Swimming ○ Tethered
Previous run Year: _____
Previous run Propulsion Method (select only one): ○ Free Swimming ○ Tethered

○ Cathodic Protection Current Measurement (CPCM)
Most recent run Year: _____
Most recent run Prop only one): ○ Free Swimming ○ Tethered
Previous run Year: _____
Previous run Propulsion Method (select only one): ○ Free Swimming ○ Tethered

○ Other, specify tool: _____
Most recent run Year: _____
Most recent run Propulsion Method (select only one): Free Swimming Tethered
Previous run Year: _____
Previous run Propulsion Method (select only one): ○ Free Swimming ○ Tethered

Answer J1.b only when the cause is:
Previous Damage due to Excavation Activity (subCause in Part G3); or
Previous Mechanical Damage NOT Related to Excavation (subCause in Part G4)

J1b. Do you have reason to believe that the internal inspection was completed BEFORE the damage was sustained? ○ Yes ○ No

J2. Has one or more hydrotest or other pressure test been conducted since original construction at the point of the Accident?
(initial po reported here)

○ Yes ⇨ Most recent year tested: _____ est pressure (psig): /___/___/___/___/___/
○ No

J3. Has Direct Asses the pipeline segment?
○ Yes, and an investigative dig was conducted at the point of the Accident ⇨ Most recent year conducted: /___/___/___/___/
○ Yes, but the point of the Accident was not identified as a dig site ⇨ Most recent year c
○ No
If J3 is Yes, J3a. For each type, indicate the year of the most recent assessment:
External Corrosion Dir DA) /___/___/___/___/
_____ /___/___/___/___/

J4. structive examination been conducted prior to the Accident at the point of the Accident since January 1, 2002?
○ Yes ○ No

J4a. If Yes, for each examination conducted, select typ tion and indicate most recent year the examination was conducted:

○ Radiography /___/___/___/___/ ,
○ Guided Wave Ultrasonic /___/___/___/___/ ,
○ Handheld Ultrasonic Tool /___/___/___/___/ ,
○ Wet Magnetic Particle Test /___/___/___/___/ ,
○ Dry Magnetic Particle /___/___/___/___/ ,
○ Other, specify type _____ /___/___/___/___/ ,

PART K – CONTRIBUTING FACTORS

The Apparent Cause of the accident is contained in Part G. Do not report the Apparent Cause again in this Part K. If Contributing Factors were identified during a root cause analysis, select all that apply below and explain each in the Narrative:

External Corrosion
- ☐ External Corrosion, Galv
- ☐ External Corrosion, Atm
- ☐ External Corrosion, Stra
- ☐ External Corrosion, Micr
- ☐ External Corrosion, Sele

Internal Corrosion
- ☐ Internal Corrosion, Corro
- ☐ Internal Corrosion, Wate
- ☐ Internal Corrosion, Micro
- ☐ Internal Corrosion, Erosion

Pipe/Weld Failure
- ☐ Design-related
- ☐ Construction-related
- ☐ Installation-related
- ☐ Fabrication-related
- ☐ Original Manufacturing-related
- ☐ Environmental Cracking-related PWF_ENV_STRESS_CORROSION_IN
- ☐ Environmental Cracking-related, Sulfide Stress Cracking PWF_ENV_SULFIDE_STRESS_IND
- ☐ Environmental Cracking-related, Hydrogen Stress Cracking PWF_ENV_HYDROGEN_STRESS_IND
- ☐ Environmental Crackin

Reproduction of this form is permitted

Natural Forces ☐ Earth Movement, NOT due to Heavy Rains/Floods ☐ Heavy Rains/Floods ☐ Lightning ☐ Temperature ☐ High Winds ☐ Tree/Vegetation Root Excavation Damage ☐ Excavation Dama ☐ Excavation Damage by Operat ☐ Excavation Damage by Thir ☐ Previous Damage due to Ex Other Outside Force ☐ Nearby Industrial, Man-ma ☐ Damage by Car, Truck, or Other Motorized Vehicl NOT Engaged in Excavation ☐ Damage by Boats, Barges, Drilling R drift Maritime Equipment ☐ Routine or Normal Fishing or Ot Engaged in Excavation ☐ Electrical Arcing from Other E ☐ Previous Mechanical Damage NO ☐	Equipment Failure ☐ Malfunction of Control/Relief Equ ☐ Pump or Pump-related Equipme ☐ Threaded Connection/Coupling Fail ☐ Non-threaded Connection Failure ☐ Defective or Loose Tubing or Fitting ☐ Failure of Equipment B Vessel Plate, or other Material Incorrect Operation ☐ Damage by Operator Excavation and NOT Vehicle/Equipment Damage ☐ Tank, Vessel, or Sump/Separator Allow rfill or Overflow ☐ Valve Left or Placed in Wrong Position, but NOT Resulting in Overpressure ☐ Pipeline or Equi ☐ Equipment Not Installed Properly ☐ Wrong Equipment Specified or In ☐ Inadequate Procedure ☐ No procedure established ☐ Failure to follow procedures

Reproduction of this form is permitted

PART H – NARRATIVE DESCRIPTION OF THE ACCIDENT

ON FEBRUARY 27, 2026, AT APPROXIMATELY 8:35 AM CST, A VENDOR WAS PERFORMING CHEMICAL INJECTION ON LINE 1008 AT THE CENTRAL JUNCTION TERMINAL WHEN A FITTING ON THE VENDOR S CHEMICAL INJECTION LINE FAILED. THIS FAILURE RESULTED IN AN ESTIMATED RELEASE OF 1.5 BARRELS OF CRUDE OIL OUTSIDE OF PRIMARY CONTAINMENT. LOCAL OPERATING PERSONNEL ONSITE ISOLATED THE VENDOR S EQUIPMENT AND NOTIFIED REGION MANAGEMENT. THE TEX

PART I – PREPARER AND AUTHORIZED SIGNATURE

Preparer's Name (type or print)	STACY SOINE ENBRIDGE HOLDINGS (GRAY OAK) LLC		7153953620 Preparer's Telephone Number
Preparer's Title (type or print)	ADVISOR REGULATORY COMPLIANCE		
Preparer's E-mail Address	stacy.soine@enbridge.com		Preparer's Facsimile Number
Local Contact Name: optional Local Contact Email: optional Local Contact Phone: optional	ENBRIDGE HOLDINGS (GRAY OAK) LLC		
Authorized Signer's Name	LUKE SCHOENECKER ENBRIDGE HOLDINGS (GRAY OAK) LLC	3/26/2026 Date	7153941584 Authorized Signer Telephone Number
Authorized Signer's Title	SUPERVISOR REGULATORY COMPLIANCE		luke.schoenecker@enbridge.com Authorized Signer's E-mail Address

Note: Field names not on the form are as following:

Field Name	Field Name Description
2026	*Year accident occurred, derived from accident date*
	The fieldname was used in Rev 7-2014 for "Weld, including heat affected zone Other" and removed from Rev 3-2021

Reproduction of this form is permitted