

BridgeSummaryReport

State Name(1): 28 - Mississippi		StructureNumber(8): 21000900240494A		InspectionDate(90): July 2008	
Identificationand Location			ConditionRatingand Evaluation		
HighwayAgencyDistrict(2): 06 - District6			BridgeRailings(36A): 1 - Meetscurrentlyacceptablestandards		
CountyName(3): 047 - HarrisonCounty			Transitions(36B): 1 - Meetscurrentlyacceptablestandards		
Place Code(4): 6220			ApproachGuardrail(36C): 1 - Meetscurrentlyacceptablestandards		
Features Intersected(6A): BILOXI BAY			BridgeGuardrailEnds(36D): 1 - Meetscurrentlyacceptablestandard...		
Facility Carried By Structure(7): US 90			Deck ConditionRating(58): 8 - Very GoodCondition		
Location(9): HARRISON/JACKSON CL			SuperstructureConditionRating(59): 8 - Very GoodCondition		
MilePoint, miles(11): 28.794			SubstructureConditionRating(60): 8 - Very GoodCondition		
Latitude,decimal(16): 30.392769			Channel and Channel ProtectionConditionRating(61): 9 - Channel pr ...		
Longitude,decimal(17): -88.87357			CulvertsConditionRating(62): N - Nota culvert		
MaintenanceResponsibility(21): 1 - State HighwayAgency			StructuralEvaluationAppraisal(67): 8 - Equal to Present Desirable...		
Owner(22): 1 - State HighwayAgency			Deck GeometryAppraisal(68): 9 - Superiorto Present DesirableCrit ...		
Year Built(27): 2008			UnderclearanceAppraisalVerticaland Horizontal(69): N - N/A		
HistoricalSignificanceCode(37): 5 - NotNationalRegister eligible			WaterwayAdequacyAppraisal(71): 9 - Superiorto Present Desirable...		
NeighboringState Code(98A):			ApproachAlignmentAppraisal(72): 7 - BetterThan Present MinimumC ...		
NeighboringState Percent Responsibility(98B):			Scour CriticalBridgesCode(113): 8 - Foundationsstable; Scour abo ...		
BorderBridgeStructureNumber(99): _			BridgeCondition(CAT10): G - Good		
Parallel StructureDesignationCode(101): L - Left of set in opposed ...			Load Ratingand Posting		
Year Reconstructed(106): 0			DesignLoad Descriptor(31): 5 - MS 18 / HS 20		
StructureType and Materials			StructureOperationaStatus Code(41): A - Open		
MainSpan Material(43A): 6 - Prestressed ConcreteContinuous			OperatingRatingMethodCode(63): 1 - Load Factor(LF)		
MainSpan Design(43B): 2 - Stringer/MultiBeamor Girder			OperatingRating, US tons(64): 60.6		
ApproachSpans Material(44A): 6 - Prestressed ConcreteContinuous			InventoryRatingMethodCode(65): 1 - Load Factor(LF)		
ApproachSpans Design(44B): 2 - Stringer/MultiBeamor Girder			InventoryRating, US tons(66): 36.4		
Numberof Spans in MainUnit(45): 1			BridgePostingCode(70): 5 - Equal to or above legal loads		
Numberof ApproachSpans(46): 70			Trafficand Roadway Data		
Deck StructureType Code(107): 1 - ConcreteCast-in-Place			Record Type(5A): 1 - On Structure		
WearingSurface Type Code(108A): 1 - MonolithiConcrete			Route SigningPrefix Code(5B): 2 - U.S. numberedhighway		
MembraneType Code(108B): 0 - None			DesignatedLevel of Service Code(5C): 1 - Mainline		
Deck ProtectionCode(108C): 0 - None			Route Number(5D): 00090		
Dimensionsand Clearances			DirectionaSuffix Code(5E): 0 - NotApplicable		
InventoryRoute - MinimumVerticalClearance, ft. (10): 327.7			Base HighwayNetwork(12): 1 - On Base Network		
ApproachRoadway Width,ft. (32): 57.1			Bypass or DetourLength,miles(19): "1"		
BridgeMedianCode(33): 3 - Closed MedianNon-MountableBarriers			Toll Status(20): 3 - On Free Road		
Skew Angle,degrees(34): 0			FunctionalClass Of InventoryRoute(26): 14 - UrbanOtherPrincipal...		
StructureFlared(35): 0 - No flare			Lanes On the Structure(28A): 3		
NavigationControlCode(38): 1 - PermitRequired			Lanes Underthe Structure(28B): 0		
NavigationVerticalClearance, ft. (39): 95.8			AverageDaily Traffic(29): 13,000		
NavigationHorizontalClearance, ft. (40): 149.9			Year of AverageDaily Traffic(30): 2006		
InventoryRoute Total HorizontalClearance, ft. (47): 57.1			Type of Service on BridgeCode(42A): 1 - Highway		
Lengthof MaximumSpan, ft. (48): 250			Type Of Service UnderBridgeCode(42B): 5 - Waterway		
StructureLength,ft. (49): 8765.7			STRAHNET HighwayDesignation(100): 0 - NotSTRAHNET		
Left Curb/SidewalkWidth,ft. (50A): 0			Directionof Traffic Code(102): 1 - 1 - way traffic		
RightCurb/SidewalkWidth,ft. (50B): 0			InventoryRoute NHS Code(104): 1 - On NHS		
BridgeRoadway WidthCurb to Curb, ft. (51): 57.1			Federal Lands HighwaysCode(105): 0 - N/A		
Deck Width- Outto Out, ft. (52): 60			AverageDaily Truck Traffic (Percent ADT)(109): 13		
MinimumVerticalClearance Over BridgeRoadway, ft. (53): 327.8			DesignatedNationalTruck NetworkCode(110): 1 - On NationalTruck ...		
MinimumVerticalUnderclearance,ft. (54B): "000"			Future AverageDaily Traffic(114): 19,500		
MinimumLateral Underclearanceon Right, ft. (55B): 0			Year of Future AverageDaily Traffic(115): 2026		
MinimumLateral Underclearanceon Left, ft. (56): "000"			MPO, Political Districts, and Cities		
Pier AbutmentProtectionCode(111): 1 - Notrequired			MetropolitaPlanningOrganization(MPO):		
MinimumVerticalClearance - Lift Bridge,ft. (116):			U.S. CongressionalDistrict:		
Deck Area, sq. ft. (CAT29): 526289.5			State Senate District:		
Inspection			State House District:		
InspectionDate(90): July 2008			City (InfoBridgePlace Code-Name):		
DesignatedInspectionFrequency(91): 24					
Fracture CriticalDetails(92A): N00					
UnderwaterInspection(92B): Y60					
OtherSpecial Inspection(92C): N00					
Fracture CriticalDetailDate(93A):					
UnderwaterInspectionDate(93B): January 2000					
OtherSpecial InspectionDate(93C):					