

BridgeSummaryReport

State Name(1): 28 - Mississippi		StructureNumber(8): 21000900240494A		InspectionDate(90): July 2012	
Identificationand Location			ConditionRatingand Evaluation		
HighwayAgencyDistrict(2): 06 - District6			BridgeRailings (36A): 0 - Does notmeetcurrentlyacceptablestanda...		
CountyName(3): 047 - HarrisonCounty			Transitions(36B): 1 - Meetscurrentlyacceptablestandards		
Place Code (4): 6220			ApproachGuardrail(36C): 1 - Meetscurrentlyacceptablestandards		
Features Intersected(6A): BILOXI BAY			BridgeGuardrailEnds (36D): 1 - Meetscurrentlyacceptablestandard...		
Facility Carried By Structure(7): US 90			Deck ConditionRating (58): 8 - Very Good Condition		
Location(9): HARRISON/JACKSON CL			SuperstructureConditionRating(59): 7 - Good Condition		
MilePoint, miles (11): 0			SubstructureConditionRating (60): 7 - Good Condition		
Latitude,decimal(16): 30.411089			Channel and Channel ProtectionConditionRating(61): 7 - Channel re ...		
Longitude,decimal(17): -88.841064			CulvertsConditionRating (62): N - Nota culvert		
MaintenanceResponsibility(21): 1 - State HighwayAgency			StructuralEvaluationAppraisal(67): 7 - BetterThan Present Minim...		
Owner(22): 1 - State HighwayAgency			Deck GeometryAppraisal(68): 9 - Superiorto Present DesirableCrit ...		
Year Built(27): 2008			UnderclearanceAppraisalVerticaland Horizontal(69): N - N/A		
HistoricalSignificanceCode (37): 5 - NotNationalRegister eligible			WaterwayAdequacyAppraisal(71): 9 - Superiorto Present Desirable...		
NeighboringState Code (98A):			ApproachAlignmentAppraisal(72): 7 - BetterThan Present MinimumC ...		
NeighboringState Percent Responsibility(98B):			Scour CriticalBridgesCode (113): 8 - Foundationsstable; Scour abo ...		
BorderBridgeStructureNumber(99):			BridgeCondition(CAT10): G - Good		
Parallel StructureDesignationCode (101): L - Left of set in opposited ...			Load Ratingand Posting		
Year Reconstructed(106): 0			DesignLoad Descriptor(31): 5 - MS 18 / HS 20		
StructureType and Materials			StructureOperationaStatus Code (41): A - Open		
MainSpan Material(43A): 6 - Prestressed ConcreteContinuous			OperatingRating MethodCode (63): 1 - Load Factor(LF)		
MainSpan Design(43B): 2 - Stringer/MultiBeamor Girder			OperatingRating, US tons (64): 60.6		
ApproachSpans Material(44A): 6 - Prestressed ConcreteContinuous			InventoryRating MethodCode (65): 1 - Load Factor(LF)		
ApproachSpans Design(44B): 2 - Stringer/MultiBeamor Girder			InventoryRating, US tons(66): 36.4		
Numberof Spans in MainUnit(45): 1			BridgePostingCode (70): 5 - Equal to or above legal loads		
Numberof ApproachSpans (46): 70			Trafficand Roadway Data		
Deck StructureType Code (107): 1 - ConcreteCast-in-Place			Record Type (5A): 1 - On Structure		
WearingSurface Type Code (108A): 0 - None			Route SigningPrefix Code (5B): 2 - U.S. numberedhighway		
MembraneType Code (108B): 0 - None			DesignatedLevel of Service Code (5C): 1 - Mainline		
Deck ProtectionCode (108C): 0 - None			Route Number(5D): 00090		
Dimensionsand Clearances			DirectionaSuffixCode (5E): 0 - NotApplicable		
InventoryRoute - MinimumVerticalClearance, ft. (10): 327.7			Base HighwayNetwork(12): 1 - On Base Network		
ApproachRoadway Width,ft. (32): 57.1			Bypass or DetourLength,miles (19): "1"		
BridgeMedianCode (33): 3 - Closed MedianNon-MountableBarriers			Toll Status (20): 3 - On Free Road		
Skew Angle,degrees(34): 0			FunctionalClass Of InventoryRoute (26): 14 - UrbanOtherPrincipal...		
StructureFlared (35): 0 - No flare			Lanes On the Structure(28A): 3		
NavigationControlCode (38): 1 - PermitRequired			Lanes Underthe Structure(28B): 0		
NavigationVerticalClearance, ft. (39): 95.8			AverageDaily Traffic (29): 13,000		
NavigationHorizontalClearance, ft. (40): 149.9			Year of AverageDaily Traffic (30): 2011		
InventoryRoute Total HorizontalClearance, ft. (47): 57.1			Type of Service on BridgeCode (42A): 1 - Highway		
Lengthof MaximumSpan, ft. (48): 250			Type Of Service UnderBridgeCode (42B): 5 - Waterway		
StructureLength,ft. (49): 8765.7			STRAHNET HighwayDesignation(100): 0 - NotSTRAHNET		
LeftCurb/SidewalkWidth,ft. (50A): 0			Directionof Traffic Code (102): 1 - 1 - way traffic		
RightCurb/SidewalkWidth,ft. (50B): 0			InventoryRoute NHS Code (104): 1 - On NHS		
BridgeRoadway WidthCurb to Curb, ft. (51): 57.1			Federal Lands HighwaysCode (105): 0 - N/A		
Deck Width- Outto Out, ft. (52): 60			AverageDaily Truck Traffic (Percent ADT) (109): 13		
MinimumVerticalClearance Over BridgeRoadway, ft. (53): 327.8			DesignatedNationalTruck NetworkCode (110): 1 - On NationalTruck ...		
MinimumVerticalUnderclearance,ft. (54B): "000"			Future AverageDaily Traffic (114): 19,500		
MinimumLateral Underclearanceon Right, ft. (55B): 0			Year of Future AverageDaily Traffic (115): 2032		
MinimumLateral Underclearanceon Left, ft. (56): "000"			MPO, Political Districts, and Cities		
Pier AbutmentProtectionCode (111): 1 - Notrequired			MetropolitanPlanningOrganization(MPO):		
MinimumVerticalClearance - Lift Bridge,ft. (116):			U.S. CongressionalDistrict:		
Deck Area, sq. ft. (CAT29): 526289.5			State Senate District:		
Inspection			State House District:		
InspectionDate (90): July 2012			City (InfoBridgePlace Code-Name):		
DesignatedInspectionFrequency(91): 24					
Fracture CriticalDetails(92A): N Notneeded					
UnderwaterInspection(92B): Y60					
OtherSpecial Inspection(92C): N					
Fracture CriticalDetailDate (93A):					
UnderwaterInspectionDate (93B): April2009					
OtherSpecial InspectionDate (93C):					