

BridgeSummaryReport

State Name(1): 28 - Mississippi

StructureNumber(8): 21000900240494A

InspectionDate(90): July 2014

| Identificationand Location                                               | ConditionRatingand Evaluation                                        |
|--------------------------------------------------------------------------|----------------------------------------------------------------------|
| HighwayAgencyDistrict(2): 06 - District6                                 | BridgeRailings(36A): 0 - Does notmeetcurrentlyacceptablestanda...    |
| CountyName(3): 047 - HarrisonCounty                                      | Transitions(36B): 0 - Does notmeetcurrentlyacceptablestandards       |
| Place Code(4): 6220                                                      | ApproachGuardrail(36C): 1 - Meetscurrentlyacceptablestandards        |
| Features Intersected(6A): BILOXI BAY                                     | BridgeGuardrailEnds(36D): 1 - Meetscurrentlyacceptablestandard...    |
| Facility Carried By Structure(7): US 90                                  | Deck ConditionRating(58): 8 - Very Good Condition                    |
| Location(9): HARRISON/JACKSON CL                                         | SuperstructureConditionRating(59): 7 - Good Condition                |
| MilePoint, miles(11): 0                                                  | SubstructureConditionRating(60): 7 - Good Condition                  |
| Latitude,decimal(16): 30.411089                                          | Channeland Channel ProtectionConditionRating(61): 7 - Channelre ...  |
| Longitude,decimal(17): -88.841064                                        | CulvertsConditionRating(62): N - Nota culvert                        |
| MaintenanceResponsibility(21): 1 - State HighwayAgency                   | StructuralEvaluationAppraisal(67): 7 - BetterThan Present Minimu...  |
| Owner(22): 1 - State HighwayAgency                                       | Deck GeometryAppraisal(68): 9 - Superiorto Present DesirableCrit ... |
| Year Built(27): 2008                                                     | UnderclearanceAppraisalVerticaland Horizontal(69): N - N/A           |
| HistoricalSignificanceCode(37): 5 - NotNationalRegister eligible         | WaterwayAdequacyAppraisal(71): 9 - Superiorto Present Desirable...   |
| NeighboringState Code(98A):                                              | ApproachAlignmentAppraisal(72): 7 - BetterThan Present MinimumC ...  |
| NeighboringState Percent Responsibility(98B):                            | Scour CriticalBridgesCode(113): 8 - Foundationsstable; Scour abo ... |
| BorderBridgeStructureNumber(99):                                         | BridgeCondition(CAT10): G - Good                                     |
| Parallel StructureDesignationCode(101): L - Left of set in opposited ... |                                                                      |
| Year Reconstructed(106): 0                                               |                                                                      |
| StructureTypeand Materials                                               | Load Ratingand Posting                                               |
| MainSpan Material(43A): 6 - Prestressed ConcreteContinuous               | DesignLoad Descriptor(31): 5 - MS 18 / HS 20                         |
| MainSpan Design(43B): 2 - Stringer/MultiBeamor Girder                    | StructureOperationaStatus Code(41): A - Open                         |
| ApproachSpans Material(44A): 6 - Prestressed ConcreteContinuous          | OperatingRating MethodCode(63): 1 - Load Factor(LF)                  |
| ApproachSpans Design(44B): 2 - Stringer/MultiBeamor Girder               | OperatingRating, US tons(64): 60.6                                   |
| Numberof Spans in MainUnit(45): 1                                        | InventoryRating MethodCode(65): 1 - Load Factor(LF)                  |
| Numberof ApproachSpans(46): 70                                           | InventoryRating, US tons(66): 36.4                                   |
| Deck StructureType Code(107): 1 - ConcreteCast-in-Place                  | BridgePostingCode(70): 5 - Equal to or above legal loads             |
| WearingSurface Type Code(108A): 0 - None                                 |                                                                      |
| MembraneType Code(108B): 0 - None                                        |                                                                      |
| Deck ProtectionCode(108C): 0 - None                                      |                                                                      |
| Dimensionsand Clearances                                                 | Trafficand Roadway Data                                              |
| InventoryRoute - MinimumVerticalClearance, ft. (10): 327.7               | Record Type(5A): 1 - On Structure                                    |
| ApproachRoadway Width,ft. (32): 57.1                                     | Route SigningPrefix Code(5B): 2 - U.S. numberedhighway               |
| BridgeMedianCode(33): 3 - Closed MedianNon-MountableBarriers             | DesignatedLevel of Service Code(5C): 1 - Mainline                    |
| Skew Angle,degrees(34): 0                                                | Route Number(5D): 00090                                              |
| StructureFlared(35): 0 - No flare                                        | DirectionaSuffixCode(5E): 0 - NotApplicable                          |
| NavigationControlCode(38): 1 - PermitRequired                            | Base HighwayNetwork(12): 1 - On Base Network                         |
| NavigationVerticalClearance, ft. (39): 95.8                              | Bypass or DetourLength,miles(19): "1"                                |
| NavigationHorizontalClearance, ft. (40): 149.9                           | Toll Status(20): 3 - On Free Road                                    |
| InventoryRoute Total HorizontalClearance, ft. (47): 57.1                 | FunctionalClass Of InventoryRoute(26): 14 - UrbanOtherPrincipal...   |
| Lengthof MaximumSpan, ft. (48): 250                                      | Lanes On the Structure(28A): 3                                       |
| StructureLength,ft. (49): 8765.7                                         | Lanes Underthe Structure(28B): 0                                     |
| LeftCurb/SidewalkWidth,ft. (50A): 0                                      | AverageDaily Traffic(29): 12,500                                     |
| RightCurb/SidewalkWidth,ft. (50B): 0                                     | Year of AverageDaily Traffic(30): 2013                               |
| BridgeRoadway WidthCurb to Curb, ft. (51): 57.1                          | Type of Service on BridgeCode(42A): 1 - Highway                      |
| Deck Width- Outto Out, ft. (52): 60                                      | Type Of Service UnderBridgeCode(42B): 5 - Waterway                   |
| MinimumVerticalClearance Over BridgeRoadway, ft. (53): 327.8             | STRAHNET HighwayDesignation(100): 0 - NotSTRAHNET                    |
| MinimumVerticalUnderclearance,ft. (54B): "000"                           | Directionof Traffic Code(102): 1 - 1 - way traffic                   |
| MinimumLateral Underclearanceon Right, ft. (55B): 0                      | InventoryRoute NHS Code(104): 1 - On NHS                             |
| MinimumLateral Underclearanceon Left, ft. (56): "000"                    | Federal Lands HighwaysCode(105): 0 - N/A                             |
| Pier AbutmentProtectionCode(111): 1 - Notrequired                        | AverageDaily Truck Traffic (Percent ADT)(109): 13                    |
| MinimumVerticalClearance - LiftBridge,ft. (116):                         | DesignatedNationalTruck NetworkCode(110): 1 - On NationalTruck ...   |
| Deck Area, sq. ft. (CAT29): 526289.5                                     | Future AverageDaily Traffic(114): 18,750                             |
| Inspection                                                               | Year of Future AverageDaily Traffic(115): 2033                       |
| InspectionDate(90): July 2014                                            |                                                                      |
| DesignatedInspectionFrequency(91): 24                                    |                                                                      |
| Fracture CriticalDetails(92A): N Notneeded                               |                                                                      |
| UnderwaterInspection(92B): Y60                                           |                                                                      |
| OtherSpecial Inspection(92C): N                                          |                                                                      |
| Fracture CriticalDetailDate(93A):                                        |                                                                      |
| UnderwaterInspectionDate(93B): April2014                                 |                                                                      |
| OtherSpecial InspectionDate(93C):                                        |                                                                      |