

BridgeSummaryReport

State Name(1): 28 - Mississippi

StructureNumber(8): 21000900240494A

InspectionDate(90): July 2014

Identificationand Location	ConditionRatingand Evaluation
HighwayAgencyDistrict(2): 06 - District6	BridgeRailings (36A): 0 - Does notmeetcurrentlyacceptablestanda...
CountyName(3): 047 - HarrisonCounty	Transitions(36B): 0 - Does notmeetcurrentlyacceptablestandards
Place Code (4): 6220	ApproachGuardrail(36C): 1 - Meetscurrentlyacceptablestandards
Features Intersected(6A): BILOXI BAY	BridgeGuardrailEnds (36D): 1 - Meetscurrentlyacceptablestandard...
Facility Carried By Structure(7): US 90	Deck ConditionRating (58): 8 - Very Good Condition
Location(9): HARRISON/JACKSON CL	SuperstructureConditionRating (59): 7 - Good Condition
MilePoint, miles (11): 0	SubstructureConditionRating (60): 7 - Good Condition
Latitude,decimal(16): 30.41109	Channeland Channel ProtectionConditionRating (61): 7 - Channel re ...
Longitude,decimal(17): -88.84106	CulvertsConditionRating (62): N - Nota culvert
MaintenanceResponsibility(21): 1 - State HighwayAgency	StructuralEvaluationAppraisal(67): 7 - BetterThan Present Minimu...
Owner(22): 1 - State HighwayAgency	Deck GeometryAppraisal(68): 9 - Superiorto Present DesirableCrit ...
Year Built(27): 2008	UnderclearanceAppraisalVerticaland Horizontal(69): N - N/A
HistoricalSignificanceCode (37): 5 - NotNationalRegister eligible	WaterwayAdequacyAppraisal(71): 9 - Superiorto Present Desirable...
NeighboringState Code (98A):	ApproachAlignmentAppraisal(72): 7 - BetterThan Present MinimumC ...
NeighboringState Percent Responsibility(98B):	Scour CriticalBridgesCode (113): 8 - Foundationsstable; Scour abo ...
BorderBridgeStructureNumber(99):	BridgeCondition(CAT10): G - Good
Parallel StructureDesignationCode (101): L - Left of set in opposited ...	
Year Reconstructed(106): 0	
StructureTypeand Materials	Load Ratingand Posting
MainSpan Material(43A): 6 - Prestressed ConcreteContinuous	DesignLoad Descriptor(31): 5 - MS 18 / HS 20
MainSpan Design(43B): 2 - Stringer/MultiBeamor Girder	StructureOperationaStatus Code (41): A - Open
ApproachSpans Material(44A): 6 - Prestressed ConcreteContinuous	OperatingRating MethodCode (63): 1 - Load Factor(LF)
ApproachSpans Design(44B): 2 - Stringer/MultiBeamor Girder	OperatingRating, US tons (64): 60.6
Numberof Spans in MainUnit(45): 1	InventoryRating MethodCode (65): 1 - Load Factor(LF)
Numberof ApproachSpans (46): 70	InventoryRating, US tons (66): 36.4
Deck StructureType Code (107): 1 - ConcreteCast-in-Place	BridgePostingCode (70): 5 - Equal to or above legal loads
WearingSurface Type Code (108A): 0 - None	
MembraneType Code (108B): 0 - None	
Deck ProtectionCode (108C): 0 - None	
Dimensionsand Clearances	Trafficand Roadway Data
InventoryRoute - MinimumVerticalClearance, ft. (10): "9999"	Record Type (5A): 1 - On Structure
ApproachRoadway Width,ft. (32): 57.1	Route SigningPrefix Code (5B): 2 - U.S. numberedhighway
BridgeMedianCode (33): 3 - Closed MedianNon-MountableBarriers	DesignatedLevel of Service Code (5C): 1 - Mainline
Skew Angle,degrees(34): 0	Route Number(5D): 00090
StructureFlared (35): 0 - No flare	DirectionaSuffixCode (5E): 0 - NotApplicable
NavigationControlCode (38): 1 - PermitRequired	Base HighwayNetwork(12): 1 - On Base Network
NavigationVerticalClearance, ft. (39): 95.8	Bypass or DetourLength,miles (19): 1.2
NavigationHorizontalClearance, ft. (40): 149.9	Toll Status (20): 3 - On Free Road
InventoryRoute Total HorizontalClearance, ft. (47): 57.1	FunctionalClass Of InventoryRoute (26): 14 - UrbanOtherPrincipal...
Lengthof MaximumSpan, ft. (48): 250	Lanes On the Structure(28A): 3
StructureLength,ft. (49): 8765.7	Lanes Underthe Structure(28B): 0
LeftCurb/SidewalkWidth,ft. (50A): 0	AverageDaily Traffic (29): 12,500
RightCurb/SidewalkWidth,ft. (50B): 0	Year of AverageDaily Traffic (30): 2013
BridgeRoadway WidthCurb to Curb, ft. (51): 57.1	Type of Service on BridgeCode (42A): 1 - Highway
Deck Width- Outto Out, ft. (52): 60	Type Of Service UnderBridgeCode (42B): 5 - Waterway
MinimumVerticalClearance Over BridgeRoadway, ft. (53): "9999"	STRAHNET HighwayDesignation(100): 0 - NotSTRAHNET
MinimumVerticalUnderclearance,ft. (54B): "000"	Directionof Traffic Code (102): 1 - 1 - way traffic
MinimumLateral Underclearanceon Right, ft. (55B): 0	InventoryRoute NHS Code (104): 1 - On NHS
MinimumLateral Underclearanceon Left, ft. (56): "000"	Federal Lands HighwaysCode (105): 0 - N/A
Pier AbutmentProtectionCode (111): 1 - Notrequired	AverageDaily Truck Traffic (Percent ADT) (109): 13
MinimumVerticalClearance - Lift Bridge,ft. (116):	DesignatedNationalTruck NetworkCode (110): 1 - On NationalTruck ...
Deck Area, sq. ft. (CAT29): 526289.5	Future AverageDaily Traffic (114): 18,750
Inspection	Year of Future AverageDaily Traffic (115): 2033
InspectionDate (90): July 2014	
DesignatedInspectionFrequency(91): 24	
Fracture CriticalDetails(92A): N Notneeded	
UnderwaterInspection(92B): Y60	
OtherSpecial Inspection(92C): N	
Fracture CriticalDetailDate (93A):	
UnderwaterInspectionDate (93B): April2014	
OtherSpecial InspectionDate (93C):	