

BridgeSummaryReport

State Name(1): 28 - Mississippi		StructureNumber(8): 21000900240494A	InspectionDate(90): July 2018
Identificationand Location		ConditionRatingand Evaluation	
HighwayAgencyDistrict(2): 06 - District6		BridgeRailings(36A): 0 - Does notmeetcurrentlyacceptablestanda...	
CountyName(3): 047 - HarrisonCounty		Transitions(36B): 0 - Does notmeetcurrentlyacceptablestandards	
Place Code(4): 6220		ApproachGuardrail(36C): 1 - Meetscurrentlyacceptablestandards	
Features Intersected(6A): BILOXI BAY		BridgeGuardrailEnds(36D): 1 - Meetscurrentlyacceptablestandard...	
Facility Carried By Structure(7): US 90		Deck ConditionRating(58): 8 - Very Good Condition	
Location(9): HARRISON/JACKSON CL		SuperstructureConditionRating(59): 7 - Good Condition	
MilePoint, miles(11): 0		SubstructureConditionRating(60): 7 - Good Condition	
Latitude,decimal(16): 30.41109		Channeland Channel ProtectionConditionRating(61): 7 - Channel re ...	
Longitude,decimal(17): -88.84106		CulvertsConditionRating(62): N - Nota culvert	
MaintenanceResponsibility(21): 1 - State HighwayAgency		StructuralEvaluationAppraisal(67): 7 - BetterThan Present Minimu...	
Owner(22): 1 - State HighwayAgency		Deck GeometryAppraisal(68): 9 - Superiorto Present DesirableCrit ...	
Year Built(27): 2008		UnderclearanceAppraisalVerticaland Horizontal(69): N - N/A	
HistoricalSignificanceCode(37): 5 - NotNationalRegister eligible		WaterwayAdequacyAppraisal(71): 9 - Superiorto Present Desirable...	
NeighboringState Code(98A):		ApproachAlignmentAppraisal(72): 7 - BetterThan Present MinimumC ...	
NeighboringState Percent Responsibility(98B):		Scour CriticalBridgesCode(113): 8 - Foundationsstable; Scour abo ...	
BorderBridgeStructureNumber(99):		BridgeCondition(CAT10): G - Good	
Parallel StructureDesignationCode(101): L - Left of set in opposited ...		Load Ratingand Posting	
Year Reconstructed(106): 0		DesignLoad Descriptor(31): 5 - MS 18 / HS 20	
StructureType and Materials		StructureOperationaStatus Code(41): A - Open	
MainSpan Material(43A): 6 - Prestressed ConcreteContinuous		OperatingRating MethodCode(63): 1 - Load Factor(LF)	
MainSpan Design(43B): 2 - Stringer/MultiBeamor Girder		OperatingRating, US tons(64): 60.6	
ApproachSpans Material(44A): 6 - Prestressed ConcreteContinuous		InventoryRating MethodCode(65): 1 - Load Factor(LF)	
ApproachSpans Design(44B): 2 - Stringer/MultiBeamor Girder		InventoryRating, US tons(66): 36.4	
Numberof Spans in MainUnit(45): 1		BridgePostingCode(70): 5 - Equal to or above legal loads	
Numberof ApproachSpans(46): 70		Trafficand Roadway Data	
Deck StructureType Code(107): 1 - ConcreteCast-in-Place		Record Type(5A): 1 - On Structure	
WearingSurface Type Code(108A): 0 - None		Route SigningPrefix Code(5B): 2 - U.S. numberedhighway	
MembraneType Code(108B): 0 - None		DesignatedLevel of Service Code(5C): 1 - Mainline	
Deck ProtectionCode(108C): 0 - None		Route Number(5D): 00090	
Dimensionsand Clearances		DirectionaSuffix Code(5E): 0 - NotApplicable	
InventoryRoute - MinimumVerticalClearance, ft. (10): "9999"		Base HighwayNetwork(12): 1 - On Base Network	
ApproachRoadway Width,ft. (32): 57.1		Bypass or DetourLength,miles(19): 1.2	
BridgeMedianCode(33): 3 - Closed MedianNon-MountableBarriers		Toll Status(20): 3 - On Free Road	
Skew Angle,degrees(34): 0		FunctionalClass Of InventoryRoute(26): 14 - UrbanOtherPrincipal...	
StructureFlared(35): 0 - No flare		Lanes On the Structure(28A): 3	
NavigationControlCode(38): 1 - PermitRequired		Lanes Underthe Structure(28B): 0	
NavigationVerticalClearance, ft. (39): 95.8		AverageDaily Traffic(29): 13,000	
NavigationHorizontalClearance, ft. (40): 149.9		Year of AverageDaily Traffic(30): 2018	
InventoryRoute Total HorizontalClearance, ft. (47): 57.1		Type of Service on BridgeCode(42A): 1 - Highway	
Lengthof MaximumSpan, ft. (48): 250		Type Of Service UnderBridgeCode(42B): 5 - Waterway	
StructureLength,ft. (49): 8765.7		STRAHNET HighwayDesignation(100): 0 - NotSTRAHNET	
LeftCurb/SidewalkWidth,ft. (50A): 0		Directionof Traffic Code(102): 1 - 1 - way traffic	
RightCurb/SidewalkWidth,ft. (50B): 0		InventoryRoute NHS Code(104): 1 - On NHS	
BridgeRoadway WidthCurb to Curb, ft. (51): 57.1		Federal Lands HighwaysCode(105): 0 - N/A	
Deck Width- Outto Out, ft. (52): 60		AverageDaily Truck Traffic (Percent ADT) (109): 2	
MinimumVerticalClearance Over BridgeRoadway, ft. (53): "9999"		DesignatedNationalTruck NetworkCode(110): 1 - On NationalTruck ...	
MinimumVerticalUnderclearance,ft. (54B): "000"		Future AverageDaily Traffic(114): 13,000	
MinimumLateral Underclearanceon Right, ft. (55B): 0		Year of Future AverageDaily Traffic(115): 2038	
MinimumLateral Underclearanceon Left, ft. (56): "000"		MPO, Political Districts, and Cities	
Pier AbutmentProtectionCode(111): 1 - Notrequired		MetropolitaPlanningOrganization(MPO):	
MinimumVerticalClearance - Lift Bridge,ft. (116):		U.S. CongressionalDistrict:	
Deck Area, sq. ft. (CAT29): 526289.5		State Senate District:	
Inspection		State House District:	
InspectionDate(90): July 2018		City (InfoBridgePlace Code-Name):	
DesignatedInspectionFrequency(91): 24			
Fracture CriticalDetails(92A): N Notneeded			
UnderwaterInspection(92B): Y60			
OtherSpecial Inspection(92C): N			
Fracture CriticalDetailDate(93A):			
UnderwaterInspectionDate(93B): March2019			
OtherSpecial InspectionDate(93C):			