
Table of Contents

a)

exercise_4_openLoop



b)

c)


```
p.L = 0.23e-3; % [H]
p.cm = 23.4e-3; % [Nm / A]
```


```
p.R = 2.4;
                   % [Ohm]
p.J = 0.23e-6;
                   % [Nm^2]
p.D = 0.4191e-5;
                   % [N * sec / m]
% Nonstiff
% Current
figure(1)
out1 = sim('exercise_4_openLoop', 'Solver', 'ode45');
out2 = sim('exercise_4_openLoop', 'Solver', 'ode23');
out3 = sim('exercise_4_openLoop', 'Solver', 'ode113');
plot(out1.MotorCurrent.time,
 out1.MotorCurrent.signals.values, 'r--', ...
 out2.MotorCurrent.time, out2.MotorCurrent.signals.values, 'b--', ...
 out3.MotorCurrent.time, out3.MotorCurrent.signals.values, 'g--');
title("Nonstiff solvers")
xlabel("Time")
ylabel("Motor current")
legend("ode45", "ode23", "ode113")
% Speed
figure(2)
plot(out1.ScopeData.time, out1.ScopeData.signals.values, 'r--', ...
 out2.ScopeData.time, out2.ScopeData.signals.values, 'b--', ...
 out3.ScopeData.time, out3.ScopeData.signals.values, 'g--');
title("Nonstiff solvers")
xlabel("Time")
ylabel("Motor speed")
legend("ode45", "ode23", "ode113")
% Stiff
% Current
figure(3)
out1 = sim('exercise_4_openLoop', 'Solver', 'ode15s');
out2 = sim('exercise_4_openLoop', 'Solver', 'ode23s');
out3 = sim('exercise_4_openLoop', 'Solver', 'ode23t');
out4 = sim('exercise_4_openLoop', 'Solver', 'ode23tb');
plot(out1.MotorCurrent.time,
 out1.MotorCurrent.signals.values, 'r--', ...
    out2.MotorCurrent.time,
 out2.MotorCurrent.signals.values, 'b--', ...
    out3.MotorCurrent.time,
 out3.MotorCurrent.signals.values, 'g--', ...
    out4.MotorCurrent.time, out4.MotorCurrent.signals.values, 'm--');
title("Stiff solvers")
```


```
xlabel("Time")
ylabel("Motor current")
legend("ode15s", "ode23s", "ode23t", "ode23tb")


% Speed
figure(4)
plot(out1.ScopeData.time, out1.ScopeData.signals.values, 'r--', ...
    out2.ScopeData.time, out2.ScopeData.signals.values, 'b--', ...
    out3.ScopeData.time, out3.ScopeData.signals.values, 'g--', ...
    out4.ScopeData.time, out4.ScopeData.signals.values, 'm---');

title("Stiff solvers")
xlabel("Time")
ylabel("Motor speed")
legend("ode15s", "ode23s", "ode23t", "ode23tb")
```









Published with MATLAB® R2018a