

UAUC Capture Report

Audit ID: MPSB-13 | Project: MPSB | 18/6/2026, 2:51:30 pm

2

Safety Issues Found

3

Recommendations

Detected Safety Issues

Safety Issue	Potential Risk
Worker not wearing a safety vest.	Worker may fall into the open gap due to unstable footing.
Worker standing on an unstable wooden plank over an open gap.	Injury due to lack of visibility without a safety vest.

AI Recommendations

- Ensure all workers wear safety vests for visibility. - Replace the wooden plank with a stable and secure platform or install proper scaffolding. - Install guardrails or barriers around open gaps to prevent falls.
--

Analyzed Image

